

Air Conditioner Replacement or Repair Application #76242



Thursday, May 7, 2026 9:35 AM

Checklist:

<input type="checkbox"/> Address	<input type="checkbox"/> Application Submitted	
<input type="checkbox"/> Drive/ROW	<input type="checkbox"/> Zoning Review	<input type="checkbox"/> Legal Lot of Record
<input type="checkbox"/> Septic	<input type="checkbox"/> Plans Reviewed	<input type="checkbox"/> Flood Zone
<input type="checkbox"/> Site Use Approved	<input type="checkbox"/> Required Inspections Assigned	<input type="checkbox"/> FDEP Needed
<input type="checkbox"/> Docs Reviewed/Accepted	<input type="checkbox"/> Invoiced	

APPLICANT: Clinton G Wilson **PHONE:** (386) 496-9000

ADDRESS: PO Box 531 Lake Butler, FL 32054

OWNER: NORRIS DAVID C, NORRIS NANCY J **PHONE:** (386) 454-4526

ADDRESS: 136 SW WOODLAND AVE FORT WHITE, FL 32038

PARCEL ID: 30-7S-17-10060-001 **SUBDIVISION:** SANTA FE RIVER PLANTATIONS REPLAT LOTS 33,34,35

LOT: 1 **BLOCK:** 45 **PHASE:** **UNIT:** **ACRES:** 3.23

CONTRACTOR	TYPE	LIC#	BUSINESS NAME
CLINTON G WILSON	General	CAC057886	WILSON HEAT & AIR INC

JOB DETAILS

Commercial or Residential Residential

Description of Work Change Out

Unit for? House

Commercial type of Building:

If "Other", please explain

Unit Type Split-System

Work details for job? Replacement Unit-Change Out(Only)

Exterior Equipment Location Ground

Roof top install:

Model

Seer

Size (Ton):

Total Estimated Cost 9000

Matched systems are required. Select one of the following means: AHRI data

Review Notes: