

INVITATION TO BID
2020-O
SALE OF SURPLUS VEHICLES

The Columbia County Board of County Commissioners will receive bids on various surplus vehicles via GovDeals until **3:00 PM ET** on **July 2, 2020**.

Additional information and bidding is available online ONLY at:
<https://www.govdeals.com/columbiacountyfl>

Vehicle Inspection Form

Inventory ID: Brush 464	Asset Number: 11977	Fair Market Value: _____
--------------------------------	----------------------------	--------------------------

Short Description:
 Year 1984 Make Chevy Model 3/4 ton 4x4

VIN:

1	G	C	G	D	3	4	J	X	E	F	3	9	0	1	1	6
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

 Title Restriction: Y N
 Odometer:

3	9	8	7	6	
---	---	---	---	---	--

 Miles Kilometers Odometer Accurate Y N: _____

Long Description:
 This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only
Engine- Type: L, V⁸ Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid
 Engine Condition: Runs Needs repair is in unknown condition
 Repairs needed: None
 This vehicle was maintained every Daily Days Hours Miles
 Date Removed From Service: 8/8/19 Maintenance Records: Available Not Available For Inspection
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition
 Repairs Needed: None
Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition: Good

Exterior: Color: White Windows: No Cracked Glass Cracked _____
 Minor: Dents Scratches Dings Tire Condition: Fair Tread: _____ #Flat 0 Hubcaps #4
 Major Damage to: None
 Additional Damage: None
 Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions
 Emergency equip: None Has been removed & There are holes in the exterior There are no holes

Interior: Color Grey Cloth Vinyl Leather
 Damage to Seats: Yes
 Damage to Dash/Floor: Dash
 Radio: Stock or Brand & Model: _____ AM AM/FM AM/FM Cassette AM/FM CD
 AC (Condition: Cold Unknown) No AC Air Bags: Driver's Side Dual
 Cruise Control Tilt Steering Remote Mirrors Climate Control
 Power: Steering Windows Door Locks Seats

Additional Equipment: N/A
 Manufacturer _____ Model _____ Serial # _____
 Tool Box Light Bar Ladder Rack Utility Body: Brand _____ Hitch: Type _____

Location of Asset: _____
For more information contact: _____
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.





BRUSH 466



**COUNTY
DISTRICT 46**



GOD BLESS AMERICA





GOD BLESS AMERICA



BRUSH 466

COUNTY
DISTRICT 46



Graphics By:
PRIDE ENTERPRISES
1-800-443-7661



BATTALION 43

GOD BLESS AMERICA

Vehicle Inspection Form

Inventory ID: <u>OPS Shift Commander</u>	Asset Number: <u>13709</u>	Fair Market Value: _____
--	----------------------------	--------------------------

Short Description:
 Year 2009 Make Ford Model F-150 4x4

VIN:

1	F	T	R	W	1	4	8	5	9	F	B	1	4	4	7	0
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

 Title Restriction: Y N

Odometer:

1	7	0	3	8	4
---	---	---	---	---	---

 Miles Kilometers Odometer Accurate Y N: _____

Long Description:
 This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only
Engine- Type: L, V⁸ Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid
 Engine Condition: Runs Needs repair is in unknown condition
 Repairs needed: None

This vehicle was maintained every Daily Days Hours Miles
 Date Removed From Service: 9/2020 Maintenance Records: Available Not Available For Inspection

Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition
 Repairs Needed: None

Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition: Good

Exterior: Color: White Windows: No Cracked Glass Cracked _____
 Minor: Dents Scratches Dings Tire Condition: Good Tread: _____ #Flat _____ Hubcaps # _____
 Major Damage to: None
 Additional Damage: None

Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions
 Emergency equip: None Has been removed & There are holes in the exterior There are no holes

Interior: Color Grey Cloth Vinyl Leather
 Damage to Seats: Driver
 Damage to Dash/Floor: None

Radio: Stock or Brand & Model: _____ AM AM/FM AM/FM Cassette AM/FM CD
 AC (Condition: Cold Unknown) No AC Air Bags: Driver's Side Dual
 Cruise Control Tilt Steering Remote Mirrors Climate Control
 Power: Steering Windows Door Locks Seats

Additional Equipment: _____
 Manufacturer _____ Model _____ Serial # _____
 Tool Box Light Bar Ladder Rack Utility Body: Brand _____ Hitch: Type _____

Location of Asset: _____
For more information contact: _____
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.



F150

**COLUMBIA COUNTY
FIRE RESCUE**



BATTALION 48



COLUMBIA COUNTY
FIRE RESCUE



BATTALION 48



COLUMBIA COUNTY
FIRE RESCUE

F150

GRABBER



F150
ROUNTREE - MOORE
LAKE CITY, FLORIDA



COLUMBIA COUNTY
FIRE RESCUE

Vehicle Inspection Form

Inventory ID: **Brush 42**

Asset Number: **09948**

Fair Market Value:

Short Description:

Year 1998

Make Ford

Model Super Duty 4x4

VIN:

1 F D L F 4 7 F 2 V E C 2 9 8 1 6

Title Restriction: Y N

Odometer:

4 0 7 6 6

Miles

Kilometers

Odometer Accurate Y N: _____

Long Description:

This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only

Engine- Type: L, V⁸ Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid

Engine Condition: Runs Needs repair is in unknown condition

Repairs needed: None

This vehicle was maintained every Daily Days Hours Miles

Date Removed From Service: 8/8/19 Maintenance Records: Available Not Available For Inspection

Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition

Repairs Needed: None

Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition: Good

Exterior:

Color: Red

Windows: No Cracked Glass Cracked

Minor: Dents Scratches Dings Tire Condition: Fair Tread: _____ #Flat 0 Hubcaps #4

Major Damage to: None

Additional Damage: None

Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions

Emergency equip: None Has been removed & There are holes in the exterior There are no holes

Interior:

Color Grey

Cloth Vinyl Leather

Damage to Seats: None

Damage to Dash/Floor: None

Radio: Stock or Brand & Model: _____ AM AM/FM AM/FM Cassette AM/FM CD

AC (Condition: Cold Unknown) No AC

Air Bags: Driver's Side Dual

Cruise Control Tilt Steering Remote Mirrors Climate Control

Power: Steering Windows Door Locks Seats

Additional Equipment: N/A

Manufacturer _____

Model _____

Serial # _____

Tool Box

Light Bar

Ladder Rack

Utility Body: Brand _____

Hitch: Type _____

Location of Asset: _____

For more information contact: _____

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.

IFDLF47F2VE29816



BRUSH 43

COLUMBIA COUNTY

F SUPER DUTY
POWER STROKE
DIESEL

4
WHEEL DRIVE
SUPER TRAK
MAX
COUSIN MANAGER







BRUSH 43

COLUMBIA COUNTY

FORD SUPER DUTY
POWER STROKE DIESEL

BATTALION 43



Vehicle Inspection Form

Inventory ID: _____	Asset Number: 12796	Fair Market Value: _____
----------------------------	-----------------------------------	---------------------------------

Short Description:
 Year 2006 Make Chevy Model 1500

VIN:

1	G	C	E	K	1	4	V	6	6	Z	2	4	4	6	1	0
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

 Title Restriction: Y N

Odometer:

1	5	7	7	4	4
---	---	---	---	---	---

 Miles Kilometers Odometer Accurate Y N: _____

Long Description:
 This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only
Engine- Type: ___ L, V ___ Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid
 Engine Condition: Runs Needs repair is in unknown condition
 Repairs needed: Needs engine

This vehicle was maintained every 5000 Days Hours Miles
 Date Removed From Service: _____ Maintenance Records: Available Not Available For Inspection

Transmission: Automatic Manual ___ Speed Condition: Operable Needs repair Is Unknown Condition
 Repairs Needed: _____

Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition: _____

Exterior: Color: White Windows: No Cracked Glass Cracked _____
 Minor: Dents Scratches Dings Tire Condition: Good Tread: _____ #Flat ___ Hubcaps # ___
 Major Damage to: _____
 Additional Damage: _____

Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions
 Emergency equip: None Has been removed & There are holes in the exterior There are no holes

Interior: Color Gray Cloth Vinyl Leather
 Damage to Seats: No
 Damage to Dash/Floor: No

Radio: Stock or Brand & Model: _____ AM AM/FM AM/FM Cassette AM/FM CD
 AC (Condition: Cold Unknown) No AC Air Bags: Driver's Side Dual
 Cruise Control Tilt Steering Remote Mirrors Climate Control
 Power: Steering Windows Door Locks Seats

Additional Equipment: _____
 Manufacturer _____ Model _____ Serial # _____
 Tool Box Light Bar Ladder Rack Utility Body: Brand _____ Hitch: Type _____

Location of Asset: _____
For more information contact: _____
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.



1GCEK14V66Z244610











CHEVROLET

Vehicle Inspection Form

Inventory ID: _____	Asset Number: 12683	Fair Market Value: _____
----------------------------	-----------------------------------	---------------------------------

Short Description:
Year 2006 Make Ford Model F-250

VIN:

1	F	T	S	X	2	1	P	4	6	E	C	3	6	8	2	2
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

 Title Restriction: Y N

Odometer:

1	5	2	4	5	1
---	---	---	---	---	---

 Miles Kilometers Odometer Accurate Y N: _____

Long Description:

This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only

Engine- Type: ___ L, V ___ Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid

Engine Condition: Runs Needs repair is in unknown condition

Repairs needed: Injectors and Rear End

This vehicle was maintained every 5000 Days Hours Miles

Date Removed From Service: _____ Maintenance Records: Available Not Available For Inspection

Transmission: Automatic Manual ___ Speed Condition: Operable Needs repair Is Unknown Condition

Repairs Needed: Transmission slips

Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition: _____

Exterior: Color: White Windows: No Cracked Glass Cracked _____

Minor: Dents Scratches Dings Tire Condition: Good Tread: _____ #Flat ___ Hubcaps # _____

Major Damage to: _____

Additional Damage: _____

Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions

Emergency equip: None Has been removed & There are holes in the exterior There are no holes

Interior: Color Gray Cloth Vinyl Leather

Damage to Seats: Worn from use

Damage to Dash/Floor: _____

Radio: Stock or Brand & Model: _____ AM AM/FM AM/FM Cassette AM/FM CD

AC (Condition: Cold Unknown) No AC Air Bags: Driver's Side Dual

Cruise Control Tilt Steering Remote Mirrors Climate Control

Power: Steering Windows Door Locks Seats

Additional Equipment: _____

Manufacturer _____ Model _____ Serial # _____

Tool Box Light Bar Ladder Rack Utility Body: Brand _____ Hitch: Type _____

Location of Asset: _____

For more information contact: _____

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.



F-250

POWERSTROKE
TURBO DIESEL

4x4







4x4

Ford

F-250
SUPER DUTY

4x4

OLET