



WEST SHORE

HOME

WINDOW MEASURE SHEET

OF INSTALLERS NEEDED: 3

CUSTOMER: Dyrnell Wormely
Yolanda Wormely

TECH: Joshua

DAYS TO COMPLETE: 1

ADDRESS: J-339453

LOCATION	QUANTITY	STYLE	WIDTH X HEIGHT	MISC
BRI	1	2Lite	69 ³ / ₈ x 58 ¹ / ₄	Temp
DR	1	Pic	70 ¹ / ₄ x 58 ¹ / ₂	Temp
DR	1	Eye/leg	70 ¹ / ₄ x 34	SL: 28 ¹ / ₄
Girls Bath	1	DH	22 ¹ / ₂ x 46 ¹ / ₄	Temp/obs
Back BR	1	2Lite	69 x 58	Temp
MBR	2	Pic	35 ³ / ₈ x 70 ¹ / ₄	Temp
MBR	1	Pic	58 ¹ / ₂ x 70 ¹ / ₄	Temp
MBR	1	Eye	58 ¹ / ₂ x 12	
MBR	2	DH	34 ¹ / ₈ x 58 ³ / ₈	Temp
			X	
			X	
			X	
			X	
			X	
			X	

- Type of tear out Metal frame

- Any mullions being removed ☒ Yes ☐ No 4

- Will shutter/blinds fit again ☐ Yes ☐ No

- Bays/Bows

- Roof or soffit tie in

- Supports or brick underneath? Condition? _____

- Need jamb depth & projection (degree _____)

- If in brick extend jamb to brick

- Exterior opening size _____

- Shoemold _____

- Changes Made ☐ Yes ☒ No

NOTES: 4 Mullions to be removed, Marble sill Brick

Darnell $\frac{1}{3}$ Yolanda
Wormely

J-339453

• Marble sil
• Brick

1. BR1 · 2Lite · $69\frac{5}{8} \times 58\frac{1}{2}$ · Temp
2. DR · Pic · $70\frac{1}{4} \times 58\frac{1}{2}$ · Exact · Temp
3. DR · Eye · $70\frac{1}{4} \times 34$ SL: $28\frac{1}{4}$ · Exact
4. Girl's Bath · DH · $22\frac{3}{4} \times 46\frac{1}{2}$ · Temp/obs
5. Back BR · 2Lite · $69\frac{1}{4} \times 58\frac{1}{4}$
6. MBR · Pic · $35\frac{3}{8} \times 70\frac{1}{4}$ · Exact · Temp
7. MBR · Pic · $58\frac{1}{2} \times 70\frac{1}{4}$ · Exact · Temp
8. MBR · Eye · $58\frac{1}{2} \times 12$ · Exact
9. MBR · Pic · $35\frac{3}{8} \times 70\frac{1}{4}$ · Exact · Temp
10. MBR · DH · $34\frac{3}{8} \times 58\frac{5}{8}$
11. MBR · DH · $34\frac{3}{8} \times 58\frac{5}{8}$

Darnell & Yolanda
Wormely
J-339453

