DATE 0//05/2006	This Permit Expires	One Year From the Da	ite of Issue	PERIVITT 000024706
	CY BECKHAM	PHO?	NE <u>352-745-2738</u>	FL 32024
ADDRESS 269 OWNER JACK	SW PARER LANE OB & REBECCA JONES	LAKE CITY PHON		FL 32024
ADDRESS 166		<del></del>	NE .	FL 32055
CONTRACTOR	STACY BECKHAM	PHON	NE 352-745-2738	<u>1L</u> <u>32033</u>
LOCATION OF PRO		TAMMY LN, L INTO DEER		
LOCATION OF TRO	TAKE 1ST LANETO E		ROWINITARK	
TYPE DEVELOPMI		ESTIMATED COST O	F CONSTRUCTION	0.00
HEATED FLOOR A	REA TO	TAL AREA	HEIGHT	STORIES
FOUNDATION	WALLS	ROOF PITCH	FLC	OOR
LAND USE & ZONI	NG RSF/MH-2		MAX. HEIGHT 35	5
Minimum Set Back F	Requirments: STREET-FRONT	25.00 REAF	R 15.00	SIDE 10.00
NO. EX.D.U. <u>13</u>	FLOOD ZONE X	DEVELOPMENT 1	PERMIT NO.	
PARCEL ID 17-3	S-17-05018-000 SUE	BDIVISION DEER RUN M	MOBILE HOM PARK	
LOT D BLO	CK PHASE	UNIT 1	TOTAL ACRES	
			122	
	IH0000051	2	The state of the s	
Culvert Permit No.	Culvert Waiver Contractor's Lic	ense Number	Applicant/Owner/C	Contractor
EXISTING	<u>05-0610-N</u>	BK	JH	<u>N</u>
Driveway Connection	Septic Tank Number LU	J & Zoning checked by	Approved for Issuance	New Resident
SECTION 2.3.8 MH I	PARK, REPLACING EXISTING MH	ZONING DEPARTME	_ Check # or Cas	
Tamparan, Paulan				(footer/Slab)
Temporary Power	date/app. by	date/app. by	Monolithic	date/app. by
Under slab rough-in p		Slab	Sheathing/N	ailing
	date/app. by	date/app. by		date/app. by
Framing	Rough-in plu	imbing above slab and below v	wood floor	
	te/app. by		<del></del>	date/app. by
Electrical rough-in	Heat & Air date/app. by		Peri. beam (Lintel)	
Permanent power	C.O. Final	date/app. by	Cultiont	date/app. by
	date/app. by	date/app. by	Culvert	date/app. by
M/H tie downs, blocki	ng, electricity and plumbing	,	Pool	
Reconnection	Pump pole	date/app. by  Utility	y Pole	date/app. by
M/H Pole	date/app. by	date/app. by	date/app. by	-
date/app.	by Travel Trailer	date/app. by	Re-roof	date/app. by
BUILDING PERMIT	FEE \$ 0.00 CERTIFICAT		SURCHARGE I	FEE \$ 0.00
	00.00 ZONING CERT. FEE \$		<del>_</del>	
FLOOD DEVELOPMI	-0 11	E \$ 25.00 CULVERT FER	111	L FEE 275.00
INSPECTORS OFFIC		CI EDKS OFFIC	nn // 1/	

NOTICE: IN ADDITION TO THE REQUIREMENTS OF THIS PERMIT, THERE MAY BE ADDITIONAL RESTRICTIONS APPLICABLE TO THIS PROPERTY THAT MAY BE FOUND IN THE PUBLIC RECORDS OF THIS COUNTY. AND THERE MAY BE ADDITIONAL PERMITS REQUIRED FROM OTHER GOVERNMENTAL ENTITIES SUCH AS WATER MANAGEMENT DISTRICTS, STATE AGENCIES, OR FEDERAL AGENCIES.

"WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF COMMENCEMENT."

### This Permit Must Be Prominently Posted on Premises During Construction

PLEASE NOTIFY THE COLUMBIA COUNTY BUILDING DEPARTMENT AT LEAST 24 HOURS IN ADVANCE OF EACH INSPECTION, IN ORDER THAT IT MAY BE MADE WITHOUT DELAY OR INCONVIENCE, PHONE 758-1008. THIS PERMIT IS NOT VALID UNLESS THE WORK AUTHORIZED BY IT IS COMMENCED WITHIN 6 MONTHS AFTER ISSUANCE.

PERMIT APPLICATION / MANUFACTURED HOME INSTALLATION APPLICATION Zoning Official RLK 2906 Building Official M 377 For Office Use Only (Revised 6-23-05) AP# 10606-80 \_\_\_\_\_ Date Received 6-21-06 By LH Permit # 2 4 706 Zoning Land Use Plan Map Category **Development Permit** Comments as a New conforming Use FEMA Map#\_\_\_\_\_Elevation\_ \_\_\_\_ Finished Floor\_\_\_\_ River\_\_\_ In Floodway\_ Site Plan with Setbacks Shown 🗸 EH Signed Site Plan 🗆 EH Release 🗆 Well letter 🖼 Existing well Copy of Recorded Deed or Affidavit from land owner 

Letter of Authorization from installer Lot D Deer Run MH Poule Property ID# 17- 35-17-05-018- 000 Must have a copy of the property deed New Mobile Home **Used Mobile Home** \_\_ Year 1980 Applicant Stacy Phone # 52-715-2738 Address 149 Phone# 911 Address 32051 Circle the correct power company -FL Power & Light Clay Electric (Circle One) -Suwannee Vailey Electric -**Progress Energy** Name of Owner of Mobile Home Deen Run MAD Phone # Address Relationship to Property Owner . Same Current Number of Dwellings on Property WH Park Lot Size \_\_\_\_\_ Total Acreage Do you : Have an Existing Drive or need a Culvert Permit or a Culvert Waiver (Circle one) is this Mobile Home Replacing an Existing Mobile Home\_ 275.00 **Driving Directions to the Property** across from Tunny

Name of Licensed Dealer/Installer Skey Beckham Phone # 35% 7% 2738
 Installers Address A61 Stu Jonky LN Jok Cek M. 8 7024
 License Number 71/00005/2 Installation Decal # 195 626

Snearwaii	Manufacturer	
	Longitudinal Stabilizing Device w/ Lateral Arms	
Sidewall	Longitudinal Stabilizing Device (LSD)	
Number	TIEDOWN COMPONENTS	
OTHER TIES		
within 2' of end of home spaced at 5' 4" oc		
FRAME TIES		
4ft 5ft	Opening Pier pad size,	
ANCHORS	and their pier pad sizes below.	
24 x 24 576 4 foot 26 x 26 676	List all marriage wall openings greater than 4 foot	
17 3/16 × 25 3/16 17 1/2 × 25 1/2	wall openings 4 foot or greater. Use this symbol to show the piers.	
13 1/4 × 26 1/4 348	(required by the mig.)	
$\coprod$	Other pier pad sizes	De Soit De Soi
$\coprod$	Perimeter pier pad size / (2 4/6)	
Pad Size Sq II	I-beam pier pad size $n \times n$	] ] ] ]
POPULAR PAD SIZES	PIER PAD SIZES	
8'	8' - 15C-1 niar son	
CQ CQ		confinement
රු රු		Show locations of Longitudinal and Lateral Systems (use dark lines to show these locations)
6.	(SQ T) 3' 4'	y process pro- oppositely
20" x 20"   22" x 22"   24" X 24"   26" x 28 (400)   (484)"   (576)"   (676)	9 size (256) (342)	Typical pier spacing
OR USED HOMES	PIER SPACING TABLE FOR USED HOMES	I understand Lateral Arm Systems cannot be used on any home (new or used) where the sidewall ties exceed 5 ft 4 in.
330304548HB	Triple/Quad Serial #	NOTE: If home is a single wide fill out one half of the blocking plan if home is a triple or quad wide sketch in remainder of home
1956160	Double wide Installation Decal #	Manufacturer 6000 Length x width 28×56/60
	Single wide Wind Zone II	being installed hut Chy A. 3224
150	Home is installed in accordance with Rule 15-C	Address of home / Cell N w Deer Run Bleun
liation Manual	Home installed to the Manufacturer's Installation Manual	Installer Strick Dell' UM License # 1.45800510
	New Home Used Home .	}

## PERMIT NUMBER

### or check here to declare 1000 lb. soil The pocket penetrometer tests are rounded down to POCKET PENETROMETER TEST without testing

× 1500

## POCKET PENETROMETER TESTING METHOD

- Test the perimeter of the home at 6 locations.
- Take the reading at the depth of the footer.
- 3. Using 500 lb. increments, take the lowest reading and round down to that increment

15

X /300

## ORQUE PROBE TEST

showing 275 inch pounds or less will require 4 foot anchors here if you are declaring 5' anchors without testing The results of the torque probe test is inch pounds or check

Note: A state approved lateral arm system is being used and 4 ft reading is 275 or less and where the mobile home manufacturer may anchors are required at all centerline tie points where the torque test anchors are allowed at the sidewall locations. I understand 5 ft requires anchors with 4000 lb holding capacity.

installer's initials

# ALL TESTS MUST, BE PERFORMED BY A LICENSED INSTALLER

Installer Name

Date Tested

Sech Man

Electrical

Connect electrical conductors between multi-wide units, but not to the main power Source This includes the bonding wire between mult-wide units.

Connect all sewer drains to an existing sewer tap or septic tank. Pg.

Connect all potable water supply piping to an existing water meter, water tap, or other independent water supply systems. Pg.

Site Preparation

Water drainage: Natural Debris and organic material removed Swale

Pad

Fastening muiti wide units

Floor Roof: Walls: Type Fastener: Type Fastener: Type Fastener: 300 E

Length: Length: Length:

Spacing:

will be centered over the peak of the roof and fastened with galv For used homes a min. 30 gauge, 8" wide, galvanized metal strip Spacing: Spacing: 12

Gastest (weatherproofing requirement)

roofing nails at 2" on center on both sides of the centerline

of tape will not serve as a gasket a result of a poorly installed or no gasket being installed. I understand a strip homes and that condensation, mold, meldew and buckled marriage walls are I understand a property installed gasket is a requirement of all new and used

nstaller's initials

Type gasket

installed:

Bottom of ridgebeam Between Walls Yes Between Floors Yes

Weatherproofing

Fireplace chimney installed so as not to allow intrusion of rain water. Yes Siding on units is installed to manufacturer's specifications. Yes The bottomboard will be repaired and/or taped. Yes

Miscellaneous

Electrical crossovers protected. Drain lines supported at 4 foot intervals. Yes Range downflow vent installed outside of skirting. Dryer vent installed outside of skirting. Yes Skirting to be installed. Yes ğ ¥

Installer verifies all information given with this permit worksheet is accurate and true based on the

Installer Signature manufacturer's installation instructions and or Rule 15C-1 & 2 Date

### **Columbia County Property** Appraiser DB Last Updated: 6/19/2006

Parcel: 17-3S-17-05018-000

### **2006 Proposed Values**

Tax Record Property Card Interactive GIS Map Print

### **Owner & Property Info**

Owner's Name	JONES JACOB W & REBECCA C
Site Address	
Mailing Address	CO-TRUSTEES 301 NW BROOKSIDE CT LAKE CITY, FL 32055
Description	N1/2 OF NE1/4 OF NW1/4 OF SW1/4. ORB 625- 561, 726-166, 762-1760, 813-2377, (DEER RUN MH PARK)WD 1017-1492

<< Prev Sea	arch Result: 6 of 14 Next >>
Use Desc. (code)	PARKING/MH (002802)
Neighborhood	17317.00
Tax District	2
UD Codes	MKTA03
Market Area	06
Total Land Area	5.000 ACRES

### **Property & Assessment Values**

Mkt Land Value	cnt: (3)	\$32,500.00
Ag Land Value	cnt: (0)	\$0.00
<b>Building Value</b>	cnt: (12)	\$46,219.00
XFOB Value	cnt: (2)	\$63,400.00
Total Appraised Value	S.	\$142,119.00

Just Value	\$142,119.00
Class Value	\$0.00
Assessed Value	\$142,119.00
Exempt Value	\$0.00
Total Taxable Value	\$142,119.00

### **Sales History**

Sale Date	Book/Page	Inst. Type	Sale VImp	Sale Qual	Sale RCode	Sale Price
6/3/2004	1017/1492	WD	I	Q		\$172,500.00
11/22/1995	813/2377	WD	I	U	08	\$125,000.00
7/21/1992	762/1760	СТ	I	U	11	\$20,000.00

### **Building Characteristics**


Bldg Item	Bldg Desc	Year Blt	Ext. Walls	Heated S.F.	Actual S.F.	Bldg Value
1	MOBILE HME (000800)	1972	Alum Siding (26)	1614	1752	\$9,261.00
2	MOBILE HME (000800)	1972	Alum Siding (26)	720	720	\$3,066.00
3	MOBILE HME (000800)	1969	Alum Siding (26)	576	672	\$2,555.00
4	MOBILE HME (000800)	1972	Alum Siding (26)	960	1768	\$5,681.00
5	MOBILE HME (000800)	1968	Alum Siding (26)	768	896	\$3,407.00
6	MOBILE HME (000800)	1972	Alum Siding (26)	720	720	\$3,066.00
7	MOBILE HME (000800)	1973	Alum Siding (26)	720	720	\$3,066.00
9	MOBILE HME (000800)	1973	Alum Siding (26)	684	844	\$3,253.00
10	MOBILE HME (000800)	1961	Alum Siding (26)	672	744	\$3,132.00
11	MOBILE HME (000800)	1972	Alum Siding (26)	792	792	\$3,632.00
12	MOBILE HME (000800)	1963	Alum Siding (26)	672	672	\$3,050.00
13	MOBILE HME (000800)	1973	Alum Siding (26)	672	672	\$3,050.00
	Note: All S.F. calculation	ons are base	ed on <u>exterior</u> bui	lding dimensio	ns.	·

### **Extra Features & Out Buildings**

0259 MHP HOOKUP 0 \$62,400.00 13.000 0 x 0 x 0 (.00)	Code	Desc	Year Blt	Value	Units	Dims	Condition (% Good)
	0259	MHP HOOKUP	0	\$62,400.00	13.000	0 x 0 x 0	(.00)


Application for Onsite Sewage Disposal System Construction Permit. Part II Site Plan Permit Application Number: 05-06/01/

ALL CHANGES MUST BE APPROVED BY THE COUNTY HEALTH UNIT





### PRELIMINARY MOBILE HOME INSPECTION REPORT

	6-21-56 BY 4 IS THE M/H ON THE PROPERTY WHERE THE PERMIT WILL BE ISSUED?	Y = 5
IERS NAME		
	K Deer Run M4Park SUBDIVISION	
	INS TO MOBILE HOME 44/ North @ into Deer Run 15	+
	lane to the end on left (CotD)	
DBILE HOME INS	STALLER Stary Berthan PHONE CELL	
	INFORMATION	
	rear 86 SIZE Z8 x 56 COLOR Tan	& Brown
	33630454 8 AB	
IIND ZONE	Must be wind zone II or higher NO WIND ZONE I ALLOWED	
NTERIOR: P or F) + P= P	INSPECTION STANDARDS PASS F= FAILED	
•	SMOKE DETECTOR () OPERATIONAL () MISSING	
	FLOORS () SOLID () WEAK () HOLES DAMAGED LOCATION	
	DOORS () OPERABLE () DAMAGED	
<del></del>	••	
<del></del>	WALLS () SOLID () STRUCTURALLY UNSOUND	
	WINDOWS () OPERABLE () INOPERABLE	
<del></del>	PLUMBING FIXTURES ( ) OPERABLE ( ) MISSING	
	CEILING () SOLID () HOLES () LEAKS APPARENT	
	ELECTRICAL (FIXTURES/OUTLETS) ( ) OPERABLE ( ) EXPOSED WIRING ( ) OUTLET COVERS MISSING ( ) LIGHT FIXTU	RES MISSING
EXTERIOR:	WALLS / SIDDING ( ) LOOSE SIDING ( ) STRUCTURALLY UNSOUND ( ) NOT WEATHERTIGHT ( ) NEEDS CLEANING	
	WINDOWS ( ) CRACKED/ BROKEN GLASS ( ) SCREENS MISSING ( ) WEATHERTIGHT	
	ROOF ( ) APPEARS SOLID ( ) DAMAGED	•
		• •
STATUS: APPROVED	WITH CONDITIONS:	
NOT APPROVE	DNEED REINSPECTION FOR FOLLOWING CONDITIONS	· ·
SIGNATURE	ID NUMBERDATE	B1



This information, GIS Map Updated: 8/19/2008, was derived from data which was compiled by the Columbia County Property Appraiser Office solely for the governmental purpose of property assessment. This information should not be relied upon by anyone as a determination of the ownership of property or market value. No warranties, expressed or implied, are provided for the accuracy of the data herein, it's use, or it's interpretation. Although it is periodically updated, this information may not reflect the data currently on file in the Property Appraiser's office. The assessed values are NOT certified values and therefore are subject to change before being finalized for advaluer assessment purposes.





### PRELIMINARY MOBILE HOME INSPECTION REPORT

	15 THE M/H ON THE PROPERTY WHERE THE PERMIT WILL BE ISSUED?	\z
/NERS NAME	Jecob & Rebecca Junes PHONE CELL	
DRESS	1 7	
	RK Deer Run M4Park SUBDIVISION	
IVING DIRECTIO	ONS TO MOBILE HOME 44/ North Cinto Deer Run 151	
	lane to the end on left (cot D)	
<del></del>		
OBILE HOME IN	STALLER Steery Beefchar PHONE CELL	•
	INFORMATION	
	reary 86 SIZE Z8 x 56 COLOR Tan	E Brown
RIAL No	33630454,8AB	
IND ZONE	Must be wind zone II or higher NO WIND ZONE I ALLOWED	
NTERIOR:	INSPECTION STANDARDS PASS F= FAILED	
/ (Irr) - F= F	SMOKE DETECTOR () OPERATIONAL () MISSING	
<del></del>		
<u> </u>	FLOORS () SOLID () WEAK () HOLES DAMAGED LOCATION	
<u> </u>	DOORS () OPERABLE () DAMAGED	
	WALLS () SOLID () STRUCTURALLY UNSOUND	
	WINDOWS () OPERABLE () INOPERABLE	
,/	PLUMBING FIXTURES ( ) OPERABLE ( ) INOPERABLE ( ) MISSING	
	CEILING () SOLID () HOLES () LEAKS APPARENT	
EXTERIOR:	ELECTRICAL (FIXTURES/OUTLETS) ( ) OPERABLE ( ) EXPOSED WIRING ( ) OUTLET COVERS MISSING ( ) LIGHT FIXTUR	ES MISSING
	WALLS / SIDDING ( ) LOOSE SIDING ( ) STRUCTURALLY UNSOUND ( ) NOT WEATHERTIGHT ( ) NEEDS CLEANING	
	WINDOWS ( ) CRACKED/ BROKEN GLASS ( ) SCREENS MISSING ( ) WEATHERTIGHT	
	ROOF ( ) APPEARS SOLID ( ) DAMAGED	e p
STATUS:		•
APPROVED	WITH CONDITIONS:	*
NOT APPROVED	NEED REINSPECTION FOR FOLLOWING CONDITIONS	* *
	A	
SIGNATURE	Day DATE 7-	6.06