

Columbia County, FL. Building & Zoning New Residential Construction Permit #000039741 Issued May 07, 2020



OWNER: ABBATE JOSEPHINE PHONE: 3867545810 ADDRESS: 249 SW BONANZA GLN LAKE CITY, FL 32025

PARCEL: 13-4S-16-02952-209 ZONING: RESIDENTIAL - MEDIUM RMF- FLOOD ZONE: A

Coords: 30.15,-82.67

SUBDIVISION: SOUTHERN APPROACHES UNIT 1

LOT: 9 BLK: PHASE: UNIT: ACRES: 0.48

ADDRESS: CONTRACTOR

PHONE: 386-754-5810

NAME: BLAKE LUNDE II

618 SW FLORIDA GATEWAY

DRIVE

LAKE CITY, FL 32024

LICENSE: CBC1253408 -

BUSINESS: BLAKE CONSTRUCTION COMPANY OF NORTH

PROJECT DETAILS

THIS IS THE CONSTRUCTION OF A:	Single Family Dwelling
HEATED AREA (SQFT):	1158
TOTAL AREA (SQFT):	1512
STORIES:	1
BUILDING HEIGHT:	17.25
BUILDING CODE CONSTRUCTION TYPE:	V
BUILDING CODE ELEMENT:	В
BUILDING CODE OCCUPANCY TYPES:	Residential
OCCUPANCY USE TITLE:	single family
SETBACKS FRONT:	65
SETBACK SIDE 1:	25
SETBACK SIDE 2:	35
SETBACKS REAR:	90
SEPTIC#:	20-0302
BUILDING CODE EDITION:	Florida Building Code 2017 6th Edition & 2014 National Electrical Code
ELEVATION REGULATION:	Subdivision Plat
FINISHED FLOOR REQUIREMENT:	111.4
REQUIREMENT NEEDED:	By Nailing Inspection
DOCUMENT NEEDED IS:	a Surveyor letter giving the Finished Floor Elevation

Notice: in addition to the requirements of this permit, there may be additional restrictions applicable to this property that may be found in the public records of this county. The issuance of this permit does not waive compliance by permittee with deed restrictions. Notice: all other applicable state or federal permits shall be obtained before commencement of this permitted development.

"WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF COMMENCEMENT."

Every permit issued shall become invalid unless the work authorized by such permit is commenced within 180 days after its issuance, or if the work authorized by such permit is suspended or abandoned for a period of 180 days after the time the work is commenced. A valid permit receives an approved inspection every 180 days. Work shall be considered not suspended, abandoned or invalid when the permit has received an approved inspection within 180 days of the previous inspection.