

Noling Pest Control

Phone (386) 454-3888

(386) 935-2007

P.O. Box 949 (32655)

High Springs, Florida

CERTIFICATE OF COMPLIANCE OF TERMITE PROTECTION

(AS REQUIRED BY FLORIDA BUILDING CODE (FBC) 1816.1.7)

1724 SW Hurlong St

Address of Treatment of Lot/Block of Treatment

Soil Barrier


Terminator H.E.

Method of Termite Prevention Treatment-soil barrier, wood treatment,
bait system, other (describe)

The building has received a complete treatment for the prevention of subterranean termites. Treatment is in accordance with rules and laws established by the Florida Department of Agriculture and Consumer Services.

Craig Noling
Authorized Signature

2-23-23
Date



Noling Pest Control

Cory Noling, Owner
Phone (386) 454-3888
(386) 935-2007
P.O. Box 949

High Springs, Florida 32655-0949

GRAPH AND SPECIFICATIONS

BUYER'S NAME Bill Blanchard SELLER'S NAME _____ DATE 2-23-23

INSPECTION ADDRESS 1724 SW Harbor St CITY Fort White STATE FL ZIP _____

BUSINESS PHONE _____ HOME PHONE _____ INSPECTED BY: Cory Noling


Scale Used: _____ Well: ☐ Yes ☐ No How close to house? _____ ft. Additions? ☐ Yes ☐ No Access? _____

Additional specifications and comments: Graph not to scale termidor H.E.

100 gallons

Lineal Footage: _____ Square Footage: 1320 sq ft Contract Price: _____

Type Foundation: ☐ Floating Slab ☐ Supported Slab ☒ Monolithic Slab ☐ Crawl ☐ Basement Type Construction: ☐ CBS ☐ Woodframe ☐ Brick



Noling Pest Control

Phone 386-454-3888

16732 NW SR 45

P.O. Box 949 High Springs, FL 32655

Pursuant to Chapter 482, Florida Statutes, 482.226(6), this notice is required to be posted. Any licensee who performs control of any wood-destroying organism shall post notice of said treatment immediately adjacent to the access to the attic or crawl area or other readily accessible area of the property treated.

Subterranean Termites
Wood-Destroying Organism Treated

Termidor HE
Pesticide Used

Square Feet Sprayed

2-23-23
Date of Treatment

2-23-23
Date of Inspection

**Notice of Inspection
and/or Treatment**

General Conditions

Stucco below grade? Yes ☐ No ☐
Are Termites swarming? Yes ☐ No ☐
Wood supports on ground? Yes ☐ No ☐
Proper clearance for treating? Yes ☐ No ☐
Make A3 access opening? Yes ☐ No ☐
Electricity available? Yes ☐ No ☐
Bath trap opening? Yes ☐ No ☐
Shrubbery Light ☐ Heavy ☐
Type Floor Covering: _____
Other: _____

_____ IS DESIGNATED BY AN "X"

