DATE <u>07/06/2006</u>	Columbia County	y Building Pe i	rmit PERM	IT
	This Permit Expires One			722
	TE GILLEY	PHONE	352.475.3133	_
ADDRESS 796	N SR 21	_ MELROSE	FL 3266	6
-	OPERTIES LLC	PHONE	352.514.6281	_
ADDRESS 167	CHERYL GLN	_ LAKE CITY	FL 3205	5
CONTRACTOR GA	AYLE G. EDDY	PHONE	386.496.3687	
LOCATION OF PROPE			CHERYL GLN	
	4TH LOT ON R.(COUNTING I	D.W)		
TYPE DEVELOPMENT	M/H/UTILITY E	ESTIMATED COST OF CON	STRUCTION 0.00	
HEATED FLOOR AREA	A TOTAL A	REA	HEIGHT STORI	ES
FOUNDATION	WALLS	ROOF PITCH	FLOOR	
LAND USE & ZONING		MAX	HEIGHT	
Minimum Set Back Requ	irments: STREET-FRONT 20.0	00 REAR	SIDE 15.00	0
NO. EX.D.U. <u>10</u>	FLOOD ZONE X	DEVELOPMENT PERM	IT NO	
PARCEL ID 18-3S-17	7-05061-012 SUBDIVIS	ION MCCALL MHP		
LOT 7 BLOCK			ACRES 4.00	
LOI / BLOCK	PHASE UNII		ACRES 4.00	
Culvert Permit No.	Culvert Waiver Contractor's License No		pplicant/Owner/Contractor	
EXISTING	06-0514-N BLK			
Driveway Connection	-		ved for Issuance New Resid	dent
PROVIDES DUMPSTER	N 2.3.8 & REPLACES EXISTING M.H. ASS	SESSMENSTS CHARGED. I	ARK	
FROVIDES DOMFSTER	ON FREMISE.		Check # or Cash 1260	
			Check # or Cash 1260	
	FOR BUILDING & ZON	ING DEPARTMENT (ONLY (footer/S	Slab)
Temporary Power	Foundation		Monolithic	
The described was about 1	date/app. by	date/app. by	date/app. l	by
Under slab rough-in plum	date/app. by	date/app. by	Sheathing/Nailingdate	e/app. by
Framing	2	above slab and below wood f		сларр. бу
date/ap		above stab and below wood t	date/app.	by
Electrical rough-in	Heat & Air Duct	Pe	ri. beam (Lintel)	
_	date/app. by	date/app. by	date/ap	pp. by
Permanent power	ate/app. by C.O. Final		Culvert	
M/H tie downs, blocking, e		date/app. by	date/app. by	•
		pp. by	Pool date/app. by	
Reconnection	date/app. by Pump pole date	Utility Pole		
M/H Pole	date/app. by dat Travel Trailer	te/app. by	date/app. by Re-roof	
date/app. by		date/app. by	date/app. by	
DIW DD - C	0.00			
BUILDING PERMIT FEE	\$ 0.00 CERTIFICATION F	EE \$	SURCHARGE FEE \$ 0.0	00
MISC. FEES \$ 200.0	O ZONING CERT. FEE \$ 50.0	0 FIRE FEE \$ 0.00	WASTE FEE \$	
FLOOD DEVELOPMENT	FEES ENOOD ZONE FEE \$ 25	.00 CULVERT FEE \$	TOTAL FEE 27	75.00

NOTICE: IN ADDITION TO THE REQUIREMENTS OF THIS PERMIT, THERE MAY BE ADDITIONAL RESTRICTIONS APPLICABLE TO THIS PROPERTY THAT MAY BE FOUND IN THE PUBLIC RECORDS OF THIS COUNTY. AND THERE MAY BE ADDITIONAL PERMITS REQUIRED FROM OTHER GOVERNMENTAL ENTITIES SUCH AS WATER MANAGEMENT DISTRICTS, STATE AGENCIES, OR FEDERAL AGENCIES.

INSPECTORS OFFICE

"WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF COMMENCEMENT."

CLERKS OFFICE

This Permit Must Be Prominently Posted on Premises During Construction

PLEASE NOTIFY THE COLUMBIA COUNTY BUILDING DEPARTMENT AT LEAST 24 HOURS IN ADVANCE OF EACH INSPECTION, IN ORDER THAT IT MAY BE MADE WITHOUT DELAY OR INCONVIENCE, PHONE 758-1008. THIS PERMIT IS NOT VALID UNLESS THE WORK AUTHORIZED BY IT IS COMMENCED WITHIN 6 MONTHS AFTER ISSUANCE.

ERMIT APPLICATION / MANUFACTURED HOME INSTALLATION APPLICATION

For Office Use Only	Zening Official SU	29.06.06 Bullet	Official Of-THE
AP# 0686-67	_ Date Received 6-28-86	By LH Perm	n 24722
Produ 2019 Dev	elopment Permit_W/A	Zoning I Land Us	e Plan Map Category
Comments Section	= 2.3.8 + Replace	y Existly mH	
	The state of the s		
FENA Map # Florest			
Site Plan with Setbacks a	Finlahed Floor	River	in Floodway
Site Plan with Setbacks a	hown DEnvironmental He	alth Signed Site Plan	Env. Health Release
-	out of G	. Horn often	Revised 0.22 ou
Property in 18-35	-17F-05061-0	12	copy of the property deed
New Mobile Home	12 030010	Must have a	copy of the property deed
OBINIONS NOTICE	in marinews mit	P (Hwy25A	* mcau Terrace
Applicant MANATE	(4: 10.1	Z	Lake City
Address 90 Val	lacore Routy, 994 Bo	ya Dr. Lave Cit	FI 32225
Magaza më Para në a	CLAR is		(352)514-6281 32055 CR 754-896 Electric Vanac Transporter
Page Address 1/07	er GLC Propertie	S. LLC Phone	# (352)514-6281
Circle the control	heryl Glen, La	Ke City, Fl. a	32055 OR 7511-891
outdia the correct power	r company - (FL Power	& Light - Cia	Electric Vanac
(Circ	ie One) - Survannes i	(elley Elegtric - E	Togressive Energy
Address % Vanacon			
michelle	Vangeow 994 Su	Baya Dr. Lak	ne# (352) 514-6281 2 Cety, F1 32025
Relationship to Propert	y Owner Same		
		· · · · · · · · · · · · · · · · · · ·	
	Illings on Property (C	puis office	- 01
Lot Size DO x		tal Acreage	
Do you : Have an Exist	ing Drive or need a Ci		
Driving Directions N	ma Masina i	iven Permit or a	Culvert Walver Permit
Terr as B	on marion to	Hwy 25A	gol tomacall
101101010	then immedia	te Ronto C	heryl Glen.
Lunit 13 4	h on LEFT (con	oting the Dull	40
Is this Mobile Home Rep	lacing an Eviation Make	Home Ves	\$275 Pd ASSESSA
			TO 13 PO ASSESSA
Name of Licensed Deale	Installer Goyle 6.	Eddy Phone	* 386-496-3687
THE PARTY OF THE P	7 Dex 3260 La	te Butler	FL. 32054
License Number THO	000714	installation Deca	
*			ordered. L
			Tallahara From

JW colled a ceft MESTAGE.



STATE OF FLORIDA DEPARTMENT OF HEALTH

APPLICATION FOR ONSITE SEWAGE DISPOSAL SYSTEM CONSTRUCTION PERMIT Permit Application Number 06-0514-PART II - SITE PLAN Scale: Each block represents 5 feet and 1 inch = 50 feet. - THCHO! Notes: Site Plan submitted by: __ 566 Signature Title

ALL CHANGES MUST BE APPROVED BY THE COUNTY HEALTH DEPARTMENT

Not Approved _

Plan Approved

Date

County Health Department

ROAD - Cheryln Glen

APPF AMED BLOCK = 5 45'

Amobin Primate & ille 5/21/04

- (Well is approx 214' away from #7)

CODE ENFORCEMENT DEPARTMENT

COLUMBIA COUNTY, FLORIDA
OUT OF COUNTY MOBILE HOME INSPECTION REPORT

COUNTY THE MOBILE HOME IS BEING MOVED FROM HICK VILLE
OWNERS NAME Annette Gilley PHONE CELL 352 514628
INSTALLER GALLE G. Eddy PHONE 386496 3687 CELL 352494 2326
INSTALLERS ADDRESS 73565W126th Ave Lake Butler FL. 32054
MOBILE HOME INFORMATION
MAKE Piedmont YEAR 1981 SIZE 14 x 66
COLOR Creen Brown 3ERIAL No. 532-816-0714GA
WIND ZONE SMOKE DETECTOR
FLOORS Good - a Couple Small Soft Spots
DOORS Good - Locks working - Doors closing
WALLS Good
CABINETS Good
ELECTRICAL (FIXTURES/OUTLETS) GOOD
EXTERIOR: WALLS/SIDDING Good - Needs presure washing
WINDOWS Window cracked
APPROVEDNOT APPROVED
NOTES: Home appears to be in good condition-
INSTALLER OR INSPECTORS PRINTED NAME Coyle G. Eddy
Installer/Inspector Signature State State License No. THOODOTIY Date 4/17/04
ONLY THE ACTUAL LICENSE HOLDER OR A BUILDING INSPECTOR CAN SIGN THIS FORM.
NO WIND ZONE ONE MOBILE HOMES WILL BE PERMITTED, MOBILE HOMES PRIOR TO 1977 ARE PRE-HUD AND THE WIND ZONE MUST BE PROVEN TO BE PERMITTED.
BEFORE THE MOBILE HOME CAN BE MOVED INTO COLUMBIA COUNTY THIS FORM MUST BE COMPLETED AND RETURNED TO THE COLUMBIA COUNTY BUILDING DEPARTMENT.
ONCE MOVED INTO COLUMBIA COUNTY AN INSPECTOR MUST COMPLETE A PRELIMINARY INSPECTION ON THE MOBILE HOME. CALL 388-719-2038 TO SET UP THIS INSPECTION, NO PERMIT WILL BE ISSUED BEFORE THIS IS DONE.

	The state of the s		-rderstand Lateral Arm Systems cannot beed on any home (new or used) are the sidewall ties exceed 5 ft 4 in. Staller's initials Ted pier specing Show loons of Longitudinal and Lateral Systems (usark lines to show these locations)	Inter Gayle G. Eddy License # THODOO 14 Asss of home be installed lake Chapt. 32055 NECTURE Predictor wide fill out chaff of the blocking plan it home is a triple or quad wide Jeh in remainder of home
TIEDOWN COM Stabilizing De Stabilizing De	oximate locations of marriage 4 foot or greater. Use this w the piers. 13 14 28 17 376 x 25 17 172 x 25 24 x 24 25 x 28 s below. Pier pad size	B B B B B B B B B B	34	New Home

PERMIT NUMBER

POCKET PENETROMETER TEST

The packet penetrometer tests are rounded down to or check here to declare 1000 lb. soil without without testing.

× So

× 2000





B

Debris and organic material removed

Site Preparation

POCKET PENETROMETER TESTING METHOD

- Take the reading at the depth of the footer Test the perimeter of the home at 6 locations
- Using 500 lb. increments, take the lowest

μ

reading and round down to that incremen

इंडि

7

TORQUE PROBETES

The results of the torque probe test is 300 here if you are declaring 5' anchors without testing showing 275 inch pounds or less will require 4 foot anchors. inch pounds or check A TOSI

Note: A state approved lateral arm system is being used and 4 ft anchors are required at all centerline tie points where the torque test anchors are allowed at the sidewall locations. I understand 5 ft requires anchors with 4000 la holding capacity. reading is 275 or less and where the mobile home manufacturer may

Installer's initials

Instater Name

ALL TESTS MUST BE PERI

DRINED BY A LICENSED INSTALLER

Date Tested

Electrical

Connect electrical conductors between multi-wide units, but not to the main power **SOUTCE** This includes the bonding wire between mult-wide units.

Connect all sewer drains to an existing sewer tap or septic tank ۾

independent water supply systems. Pg. Connect all potable water supply piping to an existing water meter, water tap, or other

Drain lines supported at 4 foot intervals, Range downflow vent installed outside of skir Dryer vent installed outside of skirting. Skirting to be installed. Siding on units is installed to manufacturer's specification and the Fireplace chimney installed so as not to allow intrusion of rain water. Electrical crossovers protected. 3 The bottomboard will be repaired and/or taped. (Ces-Type gasket \ of lape will not serve as a gasket homes and that condensation, mold, meldew and buckled marriage walls are a result of a poorly installed or no gasket being installed. I understand a strip Walls Floor: Root understand a properly installed gasket is a requirement of all new and used Water drainage: Natural will be centered over the peak of the roof and fastened with galv rooting halls at 2" on center on both sides of the centerline. For used homes aunin. 30 gauge, 8" wide, galvanized metal stric Type Fastener: Type Fastener Type Fastener Gustat (weather proofing requirements) Fastening multi wide units Swale Bullcoadseageage nstalled: Between Walls Yes Bottom of ridgebeam Yes Between Floors Length: Pad ¥ 8 **Spacing** Spacing ğ

installer verifies all information given with this permit worksheet is accurate and true based on the

Installer Signature manufacturer's installation instructions and or Rule 15C-1 & 2 Data Mal

Prepared By: Diane Marks Millenium Titte, Inc. 2641 Mccormick Drive, Suite 101 Clearwater, FL 3375

incidental to the issuance of a title insurance policy.

File Number: cl04-2691 Parcel ID #: 18-35-17-05061-012 Inst: 2004029112 Date: 12/30/2004 Time: 15:19

Doc Stamp-Deed : 910.00

_DC,P.DeWitt Cason,Columbia County B:1034 P:1536

WARRANTY DEED (INDIVIDUAL)

This WARRANTY DEED, dated 12/27/04 by DOUGLAS I. CARLSEN and CHERYL CARLSEN, husband and

whose post office address is 15401 TIMBERLINE DR., TAMPA, FL 33634, hereinafter called the GRANTOR, to GLC Properties, LLC, A Florida Limited Liability Company

whose post office address is 796 N. State Rd. 21, Melrose, FL 32666 hereinaster called the GRANTEE: (Wherever used herein the terms "Grantor" and "Grantee" shall include all parties to this instrument and the heirs, legal representatives and assigns of

WITNESSETH: That the GRANTOR, for and in consideration of the sum of \$10.00 and other valuable considerations, receipt whereof is hereby acknowledged, hereby grants, bargains, sells, aliens, remises, releases, conveys and confirms unto the GRANTEE, all that certain land situate in Columbia County, FL, viz:

Begin at the Southeast corner of the SW 1/4 of the SE 1/4, Section 18, Township 3 South, Range 17 East; thence S. 87° 41' 00" W. along the South line of said Section 18, 961.51 feet to the Easterly Right-of-way line of State Road #25-A; thence N. 42° 03' 30" W., along said Right-of-way line 92.96 feet to the Southerly Right-of-Way line of McCall Road; thence N. 47° 48' 22" E., 153.43 feet; thence N. 87° 33' 47" E. 908.21 feet to the East line of said SW 1/4 of the SE 1/4; thence S. 00° 26' 21" E., 174.00 feet to the Point of Beginning, lying and being situate in Columbia County, Florida.

SUBJECT TO covenants, conditions, restrictions, reservations, limitations, easements and agreements of record, if any; taxes and assessments for the year 2004 and subsequent years; and to all applicable zoning ordinances and/or restrictions and prohibitions imposed by governmental authorities, if any.

TOGETHER with all the tenements, hereditaments and appurtenances thereto belonging or in anywise appertaining.

TO HAVE AND TO HOLD, the same in fee simple folever

AND THE GRANTOR hereby covenants with said GRANTEE that except as above noted, the GRANTOR is lawfully seized of said land in fee simple; that the GRANTOR has good, right and lawful authority to sell and convey said land; that the GRANTOR hereby fully warrants the title to said land and will defend the same against the lawful claims of all

IN WITNESS WHEREOF, GRANTOR has signed and sealed these presents the date set forth above.

SIGNED IN HEPRESENCE OF THE FOLLOWING WITNESSES:

Signature:

Print Name:

Signature:

Print Name:

CHERYL CARLSEN

STATE OF Florida COUNTY OF PINELLAS


DEC 27 200%

To: Columbia Co. Bldg. Dept.

HTT: Jori

Dermission for annette Selly to pick up permit for my set up at 167 Cheryl Glam. Jake Cely.

> Hagle Eddy TH0000714 386 496 3687



PRELIMINARY MOBILE HOME INSPECTION REPORT

DATE RECEIVED _		9= 5
OWNERS NAME _	CARAMETICS, LLC PHONE 386,684,9278 CELL 3	52.514.6281
ADDRESS	167 CHENY GIN, CC 7/ 32055	
	ARK 9-3 - MAKLEWS MAP SUBDIVISION_	
DRIVING DIRECTI	ONS TO MOBILE HOME MARION AVE to C-25-A, The TO MCCIII NO	MICH TR
Then	a R ON CHERY/ GARNI, UNTI IS The 4th ON L.	-
MOBILE HOME II	HSTALLER GAY/E W. EDLY PHONE 386.496.3687 CELL	
	E INFORMATION	
MAKE	TREDMONT YEAR 1581 SIZE 14 X66 COLOR DELM	Brown
SERIAL No.	532.816.071460	,
WIND ZONE	Must be wind zone II or higher NO WIND ZONE I ALLOWED	
INTERIOR:	INSPECTION STANDARDS PASS F= FAILED	
P	SMOKE DETECTOR () OPERATIONAL () MISSING	
7	FLOORS () SOLID () WEAK () HOLES DAMAGED LOCATION	
$\overline{\varphi}$	DOORS () OPERABLE () DAMAGED	
P	N	
ρ	WALLS () SOLID () STRUCTURALLY UNSOUND	
-b	WINDOWS () OPERABLE () INOPERABLE	
	PLUMBING FIXTURES () OPERABLE () INOPERABLE () MISSING	
7	CEILING () SOLID () HOLES () LEAKS APPARENT	
EXTERIOR:	ELECTRICAL (FIXTURES/OUTLETS) () OPERABLE () EXPOSED WIRING () OUTLET COVERS MISSING () LIGHT	FIXTURES MISSING
EATERION:	WALLS / SIDDING () LOOSE SIDING () STRUCTURALLY UNSOUND () NOT WEATHERTIGHT () NEEDS CLEANING	G
<u> </u>	WINDOWS () CRACKED/ BROKEN GLASS () SCREENS MISSING () WEATHERTIGHT	
Ψ	ROOF () APPEARS SOLID () DAMAGED	S#1 240
STATUS:		
APPROVED	WITH CONDITIONS:	
NOT APPROVED	NEED REINSPECTION FOR FOLLOWING CONDITIONS	

SIGNATURE	Sufficient 10 NUMBER 30 7 DATE	6-29-06