

# Work Order

|                  |                                       |                        |  |
|------------------|---------------------------------------|------------------------|--|
| <b>Number</b>    | 2025-00004747                         | <b>Request Date</b>    | 4/7/2025 12:00:00 AM                   |
| <b>Type</b>      | Water Inspection                      | <b>Schedule Date</b>   | 4/8/2025 12:00:00 AM                   |
| <b>Priority</b>  |                                       | <b>Assign Date</b>     |  |
| <b>Requester</b> | Amy Fernandez                         | <b>Assigned To</b>     | Scott, William Brian                   |
| <b>Account</b>   | 143276-001<br>Oasis Oaks, Inc. Phone: | <b>Service Address</b> | 2102 SE BAYA DR<br>LAKE CITY, FL 32025 |

|          |   |
|----------|---|
| Comments | 240 Verify they connected to the water meter correctly.<br>Schedule * 04/08/25 * 10-11 Please call Kerri 386-752-5152. AF |
|----------|---|

|                  |               |  |  |  |
|------------------|---------------|--|--|--|
| New Meter Device |               |  |  |  |
| Meter #96013612  |               |  |  |  |
|                  |               |  |  |  |
|                  |               |  |  |  |
|                  |               |  |  |  |
|                  | Mxu#136795808 |  |  |  |
|                  |               |  |  |  |

Read 0000010 Read           

---

---

10:30am-11:00am

Read Date 04-07-2025 Read Date / /

|          |   |
|----------|---|
| Comments | <u>Meter and check valve and duel check valve</u><br><u>Installed properly, meter front left by side walk</u> |
|----------|---|

Completed By: Kap