

New Construction Subterranean Termite Service Record

This form is completed by the licensed Pest Control Company.

Public reporting burden for this collection of information is estimated to average 15 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. This information is required to obtain benefits. HUD may not collect this information, and you are not required to complete this form, unless it displays a currently valid OMB control number.

Section 24 CFR 200.926d(b)(3) requires that the sites for HUD insured structures must be free of termite hazards. This information collection requires the builder to certify that an authorized Pest Control company performed all required treatment for termites, and that the builder guarantees the treated area against infestation for one year. Builders, pest control companies, mortgage lenders, homebuyers, and HUD as a record of treatment for specific homes will use the information collected. The information is not considered confidential, therefore, no assurance of confidentiality is provided.

This report is submitted for informational purposes to the builder on proposed (new) construction cases when treatment for prevention of subterranean termite infestation is specified by the builder, architect, or required by the lender, architect, FHA, or VA.

All contracts for services are between the Pest Control Company and builder, unless stated otherwise.

Section 1: General Information (Pest Control Company Information)

Company Name Aspen Pest Control, Inc.
 Company Address P.O. Box 1795 City Lake City State FL Zip 32055
 Company Business License No. JB182349 Company Phone No. 904-755-3611
 FHA/VA Case No. (if any) _____

Section 2: Builder Information

Company Name FL Home Construction Phone No. 904-577-9610

Section 3: Property Information

Location of Structure(s) Treated (Street Address or Legal Description, City, State and Zip) Golf Coast Parkway ZONE 3
11174 NW 11th Avenue, Place
Lake City, FL 32054

Section 4: Service Information

Date(s) of Service(s) 5-8-2018
 Type of Construction (More than one box may be checked) ☒ Slab ☐ Basement ☐ Crawl ☐ Other _____

Check all that apply:

- ☒ A. Soil Applied Liquid Termiticide
 Brand Name of Termiticide: _____ EPA Registration No. _____
 Approx. Dilution (%): 1.5 Approx. Total Gallons Mix Applied: _____ Treatment completed on exterior: ☐ Yes ☒ No
- ☐ B. Wood Applied Liquid Termiticide
 Brand Name of Termiticide: _____ EPA Registration No. _____
 Approx. Dilution (%): _____ Approx. Total Gallons Mix Applied: _____
- ☐ C. Bait System Installed
 Name of System _____ EPA Registration No. _____ Number of Stations Installed _____
- ☐ D. Physical Barrier System Installed
 Name of System _____ Attach installation information (required)

Service Agreement Available? ☐ Yes ☒ No

Note: Some state laws require service agreements to be issued. This form does not preempt state law.

Attachments (List) _____

Comments _____

Name of Applicator(s) C. B. [unclear] Certification No. (if required by State law) JP104378

The applicator has used a product in accordance with the product label and state requirements. All materials and methods used comply with state and federal regulations.

Authorized Signature _____ Date 5-8-2018

Warning: HUD will prosecute false claims and statements. Conviction may result in criminal and/or civil penalties. (18 U.S.C. 1001, 1010, 1012; 31 U.S.C. 3729, 3802)

form HUD-NPMA-99-B (8/2008)

New Construction Subterranean Termite Service Record

OMB Approval No. 2502-0525
(exp. 05/30/2018)

This form is completed by the licensed Pest Control Company.

Public reporting burden for this collection of information is estimated to average 15 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. This information is required to obtain benefits. HUD may not collect this information, and you are not required to complete this form, unless it displays a currently valid OMB control number.

Section 24 CFR 200.926d(b)(3) requires that the sites for HUD insured structures must be free of termite hazards. This information collection requires the builder to certify that an authorized Pest Control company performed all required treatment for termites, and that the builder guarantees the treated area against infestation for one year. Builders, pest control companies, mortgage lenders, homebuyers, and HUD as a record of treatment for specific homes will use the information collected. The information is not considered confidential, therefore, no assurance of confidentiality is provided.

This report is submitted for informational purposes to the builder on proposed (new) construction cases when treatment for prevention of subterranean termite infestation is specified by the builder, architect, or required by the lender, architect, FHA, or VA.

All contracts for services are between the Pest Control Company and builder, unless stated otherwise.

Section 1: General Information (Pest Control Company Information)

Company Name Aspen Pest Control, Inc.
Company Address P.O. Box 1795 City Lake City State FL Zip 32026
Company Business License No. JF182248 Company Phone No. 385-765-3811
FHA/VA Case No. (if any) _____

Section 2: Builder Information

Company Name 2121 W. 1st St. Lake City, FL 32026 Phone No. 904-651-1111

Section 3: Property Information

Location of Structure(s) Treated (Street Address or Legal Description, City, State and Zip) 1031 W. 1st St. Lake City, FL 32026

Section 4: Service Information

Date(s) of Service(s) 3-1-2018
Type of Construction (More than one box may be checked) ☐ Slab ☐ Basement ☐ Crawl ☐ Other _____

Check all that apply:

- ☐ A. Soil Applied Liquid Termiticide
Brand Name of Termiticide: Termidor EPA Registration No. 11122-1
Approx. Dilution (%): 1:1 Approx. Total Gallons Mix Applied: 10 Treatment completed on exterior: ☐ Yes ☐ No
- ☐ B. Wood Applied Liquid Termiticide
Brand Name of Termiticide: _____ EPA Registration No. _____
Approx. Dilution (%): _____ Approx. Total Gallons Mix Applied: _____
- ☐ C. Bait System Installed
Name of System _____ EPA Registration No. _____ Number of Stations Installed _____
- ☐ D. Physical Barrier System Installed
Name of System _____ Attach installation information (required)

Service Agreement Available? ☐ Yes ☐ No

Note: Some state laws require service agreements to be issued. This form does not preempt state law.

Attachments (List) _____

Comments _____

Name of Applicator(s) J. J. J. Certification No. (if required by State law) JF104378

The applicator has used a product in accordance with the product label and state requirements. All materials and methods used comply with state and federal regulations.

Authorized Signature _____ Date _____

Warning: HUD will prosecute false claims and statements. Conviction may result in criminal and/or civil penalties. (18 U.S.C. 1001, 1010, 1012; 31 U.S.C. 3729, 3802)
form HUD-NPMA-99-B (8/2008)

New Construction Subterranean Termite Service Record

OMB Approval No. 2502-0525
(exp. 05/30/2018)

This form is completed by the licensed Pest Control Company.

Public reporting burden for this collection of information is estimated to average 15 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. This information is required to obtain benefits. HUD may not collect this information, and you are not required to complete this form, unless it displays a currently valid OMB control number.

Section 24 CFR 200.926d(b)(3) requires that the sites for HUD insured structures must be free of termite hazards. This information collection requires the builder to certify that an authorized Pest Control company performed all required treatment for termites, and that the builder guarantees the treated area against infestation for one year. Builders, pest control companies, mortgage lenders, homebuyers, and HUD as a record of treatment for specific homes will use the information collected. The information is not considered confidential, therefore, no assurance of confidentiality is provided.

This report is submitted for informational purposes to the builder on proposed (new) construction cases when treatment for prevention of subterranean termite infestation is specified by the builder, architect, or required by the lender, architect, FHA, or VA.

All contracts for services are between the Pest Control Company and builder, unless stated otherwise.

Section 1: General Information (Pest Control Company Information)

Company Name Aspen Pest Control, Inc.
Company Address P.O. Box 1795 City Lake City State FL Zip 32038
Company Business License No. JB182949 Company Phone No. 386-755-3811
FHA/VA Case No. (if any) _____

Section 2: Builder Information

Company Name Elkins Construction LLC Phone No. 904-677-4610

Section 3: Property Information

Location of Structure(s) Treated (Street Address or Legal Description, City, State and Zip) Gulf Coast Healthcare Zone 5
275 SW Prosperity Place
Lake City FL 32024

Section 4: Service Information

Date(s) of Service(s) 4-17-2018
Type of Construction (More than one box may be checked) ☒ Slab ☐ Basement ☐ Crawl ☐ Other _____

Check all that apply:

- ☒ A. Soil Applied Liquid Termiticide
Brand Name of Termiticide: Proformant EPA Registration No. 53883-229
Approx. Dilution (%): 0.05 Approx. Total Gallons Mix Applied: 1500 Treatment completed on exterior: ☐ Yes ☒ No
- ☐ B. Wood Applied Liquid Termiticide
Brand Name of Termiticide: _____ EPA Registration No. _____
Approx. Dilution (%): _____ Approx. Total Gallons Mix Applied: _____
- ☐ C. Bait System Installed
Name of System _____ EPA Registration No. _____ Number of Stations Installed _____
- ☐ D. Physical Barrier System Installed
Name of System _____ Attach installation information (required)

Service Agreement Available? ☒ Yes ☐ No

Note: Some state laws require service agreements to be issued. This form does not preempt state law.

Attachments (List) _____

Comments _____

Name of Applicator(s) C. Lacey Certification No. (if required by State law) JP104978

The applicator has used a product in accordance with the product label and state requirements. All materials and methods used comply with state and federal regulations.

Authorized Signature [Signature] Date 4-17-2018

Warning: HUD will prosecute false claims and statements. Conviction may result in criminal and/or civil penalties. (18 U.S.C. 1001, 1010, 1012; 31 U.S.C. 3729, 3802)
form HUD-NPMA-99-B (8/2008)

New Construction Subterranean Termite Service Record

OMB Approval No. 2502-0525
(exp. 05/30/2018)

This form is completed by the licensed Pest Control Company.

Public reporting burden for this collection of information is estimated to average 15 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. This information is required to obtain benefits. HUD may not collect this information, and you are not required to complete this form, unless it displays a currently valid OMB control number.

Section 24 CFR 200.926d(b)(3) requires that the sites for HUD insured structures must be free of termite hazards. This information collection requires the builder to certify that an authorized Pest Control company performed all required treatment for termites, and that the builder guarantees the treated area against infestation for one year. Builders, pest control companies, mortgage lenders, homebuyers, and HUD as a record of treatment for specific homes will use the information collected. The information is not considered confidential, therefore, no assurance of confidentiality is provided.

This report is submitted for informational purposes to the builder on proposed (new) construction cases when treatment for prevention of subterranean termite infestation is specified by the builder, architect, or required by the lender, architect, FHA, or VA.

All contracts for services are between the Pest Control Company and builder, unless stated otherwise.

Section 1: General Information (Pest Control Company Information)

Company Name Aspen Pest Control, Inc.
Company Address P.O. Box 1795 City Lake City State FL Zip 32855
Company Business License No. JB182948 Company Phone No. 352-755-3511
FHA/VA Case No. (if any) _____

Section 2: Builder Information

Company Name Elkins Construction Phone No. 279-211-1100

Section 3: Property Information

Location of Structure(s) Treated (Street Address or Legal Description, City, State and Zip) Gulf Coast Healthcare Zone 6
275 SW Prospekt City, Lake City, FL 32024

Section 4: Service Information

Date(s) of Service(s) 4-23-2018
Type of Construction (More than one box may be checked) ☒ Slab ☐ Basement ☐ Crawl ☐ Other _____

Check all that apply:

- ☒ A. Soil Applied Liquid Termiticide
Brand Name of Termiticide: Termidor EPA Registration No. 62553-227
Approx. Dilution (%): 105 Approx. Total Gallons Mix Applied: 13.0 Treatment completed on exterior: ☐ Yes ☒ No
- ☐ B. Wood Applied Liquid Termiticide
Brand Name of Termiticide: _____ EPA Registration No. _____
Approx. Dilution (%): _____ Approx. Total Gallons Mix Applied: _____
- ☐ C. Bait System Installed
Name of System _____ EPA Registration No. _____ Number of Stations Installed _____
- ☐ D. Physical Barrier System Installed
Name of System _____ Attach installation information (required)

Service Agreement Available? ☐ Yes ☒ No

Note: Some state laws require service agreements to be issued. This form does not preempt state law.

Attachments (List) _____

Comments _____

Name of Applicator(s) _____ Certification No. (if required by State law) JP104376

The applicator has used a product in accordance with the product label and state requirements. All materials and methods used comply with state and federal regulations.

Authorized Signature _____ Date 4-23-18

Warning: HUD will prosecute false claims and statements. Conviction may result in criminal and/or civil penalties. (18 U.S.C. 1001, 1010, 1012; 31 U.S.C. 3729, 3802)
form HUD-NPMA-99-B (8/2008)

New Construction Subterranean Termite Service Record

OMB Approval No. 2502-0525
(exp. 05/30/2018)

This form is completed by the licensed Pest Control Company.

Public reporting burden for this collection of information is estimated to average 15 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. This information is required to obtain benefits. HUD may not collect this information, and you are not required to complete this form, unless it displays a currently valid OMB control number.

Section 24 CFR 200.926d(b)(3) requires that the sites for HUD insured structures must be free of termite hazards. This information collection requires the builder to certify that an authorized Pest Control company performed all required treatment for termites, and that the builder guarantees the treated area against infestation for one year. Builders, pest control companies, mortgage lenders, homebuyers, and HUD as a record of treatment for specific homes will use the information collected. The information is not considered confidential, therefore, no assurance of confidentiality is provided.

This report is submitted for informational purposes to the builder on proposed (new) construction cases when treatment for prevention of subterranean termite infestation is specified by the builder, architect, or required by the lender, architect, FHA, or VA.

All contracts for services are between the Pest Control Company and builder, unless stated otherwise.

Section 1: General Information (Pest Control Company Information)

Company Name Aspen Pest Control, Inc. City Lake City State FL Zip 32050
Company Address P.O. Box 1705 Company Phone No. 386-755-3811
Company Business License No. JB182948
FHA/VA Case No. (if any) _____

Section 2: Builder Information

Company Name Elkins Construction Phone No. 904-677-4610

Section 3: Property Information

Location of Structure(s) Treated (Street Address or Legal Description, City, State and Zip) Gulf Coast Healthcare Zone 2
2985 W Prosperity Place
Lake City, Florida 32024

Section 4: Service Information

Date(s) of Service(s) 4-9-2018
Type of Construction (More than one box may be checked) ☒ Slab ☐ Basement ☐ Crawl ☐ Other _____

Check all that apply:

- ☒ A. Soil Applied Liquid Termiticide
Brand Name of Termiticide: Termise EPA Registration No. 432-1331
Approx. Dilution (%): .05 Approx. Total Gallons Mix Applied: 1600 Treatment completed on exterior: ☐ Yes ☒ No
- ☐ B. Wood Applied Liquid Termiticide
Brand Name of Termiticide: _____ EPA Registration No. _____
Approx. Dilution (%): _____ Approx. Total Gallons Mix Applied: _____
- ☐ C. Bait System Installed
Name of System _____ EPA Registration No. _____ Number of Stations Installed _____
- ☐ D. Physical Barrier System Installed
Name of System _____ Attach installation information (required) _____

Service Agreement Available? ☒ Yes ☐ No

Note: Some state laws require service agreements to be issued. This form does not preempt state law.

Attachments (List) _____

Comments _____

Name of Applicator(s) C. Lacey Certification No. (if required by State law) JF104376

The applicator has used a product in accordance with the product label and state requirements. All materials and methods used comply with state and federal regulations.

Authorized Signature [Signature] Date 4-9-2018

Warning: HUD will prosecute false claims and statements. Conviction may result in criminal and/or civil penalties. (18 U.S.C. 1001, 1010, 1012; 31 U.S.C. 3729, 3802)
form HUD-NPMA-99-B (8/2008)

New Construction Subterranean Termite Service Record

OMB Approval No. 2502-0525
(exp. 05/30/2018)

This form is completed by the licensed Pest Control Company.

Public reporting burden for this collection of information is estimated to average 15 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. This information is required to obtain benefits. HUD may not collect this information, and you are not required to complete this form, unless it displays a currently valid OMB control number.

Section 24 CFR 200.926d(b)(3) requires that the sites for HUD insured structures must be free of termite hazards. This information collection requires the builder to certify that an authorized Pest Control company performed all required treatment for termites, and that the builder guarantees the treated area against infestation for one year. Builders, pest control companies, mortgage lenders, homebuyers, and HUD as a record of treatment for specific homes will use the information collected. The information is not considered confidential, therefore, no assurance of confidentiality is provided.

This report is submitted for informational purposes to the builder on proposed (new) construction cases when treatment for prevention of subterranean termite infestation is specified by the builder, architect, or required by the lender, architect, FHA, or VA.

All contracts for services are between the Pest Control Company and builder, unless stated otherwise.

Section 1: General Information (Pest Control Company Information)

Company Name Aspen Pest Control, Inc.
Company Address P.O. Box 1795 City Lake City State FL Zip 32058
Company Business License No. J0182948 Company Phone No. 888-735-9511
FHA/VA Case No. (if any) _____

Section 2: Builder Information

Company Name L.K. Construction Phone No. 352-298-1111

Section 3: Property Information

Location of Structure(s) Treated (Street Address or Legal Description, City, State and Zip) 1033 NW 12th St, Lake City, FL 32058

Section 4: Service Information

Date(s) of Service(s) 2-10-18
Type of Construction (More than one box may be checked) ☒ Slab ☐ Basement ☐ Crawl ☐ Other _____

Check all that apply:

- ☐ A. Soil Applied Liquid Termiticide
Brand Name of Termiticide: Termidor EPA Registration No. 4373
Approx. Dilution (%): 1.0 Approx. Total Gallons Mix Applied: 1.5 Treatment completed on exterior: ☐ Yes ☐ No
- ☐ B. Wood Applied Liquid Termiticide
Brand Name of Termiticide: _____ EPA Registration No. _____
Approx. Dilution (%): _____ Approx. Total Gallons Mix Applied: _____
- ☐ C. Bait System Installed
Name of System _____ EPA Registration No. _____ Number of Stations Installed _____
- ☐ D. Physical Barrier System Installed
Name of System _____ Attach installation information (required)

Service Agreement Available? ☐ Yes ☐ No

Note: Some state laws require service agreements to be issued. This form does not preempt state law.

Attachments (List) _____

Comments _____

Name of Applicator(s) J. J. J. Certification No. (if required by State law) JF134378

The applicator has used a product in accordance with the product label and state requirements. All materials and methods used comply with state and federal regulations.

Authorized Signature _____ Date _____

Warning: HUD will prosecute false claims and statements. Conviction may result in criminal and/or civil penalties. (18 U.S.C. 1001, 1010, 1012; 31 U.S.C. 3729, 3802)
form HUD-NPMA-99-B (8/2008)

New Construction Subterranean Termite Service Record

OMB Approval No. 2502-0525
(exp. 05/30/2018)

This form is completed by the licensed Pest Control Company.

Public reporting burden for this collection of information is estimated to average 15 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. This information is required to obtain benefits. HUD may not collect this information, and you are not required to complete this form, unless it displays a currently valid OMB control number.

Section 24 CFR 200.926d(b)(3) requires that the sites for HUD insured structures must be free of termite hazards. This information collection requires the builder to certify that an authorized Pest Control company performed all required treatment for termites, and that the builder guarantees the treated area against infestation for one year. Builders, pest control companies, mortgage lenders, homebuyers, and HUD as a record of treatment for specific homes will use the information collected. The information is not considered confidential, therefore, no assurance of confidentiality is provided.

This report is submitted for informational purposes to the builder on proposed (new) construction cases when treatment for prevention of subterranean termite infestation is specified by the builder, architect, or required by the lender, architect, FHA, or VA.

All contracts for services are between the Pest Control Company and builder, unless stated otherwise.

Section 1: General Information (Pest Control Company Information)

Company Name Aspen Pest Control, Inc.
Company Address P.O. Box 1795 City Lake City State FL Zip 32955
Company Business License No. JB182948 Company Phone No. 386-755-3611
FHA/VA Case No. (if any) _____

Section 2: Builder Information

Company Name ELKINS CONSTRUCTION Phone No. 921-57-1616

Section 3: Property Information

Location of Structure(s) Treated (Street Address or Legal Description, City, State and Zip) Gulf Coast Highway 1034 NW Prosperity Place
Lake City, FL

Section 4: Service Information

Date(s) of Service(s) 9-3-2018 **ZONE 1**
Type of Construction (More than one box may be checked) ☒ Slab ☐ Basement ☐ Crawl ☐ Other _____

Check all that apply:

- ☐ A. Soil Applied Liquid Termiticide
Brand Name of Termiticide: Proshield EPA Registration No. 432-1331
Approx. Dilution (%): .05 Approx. Total Gallons Mix Applied: 1500 Treatment completed on exterior: ☐ Yes ☒ No
- ☐ B. Wood Applied Liquid Termiticide
Brand Name of Termiticide: _____ EPA Registration No. _____
Approx. Dilution (%): _____ Approx. Total Gallons Mix Applied: _____
- ☐ C. Bait System Installed
Name of System _____ EPA Registration No. _____ Number of Stations Installed _____
- ☐ D. Physical Barrier System Installed
Name of System _____ Attach installation information (required) _____

Service Agreement Available? ☒ Yes ☐ No

Note: Some state laws require service agreements to be issued. This form does not preempt state law.

Attachments (List) _____

Comments _____

Name of Applicator(s) C. Lacey Certification No. (if required by State law) JP104376

The applicator has used a product in accordance with the product label and state requirements. All materials and methods used comply with state and federal regulations.

Authorized Signature [Signature] Date 9-3-2018

Warning: HUD will prosecute false claims and statements. Conviction may result in criminal and/or civil penalties. (18 U.S.C. 1001, 1010, 1012; 31 U.S.C. 3729, 3802)

New Construction Subterranean Termite Service Record

OMB Approval No. 2502-0525
(exp. 05/30/2018)

This form is completed by the licensed Pest Control Company.

Public reporting burden for this collection of information is estimated to average 15 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. This information is required to obtain benefits. HUD may not collect this information, and you are not required to complete this form, unless it displays a currently valid OMB control number.

Section 24 CFR 200.926d(b)(3) requires that the sites for HUD insured structures must be free of termite hazards. This information collection requires the builder to certify that an authorized Pest Control company performed all required treatment for termites, and that the builder guarantees the treated area against infestation for one year. Builders, pest control companies, mortgage lenders, homebuyers, and HUD as a record of treatment for specific homes will use the information collected. The information is not considered confidential, therefore, no assurance of confidentiality is provided.

This report is submitted for informational purposes to the builder on proposed (new) construction cases when treatment for prevention of subterranean termite infestation is specified by the builder, architect, or required by the lender, architect, FHA, or VA.

All contracts for services are between the Pest Control Company and builder, unless stated otherwise.

Section 1: General Information (Pest Control Company Information)

Company Name Aspen Pest Control, Inc.
Company Address P.O. Box 1765 City Lake City State FL Zip 32826
Company Business License No. JB162948 Company Phone No. 386-765-3611
FHA/VA Case No. (if any) _____

Section 2: Builder Information

Company Name Elkins Construction Phone No. 904-677-4610

Section 3: Property Information

Location of Structure(s) Treated (Street Address or Legal Description, City, State and Zip) Gulf Coast Healthcare Zone 2
298 SW Prosperity Place
Lake City, Florida 32024

Section 4: Service Information

Date(s) of Service(s) 4-9-2018
Type of Construction (More than one box may be checked) ☒ Slab ☐ Basement ☐ Crawl ☐ Other _____

Check all that apply:

- ☒ A. Soil Applied Liquid Termiticide
Brand Name of Termiticide: Termise EPA Registration No. 452-1331
Approx. Dilution (%): .05 Approx. Total Gallons Mix Applied: 1600 Treatment completed on exterior: ☐ Yes ☒ No
- ☐ B. Wood Applied Liquid Termiticide
Brand Name of Termiticide: _____ EPA Registration No. _____
Approx. Dilution (%): _____ Approx. Total Gallons Mix Applied: _____
- ☐ C. Bait System Installed
Name of System _____ EPA Registration No. _____ Number of Stations Installed _____
- ☐ D. Physical Barrier System Installed
Name of System _____ Attach installation information (required) _____

Service Agreement Available? ☒ Yes ☐ No

Note: Some state laws require service agreements to be issued. This form does not preempt state law.

Attachments (List) _____

Comments _____

Name of Applicator(s) C. Lacey Certification No. (if required by State law) JF104375

The applicator has used a product in accordance with the product label and state requirements. All materials and methods used comply with state and federal regulations.

Authorized Signature [Signature] Date 4-9-2018

Warning: HUD will prosecute false claims and statements. Conviction may result in criminal and/or civil penalties. (18 U.S.C. 1001, 1010, 1012; 31 U.S.C. 3729, 3802)

form HUD-NPMA-99-B (8/2008)



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No.: 0210.1800019.0000
Date Typed: April 04, 2018

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Construction Materials Testing Services FIELD AND LABORATORY REPORT COVER PAGE

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

As requested, Universal Engineering Sciences, Inc. (UES) representative(s) performed construction materials testing and/or field inspection services on the above project. Testing results and/or inspection observations are reported on the attached sheets. The contents of this package are summarized below:

Scope of Work

Work Order No.	Date	Type of Report
1043676-1	03/30/2018	Field Inspection Report
1044092-1	04/03/2018	In-Place Density Test Report w/Activity Record
1044093-1	04/03/2018	Grout Prism Test Specimens Activity Record

We hope this information is sufficient for your immediate needs. If you have any questions, please do not hesitate to contact the undersigned or Jeannine Seider.

Sincerely,
Universal Engineering Sciences, Inc.
Certificate of Authorization No. 00000549



Keith L. Butts, P.E. 4-6-18
STATE OF FLORIDA
Professional Engineer No. 53986

Attachments (6)
js

This item has been electronically signed and sealed by Keith L. Butts, P.E. using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.

For the mutual protection of Universal's clients, the general public, and ourselves, our reports are submitted as the confidential property of our clients. Accordingly, authorization for reliance upon, or publication of, all or portions of this report is reserved pending our written approval.

Revised May 2015



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000
UES Report No: 02-1043676

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: 03/30/2018

Technician: Cleveland English

As Requested, a Universal Engineering Sciences Technician was present at the above referenced location for the purpose of obtaining (1) set of (5) 4x8 concrete test cylinders cast on 3/29/18 to be returned to the UES Laboratory for further testing.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000
UES Report No: 1044092-1 ARC 040318

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: Tuesday, April 03, 2018

Technician: Cleveland English

As requested, a Universal Engineering Sciences Technician was present at the above referenced project site for the purpose of earthwork testing for the Zone A.

While on site, the technician observed the general condition of the areas to be tested and performed 10 density tests for Zone A. The tests were performed in accordance with the ASTM D-6938 Nuclear Gauge Method and were found to meet the project compaction requirements of 95% of the maximum dry density per ASTM D-1557.

The Contractor was notified of the test results or a copy was left for their records.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000

Workorder No: 1044092-1

Report Date: 04/04/2018

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

In-Place Density Test Report

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

UES Technician: Cleveland English

Date Tested: 04/03/2018

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Type of Test:

Field: ASTM D-6938 Nuclear Gauge Method

Laboratory: ASTM D1557 Modified Proctor

Area Tested: Zone A

Material: Fill

Reference Datum: 0 = Bottom of Fill

The tests below meet the 95% minimum compaction requirement.

Test No.	Location of Test	Range	Maximum Density (pcf)	Optimum Moisture (%)	Field Dry Density (pcf)	Field Moisture (%)	Soil Compaction (%)	Pass or Fail
1	Zone A Northwest Corner 25' East	0-1 ft	108.3	13.6	106.4	6.8	98	Pass
2	Zone A Northwest Corner 25' East 25' South	0-1 ft	108.3	13.6	102.7	6.3	95	Pass
3	Zone A Northwest Corner 25' East 40' South	0-1 ft	108.3	13.6	105.5	5.8	97	Pass
4	Zone A Northwest Corner 25' East 40' South	0-1 ft	108.3	13.6	103.6	5.9	96	Pass
5	Zone A Northwest Corner 25' East 70' South	0-1 ft	108.3	13.6	102.6	7.1	95	Pass
6	Zone A Northwest Corner 25' East 95' South	0-1 ft	108.3	13.6	106.3	7.8	98	Pass
7	Zone A Northwest Corner 35' East 15' South	0-1 ft	108.3	13.6	107.2	7.6	99	Pass
8	Zone A Northwest Corner 35' East 40' South	0-1 ft	108.3	13.6	104.7	7.0	97	Pass
9	Zone A Northwest Corner 35' East 55' South	0-1 ft	108.3	13.6	103.9	7.6	96	Pass
10	Zone A Northwest Corner 35' East 75' South	0-1 ft	108.3	13.6	104.1	7.3	96	Pass



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

UES Project No: 0210.1800019.0000
UES Report No: 1044093-1 ARC 040318

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: Tuesday, April 03, 2018

Technician: Cleveland English

As requested, a Universal Engineering Sciences Technician was present at the above referenced project site for the purpose of grout testing for the Zone A Cell Fill.

While on site, the technician observed the general condition of the areas to be tested and cast 1 set of (5) specimens for compressive strength testing.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No.: 0210.1800019.0000
Date Typed: March 29, 2018

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Construction Materials Testing Services FIELD AND LABORATORY REPORT COVER PAGE

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

As requested, Universal Engineering Sciences, Inc. (UES) representative(s) performed construction materials testing and/or field inspection services on the above project. Testing results and/or inspection observations are reported on the attached sheets. The contents of this package are summarized below:

Scope of Work

Work Order No.	Date	Type of Report
1043623-1	03/26/2018	Field Inspection Report
1043645-1	03/27/2018	In-Place Density Test Report w/Activity Record
1043646-1	03/28/2018	Field Inspection Report

We hope this information is sufficient for your immediate needs. If you have any questions, please do not hesitate to contact the undersigned.

Sincerely,
Universal Engineering Sciences, Inc.
Certificate of Authorization No. 00000549



Keith L. Butts, P.E. 3-30-18
STATE OF FLORIDA
Professional Engineer No. 53986

Attachments (4)

This item has been electronically signed and sealed by Keith L. Butts, P.E. using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000

UES Report No: 02-1043623

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: 03/26/2018

Technician: Cleveland English

As Requested, a Universal Engineering Sciences Technician was present at the above referenced location for the purpose of obtaining one 1 set of Grout Prisms cast on March 23, 2018 to be returned to the UES Laboratory for further testing.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000
UES Report No: 1043645-1 ARC 032718

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: Tuesday, March 27, 2018

Technician: Cleveland English

As requested, a Universal Engineering Sciences Technician was present at the above referenced project site for the purpose of earthwork testing for the Zone 4.

While on site, the technician observed the general condition of the areas to be tested and performed 4 density tests for Zone 4. The tests were performed in accordance with the ASTM D-6938 Nuclear Gauge Method and were found to meet the project compaction requirements of 98% of the maximum dry density per ASTM D-1557.

The Contractor was notified of the test results or a copy was left for their records.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000

Workorder No: 1043645-1

Report Date: 03/29/2018

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

In-Place Density Test Report

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

UES Technician: Cleveland English

Date Tested: 03/27/2018

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Type of Test:

Field: ASTM D-6938 Nuclear Gauge Method

Laboratory: ASTM D1557 Modified Proctor

Area Tested: Zone 4

Material: Fill

Reference Datum: 0 = Bottom of Footing

The tests below meet the 98% minimum compaction requirement.

Test No.	Location of Test	Range	Maximum Density (pcf)	Optimum Moisture (%)	Field Dry Density (pcf)	Field Moisture (%)	Soil Compaction (%)	Pass or Fail
1	Column Line E-5	-1-0 ft	108.3	13.6	106.3	11.3	98	Pass
2	Column Line E-3	-1-0 ft	108.3	13.6	106.9	10.7	99	Pass
3	Column Line D-4	-1-0 ft	108.3	13.6	105.9	9.9	98	Pass
4	Column Line D-3	-1-0 ft	108.3	13.6	106.1	11.6	98	Pass



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000
UES Report No: 02-1043646

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: 03/28/2018

Technician: Cleveland English

As Requested, a Universal Engineering Sciences Technician was present at the above referenced location for the purpose of observing the placement of reinforcing steel for the Concrete Foundation.

The reinforcing steel was observed to be installed per the details of the project drawings S-0 & S-1 dated April 25, 2017. The reinforcing steel was observed for bar size, quantity, spacing, lap, ties, and clearance.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

UES Project No.: 0210.1800019.0000
Date Typed: April 04, 2018

Construction Materials Testing Services FIELD AND LABORATORY REPORT COVER PAGE

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

As requested, Universal Engineering Sciences, Inc. (UES) representative(s) performed construction materials testing and/or field inspection services on the above project. Testing results and/or inspection observations are reported on the attached sheets. The contents of this package are summarized below:

Scope of Work

Work Order No.	Date	Type of Report
1043676-1	03/30/2018	Field Inspection Report
1044092-1	04/03/2018	In-Place Density Test Report w/Activity Record
1044093-1	04/03/2018	Grout Prism Test Specimens Activity Record

We hope this information is sufficient for your immediate needs. If you have any questions, please do not hesitate to contact the undersigned or Jeannine Seider.

Sincerely,
Universal Engineering Sciences, Inc.
Certificate of Authorization No. 00000549



Keith L. Butts, P.E. 4-6-18
STATE OF FLORIDA
Professional Engineer No. 53986

Attachments (6)
js

This item has been electronically signed and sealed by Keith L. Butts, P.E. using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.

For the mutual protection of Universal's clients, the general public, and ourselves, our reports are submitted as the confidential property of our clients. Accordingly, authorization for reliance upon, or publication of, all or portions of this report is reserved pending our written approval.

Revised May 2015



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000
UES Report No: 02-1043676

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: 03/30/2018

Technician: Cleveland English

As Requested, a Universal Engineering Sciences Technician was present at the above referenced location for the purpose of obtaining (1) set of (5) 4x8 concrete test cylinders cast on 3/29/18 to be returned to the UES Laboratory for further testing.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

UES Project No: 0210.1800019.0000
UES Report No: 1044092-1 ARC 040318

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: Tuesday, April 03, 2018

Technician: Cleveland English

As requested, a Universal Engineering Sciences Technician was present at the above referenced project site for the purpose of earthwork testing for the Zone A.

While on site, the technician observed the general condition of the areas to be tested and performed 10 density tests for Zone A. The tests were performed in accordance with the ASTM D-6938 Nuclear Gauge Method and were found to meet the project compaction requirements of 95% of the maximum dry density per ASTM D-1557.

The Contractor was notified of the test results or a copy was left for their records.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

UES Project No: 0210.1800019.0000

Workorder No: 1044092-1

Report Date: 04/04/2018

In-Place Density Test Report

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

UES Technician: Cleveland English

Date Tested: 04/03/2018

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Type of Test:

Area Tested: Zone A

Field: ASTM D-6938 Nuclear Gauge Method

Material: Fill

Laboratory: ASTM D1557 Modified Proctor

Reference Datum: 0 = Bottom of Fill

The tests below meet the 95% minimum compaction requirement.

Test No.	Location of Test	Range	Maximum Density (pcf)	Optimum Moisture (%)	Field Dry Density (pcf)	Field Moisture (%)	Soil Compaction (%)	Pass or Fail
1	Zone A Northwest Corner 25' East	0-1 ft	108.3	13.6	106.4	6.8	98	Pass
2	Zone A Northwest Corner 25' East 25' South	0-1 ft	108.3	13.6	102.7	6.3	95	Pass
3	Zone A Northwest Corner 25' East 40' South	0-1 ft	108.3	13.6	105.5	5.8	97	Pass
4	Zone A Northwest Corner 25' East 40' South	0-1 ft	108.3	13.6	103.6	5.9	96	Pass
5	Zone A Northwest Corner 25' East 70' South	0-1 ft	108.3	13.6	102.6	7.1	95	Pass
6	Zone A Northwest Corner 25' East 95' South	0-1 ft	108.3	13.6	106.3	7.8	98	Pass
7	Zone A Northwest Corner 35' East 15' South	0-1 ft	108.3	13.6	107.2	7.6	99	Pass
8	Zone A Northwest Corner 35' East 40' South	0-1 ft	108.3	13.6	104.7	7.0	97	Pass
9	Zone A Northwest Corner 35' East 55' South	0-1 ft	108.3	13.6	103.9	7.6	96	Pass
10	Zone A Northwest Corner 35' East 75' South	0-1 ft	108.3	13.6	104.1	7.3	96	Pass

To establish a mutual protection to Universal's clients, the Public and ourselves, all reports are submitted as confidential property of our clients and authorization for publication of statements, conclusions or extracts from or regarding Universal's reports is reserved pending our written approval.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000
UES Report No: 1044093-1 ARC 040318

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: Tuesday, April 03, 2018

Technician: Cleveland English

As requested, a Universal Engineering Sciences Technician was present at the above referenced project site for the purpose of grout testing for the Zone A Cell Fill.

While on site, the technician observed the general condition of the areas to be tested and cast 1 set of (5) specimens for compressive strength testing.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

UES Project No.: 0210.1800019.0000
Date Typed: April 09, 2018

Construction Materials Testing Services FIELD AND LABORATORY REPORT COVER PAGE

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

As requested, Universal Engineering Sciences, Inc. (UES) representative(s) performed construction materials testing and/or field inspection services on the above project. Testing results and/or inspection observations are reported on the attached sheets. The contents of this package are summarized below:

Scope of Work

Work Order No.	Date	Type of Report
1044191-1	04/07/2018	In-Place Density Test Report w/Activity Record

We hope this information is sufficient for your immediate needs. If you have any questions, please do not hesitate to contact the undersigned or Jeannine Seider.

Sincerely,
Universal Engineering Sciences, Inc.
Certificate of Authorization No. 00000549



Keith L. Butts, P.E. 4-11-18
STATE OF FLORIDA
Professional Engineer No. 53986

Attachments (2)
js

This item has been electronically signed and sealed by Keith L. Butts, P.E. using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

UES Project No: 0210.1800019.0000
UES Report No: 1044191-1 ARC 040718

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: Saturday, April 07, 2018

Technician: Cleveland English

As requested, a Universal Engineering Sciences Technician was present at the above referenced project site for the purpose of earthwork testing for the Zone 2.

While on site, the technician observed the general condition of the areas to be tested and performed 10 density tests for Zone 2. The tests were performed in accordance with the ASTM D-6938 Nuclear Gauge Method and were found to meet the project compaction requirements of 95% of the maximum dry density per ASTM D-1557.

The Contractor was notified of the test results or a copy was left for their records.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000

Workorder No: 1044191-1

Report Date: 04/09/2018

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

In-Place Density Test Report

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

UES Technician: Cleveland English

Date Tested: 04/07/2018

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Type of Test:

Area Tested: Zone 2

Field: ASTM D-6938 Nuclear Gauge Method

Material: Fill

Laboratory: ASTM D1557 Modified Proctor

Reference Datum: 0 = Top of Fill

The tests below meet the 95% minimum compaction requirement.

Test No.	Location of Test	Range	Maximum Density (pcf)	Optimum Moisture (%)	Field Dry Density (pcf)	Field Moisture (%)	Soil Compaction (%)	Pass or Fail
1	Zone B Southwest Corner 35' East 20' North	-1-0 ft	108.3	13.6	104.2	7.3	96	Pass
2	Zone B Southwest Corner 35' East 50' North	-1-0 ft	108.3	13.6	106.8	6.8	99	Pass
3	Zone B Southwest Corner 35' East 50' North	-1-0 ft	108.3	13.6	103.7	7.2	96	Pass
4	Zone B Southwest Corner 45' East 70' North	-1-0 ft	108.3	13.6	105.1	8.8	97	Pass
5	Zone B Southwest Corner 45' East 85' North	-1-0 ft	108.3	13.6	107.3	8.8	99	Pass
6	Zone B Southwest Corner 55' East 35' North	-1-0 ft	108.3	13.6	106.6	8.5	98	Pass
7	Zone B Southwest Corner 55' East 60' North	-1-0 ft	108.3	13.6	106.4	7.6	98	Pass
8	Zone B Southwest Corner 55' East 60' North	-1-0 ft	108.3	13.6	102.8	8.0	95	Pass
9	Zone B Southwest Corner 55' East 75' North	-1-0 ft	108.3	13.6	107.4	7.5	99	Pass
10	Zone B Southwest Corner 75' East 20' North	-1-0 ft	108.3	13.6	104.6	6.4	97	Pass



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

UES Project No.: 0210.1800019.0000
Date Typed: April 06, 2018

Construction Materials Testing Services FIELD AND LABORATORY REPORT COVER PAGE

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

As requested, Universal Engineering Sciences, Inc. (UES) representative(s) performed construction materials testing and/or field inspection services on the above project. Testing results and/or inspection observations are reported on the attached sheets. The contents of this package are summarized below:

Scope of Work

Work Order No.	Date	Type of Report
1044094-1	04/05/2018	Field Inspection Report
1044121-1	04/05/2018	4" x 8" Cylinder Test Specimens Activity Record
1044122-1	04/06/2018	Field Inspection Report

We hope this information is sufficient for your immediate needs. If you have any questions, please do not hesitate to contact the undersigned or Jeannine Seider.

Sincerely,
Universal Engineering Sciences, Inc.
Certificate of Authorization No. 00000549



Keith L. Butts, P.E. 4-11-18
STATE OF FLORIDA
Professional Engineer No. 53986

Attachments (3)
js

This item has been electronically signed and sealed by Keith L. Butts, P.E. using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000
UES Report No: 02-1044094

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: 04/05/2018

Technician: Cleveland English

As Requested, a Universal Engineering Sciences Technician was present at the above referenced location for the purpose of obtaining (1) set of (5) Grout Prisms cast on 4/3/18 to be returned to the UES Laboratory for further testing.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

UES Project No: 0210.1800019.0000
UES Report No: 1044121-1 ARC 040518

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: Thursday, April 05, 2018

Technician: Cleveland English

As requested, a Universal Engineering Sciences Technician was present at the above referenced project site for the purpose of concrete testing for the Zone A.

While on site, the technician observed the general condition of the areas to be tested and cast 4 sets of (5) 4 x 8 specimens for compressive strength testing.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000
UES Report No: 02-1044122

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: 04/06/2018

Technician: Cleveland English

As Requested, a Universal Engineering Sciences Technician was present at the above referenced location for the purpose of obtaining (4) sets of concrete cylinders cast on 4/5/18 to be returned to the UES Laboratory for further testing.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

UES Project No.: 0210.1800019.0000
Date Typed: April 11, 2018

Construction Materials Testing Services FIELD AND LABORATORY REPORT COVER PAGE

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

As requested, Universal Engineering Sciences, Inc. (UES) representative(s) performed construction materials testing and/or field inspection services on the above project. Testing results and/or inspection observations are reported on the attached sheets. The contents of this package are summarized below:

Scope of Work

Work Order No.	Date	Type of Report
1044159-1	04/09/2018	Grout Prism Test Specimens Activity Record
1044272-1	04/10/2018	Field Inspection Report

We hope this information is sufficient for your immediate needs. If you have any questions, please do not hesitate to contact the undersigned or Jeannine Seider.

Sincerely,
Universal Engineering Sciences, Inc.
Certificate of Authorization No. 00000549



Keith L. Butts, P.E. 4-18-18
STATE OF FLORIDA
Professional Engineer No. 53986

Attachments (2)
js

This item has been electronically signed and sealed by Keith L. Butts, P.E. using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000
UES Report No: 1044159-1 ARC 040918

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: Monday, April 09, 2018

Technician: Cleveland English

As requested, a Universal Engineering Sciences Technician was present at the above referenced project site for the purpose of grout testing for the Zone 2 (12" Stemwall).

While on site, the technician observed the general condition of the areas to be tested and cast 1 set of 4 specimens for compressive strength testing.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

UES Project No: 0210.1800019.0000
UES Report No: 02-1044272

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC
40 South Palafox Place, Suite 400
Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD
385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: 04/10/2018

Technician: Cleveland English

As Requested, a Universal Engineering Sciences Technician was present at the above referenced location for the purpose of obtaining one set of Grout Prisms cast on April 9, 2018, to be returned to the UES Laboratory for further testing.

This test was performed without deviation from ASTM procedures.

This report shall not be reproduced, except in full, without the written approval of Universal Engineering Sciences.

