

Work Order

| | | | |
|------------------|---|------------------------|---|
| Number | 2025-00014356 | Request Date | 11/10/2025 12:00:00 AM |
| Type | Water Inspection | Schedule Date | 11/12/2025 12:00:00 AM |
| Priority | | Assign Date | |
| Requester | Amy Fernandez | Assigned To | Scott, William Brian |
| Account | 143340-001 JM Phelps Construction LLC Phone: | Service Address | 372 SW WINDSWEPT GLN LAKE CITY, FL 32024 |


| | |
|-----------------|---|
| Comments | 243 - Schedule 11/12/25 10-11 - Please give to Kevin - Josh can be reached at 850-851-7934 - Verify that they connected to the water meter correctly AF |
|-----------------|---|

| New Meter Device | | | | |
|------------------|--|-----------------------|--|--|
| | | | | |
| | | meter number 97704127 | | |
| | | | | |
| | | MXU number 137215396 | | |
| | | | | |

Read

0000010

Read



Customer on site
11:00am—11:45am

Read Date

11 / 12 / 2025

Read Date

___ / ___ / ___

Comments

Water meter check valve and Back Flow installed properly

Water meter and Back Flow front left by telephone pole

Completed By:



Work Order

| | | | |
|------------------|---|------------------------|---|
| Number | 2025-00014355 | Request Date | 11/10/2025 12:00:00 AM |
| Type | Irr. Inspection | Schedule Date | 11/12/2025 12:00:00 AM |
| Priority | | Assign Date | |
| Requester | Amy Fernandez | Assigned To | Scott, William Brian |
| Account | 143340-001 JM Phelps Construction LLC Phone: | Service Address | 372 SW WINDSWEPT GLN LAKE CITY, FL 32024 |

| | |
|-----------------|---|
| Comments | 243 - Schedule 11/12/25 10-11 - Please give to Kevin - Josh can be reached at 850-851-7934 - Verify that they connected to the water meter correctly AF |
|-----------------|---|

| New Meter Device | | | | |
|------------------|--|------------------------|--|--|
| | | | | |
| | | Meter number 100600776 | | |
| | | | | |
| | | MXU number 137214666 | | |
| | | | | |

Read

0000010

Read

AF

Customer on site

11:00am-11:45am

Read Date

11 / 12 / 2025

Read Date

/ /

Comments

water meter check valve and backflow installed properly

Water meter and Back Flow front left by telephone pole

Completed By:

Kap

Work Order


| | | | |
|------------------|---|------------------------|---|
| Number | 2025-00014357 | Request Date | 11/10/2025 12:00:00 AM |
| Type | Sewer Inspection | Schedule Date | 11/12/2025 12:00:00 AM |
| Priority | | Assign Date | |
| Requester | Amy Fernandez | Assigned To | Scott, William Brian |
| Account | 143340-001 JM Phelps Construction LLC Phone: | Service Address | 372 SW WINDSWEPT GLN LAKE CITY, FL 32024 |

| | |
|-----------------|---|
| Comments | 243 - Schedule 11/12/25 10-11 - Please give to Kevin - Josh can be reached at 850-851-7934 - Verify that they connected to the sewer tap correctly AF |
|-----------------|---|

| New Meter Device | | | | |
|------------------|--|--|--|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Read

Read



Read Date

11 / 12 / 2025

Read Date

___ / ___ / ___

Comments

Sewer and clean out installed properly building owner on

Sewer and clean out front right of building by driveway

Completed By:

Kap