

Work Order

Number	2025-00004394	Request Date	4/1/2025 12:00:00 AM
Type	Water Inspection	Schedule Date	4/1/2025 12:00:00 AM
Priority		Assign Date	
Requester	Shasta Pelham	Assigned To	Scott, William Brian
Account	143301-001 C.A. Boone Construction Phone:	Service Address	375 SW SISTERS WELCOME RD LAKE CITY, FL 32025

Comments	12:29 pm Col Brooks (352-284-4618) said the water was already on. The plumber came this morning and installed and certified the backflow preventer. Please verify if they connected to water meter 93632150 correctly. - SMP
-----------------	--

New Meter Device				

Read <u>0000010</u> <hr/> <hr/> <hr/>	Read <hr/> <hr/> <hr/>
---	----------------------------------

Read Date <u>04</u> / <u>01</u> / <u>25</u>	Read Date ____ / ____ / ____
--	-------------------------------------

Comments Customer side plumbed properly, backflow installed

Completed By: NW/CJ

Work Order

Number	2025-00004395	Request Date	4/1/2025 12:00:00 AM
Type	Sewer Inspection	Schedule Date	4/1/2025 12:00:00 AM
Priority		Assign Date	
Requester	Shasta Pelham	Assigned To	Scott, William Brian
Account	143301-001 C.A. Boone Construction Phone:	Service Address	375 SW SISTERS WELCOME RD LAKE CITY, FL 32025

Comments	12:33 pm Please verify if they connected to the sewer tap correctly. Col Brooks can be reached at 352-284-4618 if needed. - SMP
-----------------	---

New Meter Device				

Read _____ _____ _____ _____	Read _____ _____ _____ _____
---	---

Read Date <u> 04 </u> / <u> 01 </u> / <u> 25 </u>	Read Date <u> </u> / <u> </u> / <u> </u>
--	--

Comments Sewer tap and clanout are correct

Completed By: NW/CJ