

UES Project No.: 0210.1800019.0000 Date Typed: April 02, 2018

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

## **Construction Materials Testing Services** FIELD AND LABORATORY REPORT COVER PAGE

Client: SF Brevard, LLC

40 South Palafox Place, Suite 400

Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD

385 SW Property Place, Lake City, Columbia County, FL 32024

As requested, Universal Engineering Sciences, Inc. (UES) representative(s) performed construction materials testing and/or field inspection services on the above project. Testing results and/or inspection observations are reported on the attached sheets. The contents of this package are summarized below:

## Scope of Work

Work Order No.	Date	Type of Report
1043675-1	03/29/2018	4" x 8" Cylinder Test Specimens Activity Record
1043709-1	03/29/2018	Field Inspection Report

We hope this information is sufficient for your immediate needs. If you have any questions, please do not hesitate to contact the undersigned.

> Sincerely, Universal Engineering Sciences, Inc. Certificate of Authorization No. 00000549

Attachments (2)

Keith L. Butts, P.E. 4-3-18 STATE OF FLORIDA

Professional Engineer No. 53986

This item has been electronically signed and sealed by Keith L. Butts, P.E. using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.



**UES Project No:** 0210.1800019.0000 **UES Report No:** 1043675-1 ARC 032918

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

**Activity Record** 

Client: SF Brevard, LLC

40 South Palafox Place, Suite 400

Pensacola, FL 32502

**Project:** The Rehab Center of Lake City, CSD

385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: Thursday, March 29, 2018

**Technician:** Cleveland English

As requested, a Universal Engineering Sciences Technician was present at the above referenced project site for the purpose of concrete testing for the South Foundations.

While on site, the technician observed the general condition of the areas to be tested and cast 1 set of 5 - 4 x 8 specimens for compressive strength testing.

**UES Project No:** 0210.1800019.0000 **UES Report No:** 02-1043709

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352,372,3392 - F: 352,336,7914

**Activity Record** 

Client: SF Brevard, LLC

40 South Palafox Place, Suite 400

Building Code Administration, Compliance Inspection & Plan Review

Pensacola, FL 32502

**Project:** The Rehab Center of Lake City, CSD

385 SW Property Place, Lake City, Columbia County, FL 32024

**Date of Activity:** 03/29/2018

Cleveland English

Technician:

As Requested, a Universal Engineering Sciences Technician was present at the above referenced location for the purpose of observing the placement of reinforcing steel for masonry units placed on Column Line A from Column Line 1 to Column Line 5. The reinforcement was observed at (10 Feet and Cleanouts).

The reinforcing steel was observed to be installed per the details of the project drawings S.0 and S.1 dated 5/25/2017. The reinforcing steel was observed for bar size, quantity, spacing, lap, ties, and clearance.