

FIELD DENSITY WORKSHEET

CLIENT Maranda Homes DATE 12-4-24
 PROJECT NAME Forest Cove Lot 3 PROJECT NO. _____
 EARTH CONTRACTOR ZIS PERMIT NO. _____
 COMPACTION REQUIREMENT (%) 95 ☐ Standard Proctor TESTED BY CE
☒ Modified Proctor FIELD CONTACT _____
 TOTAL ON-SITE TIME _____ MILES FROM OFFICE _____
☐ Limerock ☐ Subgrade ☐ Pipe Backfill ☒ Building Pad ☐ Building Footing ☐ Other _____

TEST LOCATION	LAB PROCTOR		TEST DEPTH	PROBE DEPTH	% MOIST.	WET DENSITY (PCF)	DRY DENSITY (PCF)	% COMP.
	DENS.	OMC						
Approx 15' NE of SW corner	108.2	9.4	FLG	12"	36	110.3	106.5	98.4
11' CTR of Pad	1	1	1	1	42	111.7	107.2	99.1
15' SW of NE corner	1	1	1	1	33	109.0	105.5	97.5

REMARKS _____

- * Density failed to meet minimum project requirement
- ** Retest indicates minimum density requirement was obtained.
- () Client is aware of unsatisfactory test results.