

**Inspection Solutions, LLC.
PO BOX 219
Starke, Florida, 32091**

**Columbia County
Building Inspection Division
Private Provider Inspection Result**

Project: Residential Swimming Pool

Inspection Type; Coping Footing

Inspection Date: 1-8-23
Contractor's Name: Florida Leisure Pool & Spa, Inc.
Permit Number: 000048658
Building Address: 1911 SW CR 252B, Lake City, FL 32024
Parcel Number: 10-4S-16-02862-118
Private Provider Firm: Inspection Solutions, LLC.
Private Provider Name: Kevin Powell – BU 1814
Duly Authorized Rep's Name: Kevin Powell – BN 4866

Inspection Performed: Coping Footing
Inspection work code(s):
Result of Inspection: Pass

To the best of my knowledge and belief, the building components outlined herein and inspected under my authority have been completed in conformance with the approved plans and the applicable codes.

Signature of Private Provider or Duly Authorized Representative:

Kevin Powell 
Certified Building Code Administrator

I hereby certify that the information indicated in this report or supplement report is true and accurate and that my electronic signature shall have the same legal effect as if made under oath.