

OSTDS Application for Construction (Repair System) Page # 1



STATE OF FLORIDA DEPARTMENT OF HEALTH ONSITE SEWAGE DISPOSAL SYSTEM APPLICATION FOR CONSTRUCTION PERMIT Authority: Chapkay 301, FS

CENTRAK #: 12-SC-03356 DATE PAID: 4/2/02 FEE PAID: \$ 115.00 RECEIPT: OSTOSNR: 02-0268-R

02111887

Rotate Right 90°

Rotate 180

Default Orientation System [] Existing System [] Holding Tank [] Innovative [X] Repair [] Abandonment [] Temporary [NA]

Full Size

APPLICANT: Moore, Hugh TELEPHONE: 386 752-3000

Delete Images Property Owner, Owner MAILING ADDRESS: P O Box 844 Ida 32056 Close Window

TO BE COMPLETED BY APPLICANT OR APPLICANT'S AUTHORIZED AGENT. ATTACH BUILDING PLAN AND TO-SCALE SITE PLAN SHOWING PERTINENT FEATURES REQUIRED BY CHAPTER 64E 6, FLORIDA ADMINISTRATIVE CODE

PROPERTY INFORMATION (IF LOT IS NOT IN A RECORDED SUBDIVISION, ATTACH LEGAL DESCRIPTION OR DEED)

LOT: 19 BLOCK 5 SUBDIVISION: Wilson Springs Unrec PLATTED:

PROPERTY ID #: --- ZONING: I / M OR EQUIVALENT: [Y / N]

PROPERTY SIZE: 1.45 ACRES (Sqt/43560) PROPERTY WATER SUPPLY: [X] PRIVATE [] PUBLIC

IS SEWER AVAILABLE AS PER 381.0068, FLORIDA STATUTES? [Y / N] DISTANCE TO SEWER: --- FT

PROPERTY STREET ADDRESS: Memorial Dr, Ft White

DIRECTIONS TO PROPERTY: wilson springs rd turn on memorial dr, property on right, light blue house

BUILDING INFORMATION [X] RESIDENTIAL [] COMMERCIAL

Table with 6 columns: Unit No, Type of Establishment, No of Bedrooms, Building Area Sqt, # Persons Served, Business Activity For Commercial Only. Row 1: 0, 1 Bdrm Single/Multi Fa, 1, 672, 2.

[Y] Floor/Equipment Drains [N] Other (Specify)

APPLICANT'S SIGNATURE: Hugh H. Moore DATE: 4/2/02

OSTDS Final Approval Page # 1

N 2A 90058°
W 057.75957°

rechecked
4/16/02



STATE OF FLORIDA
DEPARTMENT OF HEALTH
ON-SITE SEWAGE TREATMENT AND DISPOSAL SYSTEM
CONSTRUCTION INSPECTION AND FINAL APPROVAL

CENTRAX #: 12-SC-03386
DATE PAID: _____
FEE PAID: _____
RECEIPT: _____
OUTDNR #: 02-0268-R

APPLICANT: Moore, Hugh AGENT: OWNER

Default Orientation

PROPERTY STREET ADDRESS: Memorial Dr Ft White FL 32038

Lot: 19 BLOCK: 5 SUBDIVISION: Wilson Springs Unrec
[Section/Township/Range/Parcel No.]
Delete Image [OR TAX ID NUMBER]

Close Window: ITEMS ARE NOT IN COMPLIANCE WITH CHAPTER 64E-6, FLORIDA ADMINISTRATIVE CODE

TANK INSTALLATION		SETBACKS	
[]	(01) TANK SIZE <u>750</u> [2]	[]	(27) SURFACE WATER
[]	(02) TANK MATERIAL <u>plc - case</u>	[]	(28) DITCHES
[]	(03) OUTLET DEVICE	[]	(29) PRIVATE WELLS
[]	(04) MULTI CHAMBERS	[]	(30) PUBLIC WELLS
[]	(05) LEGEND	[]	(31) IRRIGATION WELLS
[]	(06) WATER TIGHT	[]	(32) POTABLE WATER LINES
[]	(07) LEVEL	[]	(33) BUILDING FOUNDATION
[]	(08) DEPTH OF LID	[]	(34) PROPERTY LINES
[]	(09) AREA [1] <u>150</u> [2] <u>SOFT</u>	[]	(35) OTHER
[]	(10) DISTRIBUTION BOX <u>HEAD</u>	[]	FILLED/MOUND SYSTEM
[]	(11) NUMBER OF DRAINLINES <u>1 (50)</u>	[]	(36) DRAINFIELD COVER
[]	(12) DRAINLINE SEPARATION	[]	(37) SHOULDERS
[]	(13) DRAINLINE SLOPE	[]	(38) SLOPES
[]	(14) DEPTH OF COVER	[]	(39) STABILIZATION MATERIAL
[]	(15) SYSTEM ELEVATION <u>19 below 80</u>	[]	ADDITIONAL INFORMATION
[]	(16) SYSTEM LOCATION	[]	(40) UNOBSTRUCTED AREA
[]	(17) DOSING PUMPS	[]	(41) STORMWATER RUNOFF
[]	(18) AGGREGATE SIZE	[]	(42) ALARMS
[]	(19) AGGREGATE SOURCE	[]	(43) MAINTENANCE AGREEMENT
[]	(20) AGGREGATE WASHED	[]	(44) BULLDOING AREA
[]	(21) AGGREGATE DEPTH	[]	(45) PLUMBING FIXTURES
[]	FILL/EXCAVATION MATERIAL	[]	(46) FINAL SITE GRADING
[]	(22) FILL AMOUNT	[]	(47) CONTRACTOR <u>A & B 4/18 10:00</u>
[]	(23) FILL TEXTURE	[]	(48) OTHER <u>rubber rock</u>
[]	(24) EXCAVATION DEPTH	[]	ABANDONMENT
[]	(25) EXCAVATION AREA	[]	(49) TANK PUMPED
[]	(26) REPLACEMENT MATERIAL	[]	(50) TANK CRUSHED AND FILLED

EXPLANATION OF VIOLATIONS:

CONSTRUCTION (APPROVE/DISAPPROVE) J. A. Owens Columbia CHD Date: 4/15/02
FINAL SYSTEM (APPROVE/DISAPPROVE) J. A. Owens Columbia CHD Date: 4/18/02



STATE OF FLORIDA
 DEPARTMENT OF ENVIRONMENTAL PROTECTION
 ONSITE SEWAGE TREATMENT AND DISPOSAL SYSTEM
 EXISTING SYSTEM AND SYSTEM REPAIR EVALUATION

PERMIT # _____

APPLICANT: Steve Norris 493 SW Memorial Dr Ft. White 32038

CONTRACTOR / AGENT: Raymond Howard Septic Tank Service LLC

LOT: _____ BLOCK: _____ SUBDIV: _____ ID#: _____

TO BE COMPLETED BY FLORIDA REGISTERED ENGINEER, DEPARTMENT EMPLOYEE, SEPTIC TANK CONTRACTOR OR OTHER CERTIFIED PERSON. SIGN AND SEAL ALL SUBMITTED DOCUMENTS. COMPLETE ALL APPLICABLE ITEMS. COMPLETE TANK CERTIFICATION BELOW OR NOTE IN REMARKS WHY THE TANKS CANNOT BE CERTIFIED.

EXISTING TANK INFORMATION

[800] GALLONS SEPTIC TANK/GPD ATU LEGEND: _____ MATERIAL: Concrete BAFFLED: [Y / N]
 [] GALLONS SEPTIC TANK/GPD ATU LEGEND: _____ MATERIAL: _____ BAFFLED: [Y / N]
 [] GALLONS GREASE INTERCEPTOR LEGEND: _____ MATERIAL: _____
 [] GALLONS DOSING TANK LEGEND: _____ MATERIAL: _____ # PUMPS: []

I CERTIFY THAT THE LISTED TANKS WERE PUMPED ON 11 / 13 / 24 BY Deric King, HAVE THE VOLUMES SPECIFIED AS DETERMINED BY [DIMENSIONS / FILLING / LEGEND], ARE FREE OF OBSERVABLE DEFECTS OR LEAKS, AND HAVE A [SOLIDS DEPLETION DEVICE / OUTLET FILTER DEVICE] INSTALLED.

Raymond Howard SIGNATURE OF LICENSED CONTRACTOR
Raymond Howard Septic Tank Service LLC BUSINESS NAME
11/20/24 DATE

EXISTING DRAINFIELD INFORMATION

[] SQUARE FEET PRIMARY DRAINFIELD SYSTEM NO. OF TRENCHES [] DIMENSIONS: _____ X _____
 [] SQUARE FEET SYSTEM NO. OF TRENCHES [] DIMENSIONS: _____ X _____
 TYPE OF SYSTEM [] STANDARD [] FILLED [] MOUND []
 CONFIGURATION: [] TRENCH [] DBO []
 DESIGN: [] HEADER [] D-BOX [] GRAVITY SYSTEM [] DOSED SYSTEM
 ELEVATION OF BOTTOM OF DRAINFIELD IN RELATION TO NATURAL GRADE _____ INCHES [ABOVE / BELOW]

SYSTEM FAILURE AND REPAIR INFORMATION

[] SYSTEM INSTALLATION DATE TYPE OF WASTE [] DOMESTIC [] COMMERCIAL
 [] GPD ESTIMATED SEWAGE FLOW BASED ON [] METERED WATER [] TABLE I, 62-6, FAC
 SITE [] DRAINAGE STRUCTURES [] POOL [] PATIO / DECK [] PARKING
 CONDITIONS: [] SLOPING PROPERTY []
 NATURE OF [] HYDRAULIC OVERLOAD [] SOILS [] MAINTENANCE [] SYSTEM DAMAGE
 FAILURE [] DRAINAGE / RUN OFF [] ROOTS [] WATER TABLE []
 FAILURE [] SEWAGE ON GROUND [] TANK [] D BOX/HEADER [] DRAINFIELD
 SYMPTOM. [] PLUMBING BACKUP []

REMARKS/ADDITIONAL CRITERIA 25x61x46 No cracks in tank, looks good.

SUBMITTED BY: _____ TITLE/LICENSE # _____ DATE: _____

