

SCOPE OF WORK

PERMIT #: _____

JOB SITE ADDRESS: 1861 SE Oleno Rd. High Springs, FL

BUILDING (INTERIOR)

☐ No structural work being done.

1. Complete Demo and Remodel
2. New Bathroom stalls and flooring
- 3.

BUILDING (EXTERIOR)

☐ No structural work being done.

1. Adding 9 new Rafters to support new Entrance
2. Paint
- 3.

MECHANICAL

☐ No mechanical work being done.

1. N/A
- 2.
- 3.

ELECTRICAL

☐ No electrical work being done.

1. New panel box and interior wiring
- 2.
- 3.

PLUMBING

☐ No plumbing work being done.

1. All new plumbing
2. Using existing septic tank
- 3.

GAS

☐ No gas work being done.

1. N/A
- 2.
- 3.

ROOF

☐ No roof work being done.

1. N/A
- 2.
- 3.