



Checklist:

<input type="checkbox"/> Address	<input type="checkbox"/> Application Submitted	
<input type="checkbox"/> Drive/ROW	<input type="checkbox"/> Zoning Review	<input type="checkbox"/> Legal Lot of Record
<input type="checkbox"/> Septic	<input type="checkbox"/> Plans Reviewed	<input type="checkbox"/> Flood Zone
<input type="checkbox"/> Site Use Approved	<input type="checkbox"/> Required Inspections Assigned	<input type="checkbox"/> FDEP Needed
<input type="checkbox"/> Docs Reviewed/Accepted	<input type="checkbox"/> Invoiced	

APPLICANT: JIMMY MARSHAL SELLERS

PHONE: (860) 952-4112

ADDRESS: 5655 CARTER RD, ORLANDO, FL 32810

OWNER: MUNOZ MARTIN C,

PHONE: (386) 466-2803

ADDRESS: 461 SW ANGELA TER LAKE CITY, FL 32024

PARCEL ID: 24-4S-16-03116-004

SUBDIVISION: PICCADILLY PARK REPLAT UNR

LOT: 10 BLOCK: A PHASE: _____ UNIT: _____ ACRES: 0.74

CONTRACTOR	TYPE	LIC#	BUSINESS NAME
RENEWAL BY ANDERSEN FL - JIMMY SELLERS	General		RENEWAL BY ANDERSEN FL

JOB DETAILS

Description of the work being performed:	Remove and Replace 10 Windows, like for like, No Structural Changes.
Total Estimated Cost	35614
Commercial or Residential?	Residential
Type of Structure	House
Heated Area (Sqft)	1787
Total Area (Sqft)	1787
If remodel of damage, what was the cause?	N/A
Site Plan Setbacks Front	00
Site Plan Setback Side 1	00
Site Plan Setback Side 2	00
Site Plan Setbacks Rear	00
Existing Dwelling Units	
Septic#	
Power Company Used:	
Service Amps	
Current Use/Occupancy of building:	Single Family Residence
Is this changing?	No
If Yes, Explain, Proposed Use/Occupancy	
Is the building Fire Sprinkled?	
Are blue prints included?	
Any driveway changes?	
Please explain any Ingress/Egress changes:	

Review Notes: