

1402-32
CODE ENFORCEMENT
PRELIMINARY MOBILE HOME INSPECTION REPORT

DATE RECEIVED _____ BY Ut IS THE M/H ON THE PROPERTY WHERE THE PERMIT WILL BE ISSUED? Yes

OWNERS NAME Curtis Anderson PHONE _____ CELL 288-5763

ADDRESS 2047 NW Hamp farmer Rd

MOBILE HOME PARK _____ SUBDIVISION _____

DRIVING DIRECTIONS TO MOBILE HOME 441 North, (L) Hamp farmer, on (R)
Just before Canosa Rd (20 Acre wooded property)

MOBILE HOME INSTALLER Bernie Thrift PHONE _____ CELL 623-0046

MOBILE HOME INFORMATION

MAKE Fleetwood YEAR 92 SIZE 14 x 60 COLOR _____

SERIAL No. 1

WIND ZONE II Must be wind zone II or higher NO WIND ZONE I ALLOWED

INSPECTION STANDARDS

INTERIOR:

(P or F) - P= PASS F= FAILED

\$50.00

P SMOKE DETECTOR () OPERATIONAL () MISSING

Date of Payment 2-19-14

P FLOORS () SOLID () WEAK () HOLES DAMAGED LOCATION _____

Paid By Curtis Anderson

P DOORS () OPERABLE () DAMAGED

Notes Cash paid

P WALLS () SOLID () STRUCTURALLY UNSOUND

P WINDOWS () OPERABLE () INOPERABLE

P PLUMBING FIXTURES () OPERABLE () INOPERABLE () MISSING

P CEILING () SOLID () HOLES () LEAKS APPARENT

P ELECTRICAL (FIXTURES/OUTLETS) () OPERABLE () EXPOSED WIRING () OUTLET COVERS MISSING () LIGHT FIXTURES MISSING

EXTERIOR:

P WALLS / SIDING () LOOSE SIDING () STRUCTURALLY UNSOUND () NOT WEATHERTIGHT () NEEDS CLEANING

P WINDOWS () CRACKED/ BROKEN GLASS () SCREENS MISSING () WEATHERTIGHT

P ROOF () APPEARS SOLID () DAMAGED

STATUS

APPROVED ✓ WITH CONDITIONS: _____

NOT APPROVED _____ NEED RE-INSPECTION FOR FOLLOWING CONDITIONS _____

SIGNATURE Joe C ID NUMBER 306 DATE 2-20-14