

Columbia County, FL. Building & Zoning Swimming Pool and Spa Permit #000039407



OWNER: WINNER-HALL DEBORAH ADDRESS:

PHONE: 407.421.7443 **DATE ISSUED:** March 05, 2020 210 SW BLUEBERRY PL LAKE CITY, FL 32024

PARCEL ID: 25-4S-16-03121-057 ACRES: 0.00

SUBDIVISION: PICCADILLY PARK SOUTH LOT: 5 BLK: D PHASE: UNIT:

ZONING: RESIDENTIAL - LOW RSF-2 **FLOOD ZONE:** X **Latitude:** 30.114009 **Longitude:** -82.668101

CONTRACTOR

NAME: MICHAEL CANTO ADDRESS: PHONE: 352.332.7665 3601 NW 97TH BLVD

BUSINESS: FUN STATE POOLS GAINESVILLE, FL 32606 LICENSE: CPC1457306 -

PROJECT DETAILS

EXISTING HOME

IS THIS FOR RESIDENTIAL OR COMMERCIAL USE?: Residential THIS IS THE CONSTRUCTION OF A:: ADA COMPLIANT: No TOTAL ESTIMATED COST: 35000 **SETBACKS FRONT: SETBACK SIDE 1:** 10 **SETBACK SIDE 2:** SETBACKS REAR: SEPTIC #: 20-0114 **BUILDING CODE EDITION:** Florida Building Code 2017 6th Edition & 2014

Notice: in addition to the requirements of this permit, there may be additional restrictions applicable to this property that may be found in the public records of this county. The issuance of this permit does not waive compliance by permittee with deed restrictions. **Notice:** all other applicable state or federal permits shall be obtained before commencement of this permitted development.

National Electrical Code

"WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF COMMENCEMENT."

Every permit issued shall become invalid unless the work authorized by such permit is commenced within 180 days after its issuance, or if the work authorized by such permit is suspended or abandoned for a period of 180 days after the time the work is commenced. A valid permit receives an approved inspection every 180 days. Work shall be considered not suspended, abandoned or invalid when the permit has received an approved inspection within 180 days of the previous inspection.