

## COLUMBIA COUNTY BUILDING DEPARTMENT Blower Door Test Results Form

Date: 2 - 28 - 18	Permit Number: 0000 35632
Job Address: 196 SW Hally Glen	Lake City FL 32024
AIR INFILTRATION TEST RESULTS	
CFM (50) = 795	
Volume = 7722	
ACH (50) = CFH (50) X 60 / Volume = 47 700	PASSFAII
CERTIFICATION OF TEST RESULTS	
exceeding 7 air changes per hour in Climate Zones 1 and through 8. Testing shall be conducted with a blower doc shall be conducted by either individuals as defined in Se	oor at a pressure of 0.2 inches w.g. (50 Pascals). Testing ection 553.993(5) or (7), Florida Statutes or individuals or an approved third party. A written report of the resultest and provided to the code official. Testing shall be
I hereby certify that the above Air Infiltration Florida Energy Code requirements in accord Building Code-Energy Conservation R402.4.	
Testing Company Name: TC Testing	Service LLC
Tester Name: Tanya C. Sikes Tester Signature Janya C. Sikes	Lic./Cert.#: 6059953
Tester Signature Janya C. S. ko	<u> </u>
135 NE Hernando Avenue, 8-21	
Care City, FL 320CC	Phone: 386-758-1008 Fax: 386-758-2160
www.columbiacountyfla.com	Lav. 200-130-1100