

CODE ENFORCEMENT  
PRELIMINARY MOBILE HOME INSPECTION REPORT

DATE RECEIVED \_\_\_\_\_ BY \_\_\_\_\_ IS THE M/H ON THE PROPERTY WHERE THE PERMIT WILL BE ISSUED? Yes  
OWNERS NAME John + Sarah Ruark PHONE 386 454-7599 CELL \_\_\_\_\_  
ADDRESS 232 SW Dana Gln, Fort White, FL 32038

MOBILE HOME PARK \_\_\_\_\_ SUBDIVISION \_\_\_\_\_

DRIVING DIRECTIONS TO MOBILE HOME Turn on Rum Island Terrace, come down to SW Dana Gln - on your right - 1st gate on the left 232 (on the gate)

MOBILE HOME INSTALLER Dale Houston PHONE \_\_\_\_\_ CELL 386-623-6522

MOBILE HOME INFORMATION

MAKE HRT0 YEAR 2010 SIZE 28' x 52' COLOR Cream

SERIAL No. 402348

WIND ZONE 2 Must be wind zone II or higher NO WIND ZONE I ALLOWED

INSPECTION STANDARDS

INTERIOR:

(P or F) - P= PASS F= FAILED

- SMOKE DETECTOR  OPERATIONAL ( ) MISSING
- FLOORS  SOLID ( ) WEAK ( ) HOLES DAMAGED LOCATION \_\_\_\_\_
- DOORS  OPERABLE ( ) DAMAGED
- WALLS  SOLID ( ) STRUCTURALLY UNSOUND
- WINDOWS  OPERABLE ( ) INOPERABLE
- PLUMBING FIXTURES  OPERABLE ( ) INOPERABLE ( ) MISSING
- CEILING  SOLID ( ) HOLES ( ) LEAKS APPARENT
- ELECTRICAL (FIXTURES/OUTLETS)  OPERABLE ( ) EXPOSED WIRING ( ) OUTLET COVERS MISSING ( ) LIGHT FIXTURES MISSING

EXTERIOR:

- WALLS / SIDING  LOOSE SIDING ( ) STRUCTURALLY UNSOUND ( ) NOT WEATHERTIGHT ( ) NEEDS CLEANING
- WINDOWS ( ) CRACKED/ BROKEN GLASS ( ) SCREENS MISSING  WEATHERTIGHT
- ROOF  APPEARS SOLID ( ) DAMAGED

STATUS

APPROVED \_\_\_\_\_ WITH CONDITIONS: \_\_\_\_\_

NOT APPROVED \_\_\_\_\_ NEED RE-INSPECTION FOR FOLLOWING CONDITIONS \_\_\_\_\_

SIGNATURE \_\_\_\_\_ ID NUMBER \_\_\_\_\_ DATE \_\_\_\_\_