



STATE OF FLORIDA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
ONSITE SEWAGE TREATMENT AND DISPOSAL SYSTEM  
EXISTING SYSTEM AND SYSTEM REPAIR EVALUATION

PERMIT # \_\_\_\_\_

APPLICANT:

Reed McDaniel Construction / Harrell

CONTRACTOR / AGENT: LUNDY'S SEPTIC INC / ADAM LUNDY

LOT: \_\_\_\_\_ BLOCK: \_\_\_\_\_ SUBDIV: \_\_\_\_\_ ID#: \_\_\_\_\_

TO BE COMPLETED BY FLORIDA REGISTERED ENGINEER, DEPARTMENT EMPLOYEE, SEPTIC TANK CONTRACTOR OR OTHER CERTIFIED PERSON. SIGN AND SEAL ALL SUBMITTED DOCUMENTS. COMPLETE ALL APPLICABLE ITEMS. COMPLETE TANK CERTIFICATION BELOW OR NOTE IN REMARKS WHY THE TANKS CANNOT BE CERTIFIED.

EXISTING TANK INFORMATION

[ 1050 ]	GALLONS SEPTIC TANK/GPD ATU	LEGEND: _____	MATERIAL: <u>Concrete</u>	BAFFLED: [ Y / <u>N</u> ]
[ ]	GALLONS SEPTIC TANK/GPD ATU	LEGEND: _____	MATERIAL: _____	BAFFLED: [ Y / N ]
[ ]	GALLONS GREASE INTERCEPTOR	LEGEND: _____	MATERIAL: _____	
[ ]	GALLONS DOSING TANK	LEGEND: _____	MATERIAL: _____	# PUMPS: [ ]

I CERTIFY THAT THE LISTED TANKS WERE PUMPED ON 4/22/24 BY LUNDY'S SEPTIC, HAVE THE VOLUMES SPECIFIED AS DETERMINED BY [ DIMENSIONS / FILLING / LEGEND ], ARE FREE OF OBSERVABLE DEFECTS OR LEAKS, AND HAVE A [ SOLIDS DEFLECTION DEVICE / OUTLET FILTER DEVICE ] INSTALLED

Adam W Lundy LUNDY'S SEPTIC INC\* 4/22/24  
SIGNATURE OF LICENSED CONTRACTOR BUSINESS NAME DATE

EXISTING DRAINFIELD INFORMATION Tank appears to be in good condition

[ ]	SQUARE FEET PRIMARY DRAINFIELD SYSTEM	NO. OF TRENCHES [ ]	DIMENSIONS: _____	X
[ ]	SQUARE FEET _____ SYSTEM	NO. OF TRENCHES [ ]	DIMENSIONS: _____	X

TYPE OF SYSTEM: [ ] STANDARD [ ] FILLED [ ] MOUND [ ] \_\_\_\_\_  
CONFIGURATION: [ ] TRENCH [ ] BED [ ] \_\_\_\_\_  
DESIGN: [ ] HEADER [ ] D-BOX [ ] GRAVITY SYSTEM [ ] DOSED SYSTEM  
ELEVATION OF BOTTOM OF DRAINFIELD IN RELATION TO NATURAL GRADE \_\_\_\_\_ INCHES [ ABOVE / BELOW ]

SYSTEM FAILURE AND REPAIR INFORMATION

[ ] SYSTEM INSTALLATION DATE TYPE OF WASTE [ ] DOMESTIC [ ] COMMERCIAL  
[ ] GPD ESTIMATED SEWAGE FLOW BASED ON [ ] METERED WATER [ ] TABLE I, 62-6, FAC

SITE [ ] DRAINAGE STRUCTURES [ ] POOL [ ] PATIO / DECK [ ] PARKING  
CONDITIONS: [ ] SLOPING PROPERTY [ ] \_\_\_\_\_

NATURE OF [ ] HYDRAULIC OVERLOAD [ ] SOILS [ ] MAINTENANCE [ ] SYSTEM DAMAGE  
FAILURE: [ ] DRAINAGE / RUN OFF [ ] ROOTS [ ] WATER TABLE [ ] \_\_\_\_\_

FAILURE [ ] SEWAGE ON GROUND [ ] TANK [ ] D BOX/HEADER [ ] DRAINFIELD  
SYMPTOM: [ ] PLUMBING BACKUP [ ] \_\_\_\_\_

REMARKS/ADDITIONAL CRITERIA Tank Dimensions: \_\_\_\_\_ Inches Wide \_\_\_\_\_ Inches Long \_\_\_\_\_ Inches Deep

1402 SW Tommy Lites, St  
Fl. White

Adam Lundy

SUBMITTED BY: \_\_\_\_\_ TITLE/LICENSE \_\_\_\_\_ DATE: \_\_\_\_\_