



Initial Roof Inspection

Client Information

Client Name	Scott Cassady
Address	403 SW Sunday glen
City	Lake city
State	Florida
Zip Code	32024

Roof Photos - Ground Level

Mailbox	Jan 13, 2024 01:28 PM 
Front Elevation	Jan 13, 2024 12:51 PM 



Initial Roof Inspection

Right Elevation



Left Elevation




Rear Elevation





Initial Roof Inspection

Drip Edge present?	Yes
Drip Edge Photos	Jan 13, 2024 01:29 PM 
Gutter Screen/ Gutter Guards present?	No
Gutter Damage Photos	



Initial Roof Inspection

Items that may need protection



Roof Photos - On Roof

Front Slope






Initial Roof Inspection

Right Slope



Left Slope





Initial Roof Inspection

Rear Slope	 Jan 13, 2024 12:32 PM A high-angle photograph of a steep, grey-shingled roof slope. A person's leg and foot are visible in the lower right corner. In the background, a white building with a red roof and a grassy area are visible under a blue sky with some clouds.
Pipe Jacks present?	Yes
How many?	2
Pipe Jack Photos	 Jan 13, 2024 12:33 PM A close-up photograph of a grey-shingled roof. A white pipe jack is visible in the center of the frame. A shadow of the person taking the photo is cast on the roof to the left. A white building is visible in the upper right corner.



Initial Roof Inspection

	Jan 13, 2024 12:33 PM 	
Power vent present?	No	
Exhaust vent present?	No	
Chimney present?	Yes	
Chimney photos	Jan 13, 2024 12:33 PM 	



Initial Roof Inspection

Skylights present?	No
Turtle Boxes present?	No
Ridge vent present?	Yes
Ridge vent photos	Jan 13, 2024 12:34 PM  Jan 13, 2024 12:37 PM 



Initial Roof Inspection

	
Satellite Dish?	Yes
Satellite Dish photos	
Solar Panels?	No



Initial Roof Inspection

General Notes

What kind of roof damage was found?	Hail
Photos	Jan 13, 2024 12:34 PM  Jan 13, 2024 12:35 PM 



Initial Roof Inspection





Initial Roof Inspection





Initial Roof Inspection





Initial Roof Inspection





Initial Roof Inspection





Initial Roof Inspection





Initial Roof Inspection





Date Submitted: 01-13-2024 01:43 PM
Submitted By: jesse.nolan@jandmroofing.com

Initial Roof Inspection

Jan 13, 2024 01:10 PM

