



Columbia County, FL. Building & Zoning

New Residential Construction Permit #000039491

Issued March 19, 2020



OWNER: WILBURN & SYLVIA FENDER

PHONE: 813-361-2826

ADDRESS: 6046 SE COUNTY ROAD 252 LAKE CITY, FL 32025

PARCEL: 30-4S-18-10513-008

ZONING: AGRICULTURE - 3 A-3

FLOOD ZONE: X

Coords: 30.11,-82.55

SUBDIVISION: HIGH FALLS UNR

LOT: **BLK:** **PHASE:** **UNIT:** **ACRES:** 5.12

CONTRACTOR

NAME: DOUGLAS EDGLEY

BUSINESS: CEE-BAS INCORPORATED DBA EDGLEY

ADDRESS:

590 SW ARLINGTON BLVD.,
SUITE 113
LAKE CITY, FL 32055

PHONE: 623-6654

LICENSE: CRC1330689 -

PROJECT DETAILS

EACH 5 AC LOT IS LEGAL LOT OF RECORD, HOUSE LOCATED OUT OF A ZONE PER SITE PLAN

THIS IS THE CONSTRUCTION OF A:	Single Family Dwelling
HEATED AREA (SQFT):	1715
TOTAL AREA (SQFT):	2763
STORIES:	1
BUILDING HEIGHT:	19
BUILDING CODE CONSTRUCTION TYPE:	V
BUILDING CODE ELEMENT:	B
BUILDING CODE OCCUPANCY TYPES:	Residential
OCCUPANCY USE TITLE:	single family
SETBACKS FRONT:	30
SETBACK SIDE 1:	25
SETBACK SIDE 2:	25
SETBACKS REAR:	25
BUILDING CODE EDITION:	Florida Building Code 2017 6th Edition & 2014 National Electrical Code
ELEVATION REGULATION:	Minimum Requirement
FINISHED FLOOR REQUIREMENT:	One foot above the road
IN FLOODWAY :	N

Notice: in addition to the requirements of this permit, there may be additional restrictions applicable to this property that may be found in the public records of this county. The issuance of this permit does not waive compliance by permittee with deed restrictions.

Notice: all other applicable state or federal permits shall be obtained before commencement of this permitted development.

"WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF COMMENCEMENT."

Every permit issued shall become invalid unless the work authorized by such permit is commenced within 180 days after its issuance, or if the work authorized by such permit is suspended or abandoned for a period of 180 days after the time the work is commenced. A valid permit receives an approved inspection every 180 days. Work shall be considered not suspended, abandoned or invalid when the permit has received an approved inspection within 180 days of the previous inspection.