

RE: Permit Number:

3/087

Inspection Affidavit

I LEVIN Beders And , licensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle Lic. Type) FS 468 Building Inspector*
License #; CCC 1329482
On or about 74A7 31 2013 12:00 Pm, I did personally inspect the (Date & time)
roof deck attachment secondary water barrier roof to wall connection
work at 102 NW HARRIS Cake Pene, Cake CL 3205-5-
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)
Signature
STATE OF FLORIDA COUNTY OF Sworn to and subscribed before me this 3 day of June . 201 3
By White State of Florida
WILLIAM H JOHNS MY COMMISSION #DD972377 Or SM2NFF6 MARA 2014 Bonded through 1st State Insurance

* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

Produced Identification Type of identification produced.

- * Photographs must clearly show all work and have the permit number indicated on the roof.
- * Affidavit and Photographs must be provided when final inspection is requested.