



Logged in as: Brad Davis, Georgia IPJA User | [Change Password](#) | [Logout](#)

04/22/2014 03:03 PM

[Site Map](#) | [IBIS Home](#)

- [F101](#)
- [F301](#)
- [F302](#)
- [OMB](#)
- [UPDATE](#)
- [Adjust](#)
- [Search](#)
- [Print](#)
- [Archive](#)
- [List](#)
- [Report](#)
- [Print](#)
- [Alert](#)

Label Search

IPJA: Start Date: End Date:

Label No: Label Start No:

Plant Code: Serial No: Label End No:

☐ Exact Match

Note : Use % for wild card search.

Label Number	IPJA	Status	Date	Print	Serial Number	Type	Origin Name	City	State	Zip
0080475523	GEO	S	04/23/1987	CONR04	8840	S	CONNER	JAX BCH	FL	

Showing 1 to 1 of 1

- [Search](#)
- [Sort](#)
- [Close](#)
- [Print](#)

Baker County did not issue MH Permits prior
to 1997 1/2 year. M/H was on property prior
to that. ~~Only~~ documentation is deed in 01
showing **FAX** ~~M/H~~ already on property, Jenny Hamilton
Baker County did require Wind Zone
2 M/Hs even then.

Cell: 386-984-7470
W/Li 386-719-5451

This M/H is RP'd since 2008
9-26-08

To:

Company:

404-656-3205

Trailer ID #:

Fax Number:

913867195456

CHCE GA 68 147 008840

Phone Number:

Donald Broughman

From:

BRADD

20345 Benny Jo
Sanderson fc Bennett Rd

Fax Number:

Phone Number

Time Sent:

Tuesday, Apr 22, 2014 03:17PM

Pages:

2

Description:

Per Troy Crews, with this information we can
reasonably determine the M/H is a Wind Zone II.
Ok to Permit.

Brad Davis

Spoke to Jenny on 4/28/14 L.J.H.

CODE ENFORCEMENT
PRELIMINARY MOBILE HOME INSPECTION REPORT

DATE RECEIVED 5-20-14 BY JL IS THE M/H ON THE PROPERTY WHERE THE PERMIT WILL BE ISSUED? YES

OWNERS NAME JENNY HAMILTON PHONE _____ CELL 984-7470

ADDRESS _____

MOBILE HOME PARK _____ SUBDIVISION OLD WINE FOREST - UNREC - LOT 10

DRIVING DIRECTIONS TO MOBILE HOME 47-S to C-238, TL to OLD WINE, TL to
MA NEWOOD, TR @ END to GRAPES VINE, TR to END ON L.

MOBILE HOME INSTALLER FERMON JONES PHONE _____ CELL 352-318-4711

MOBILE HOME INFORMATION

MAKE CONNER YEAR 1987 SIZE 14 X 70 COLOR WHITE

SERIAL No. XCHCEGA68 147008846

WIND ZONE II Must be wind zone II or higher NO WIND ZONE I ALLOWED Pending Verification

INSPECTION STANDARDS

INTERIOR:

(P or F) - P= PASS F= FAILED

P SMOKE DETECTOR () OPERATIONAL () MISSING

F FLOORS () SOLID () WEAK () HOLES DAMAGED LOCATION Rear Bed room Repair

P DOORS () OPERABLE () DAMAGED

P WALLS () SOLID () STRUCTURALLY UNSOUND some repairs

F WINDOWS () OPERABLE () INOPERABLE

P PLUMBING FIXTURES () OPERABLE () INOPERABLE () MISSING

P CEILING () SOLID () HOLES () LEAKS APPARENT

P ELECTRICAL (FIXTURES/OUTLETS) () OPERABLE () EXPOSED WIRING () OUTLET COVERS MISSING () LIGHT
FIXTURES MISSING

GEO 475523
Zone II
Based on Permit
in other County

EXTERIOR:

P WALLS / SIDING () LOOSE SIDING () STRUCTURALLY UNSOUND () NOT WEATHERTIGHT () NEEDS CLEANING

F WINDOWS () CRACKED/ BROKEN GLASS () SCREENS MISSING () WEATHERTIGHT

P ROOF () APPEARS SOLID () DAMAGED

STATUS

APPROVED ✓ WITH CONDITIONS: Fix Rear Window Several Floor Repairs

NOT APPROVED _____ NEED RE-INSPECTION FOR FOLLOWING CONDITIONS _____

SIGNATURE Jay C

ID NUMBER 306 DATE 5-21-14