## CODE ENFORCEMENT PRELIMINARY MOBILE HOME INSPECTION REPORT

OWNERS NAME Jason Schnapp **PHONE** ADDRESS 2153 SE October Rd, Lake Coty for 32025 SUBDIVISION MOBILE HOME PARK Across from Walmant DRIVING DIRECTIONS TO MOBILE HOME \_\_\_ MOBILE HOME INSTALLER Bernie Throft PHONE CELL 623 - 5046 MOBILE HOME INFORMATION YEAR 06 SIZE 28 X 60 COLOR Beign MAKE three of Merit SERIAL No. WIND ZONE Must be wind zone II or higher NO WIND ZONE I ALLOWED INSPECTION STANDARDS INTERIOR: \$50 00 (P or F) - P= PASS F= FAILED SMOKE DETECTOR () OPERATIONAL () MISSING Date of Payment 4-1-19 FLOORS () SOLID () WEAK () HOLES DAMAGED LOCATION \_ Paid By Tiffany Chaucey DOORS () OPERABLE () DAMAGED WALLS () SOLID () STRUCTURALLY UNSOUND WINDOWS () OPERABLE () INOPERABLE PLUMBING FIXTURES ( ) OPERABLE ( ) INOPERABLE ( ) MISSING CEILING () SOLID () HOLES () LEAKS APPARENT ELECTRICAL (FIXTURES/OUTLETS) ( ) OPERABLE ( ) EXPOSED WIRING ( ) OUTLET COVERS MISSING ( ) LIGHT **FIXTURES MISSING** WALLS / SIDDING ( ) LOOSE SIDING ( ) STRUCTURALLY UNSOUND ( ) NOT WEATHERTIGHT ( ) NEEDS CLEANING WINDOWS ( ) CRACKED/ BROKEN GLASS ( ) SCREENS MISSING ( ) WEATHERTIGHT ROOF () APPEARS SOLID () DAMAGED **STATUS** WITH CONDITIONS: NOT APPROVED \_\_\_\_\_ NEED RE-INSPECTION FOR FOLLOWING CONDITIONS\_

SIGNATURE

ID NUMBER 306 DATE 4-2-1