

FIELD DENSITY WORKSHEET

CLIENT Maranda Homes DATE 4-4-25
 PROJECT NAME Forest Cove Lot 4 PROJECT NO. 25-1866-1577
 EARTH CONTRACTOR 248 SW Augustine Glen Lake City PERMIT NO. _____
 COMPACTION REQUIREMENT (%) 95 ☐ Standard Proctor TESTED BY CE
☒ Modified Proctor FIELD CONTACT _____
 TOTAL ON-SITE TIME _____ MILES FROM OFFICE _____
☐ Limerock ☐ Subgrade ☐ Pipe Backfill ☒ Building Pad ☐ Building Footing ☐ Other _____

TEST LOCATION	LAB PROCTOR		TEST DEPTH	PROBE DEPTH	% MOIST.	WET DENSITY (PCF)	DRY DENSITY (PCF)	% COMP.
	DENS.	OMC						
Approx 15' NW of SE corner	1130	9.7	FL	12"	45	115.7	110.7	98.0
170' of Pad	1	1	1	1	49	117.2	111.8	98.9
15' SE of NW corner	1	1	1	1	40	114.3	109.9	97.3

REMARKS _____

* Density failed to meet minimum project requirement
 ** Retest indicates minimum density requirement was obtained.
 () Client is aware of unsatisfactory test results.