

Deck nailing

A close-up photograph of a wooden deck surface. The wood is light brown with visible grain and numerous dark spots, possibly from moisture or insects. A sharp shadow of a person's leg and foot is cast across the upper left portion of the image. The text "Deck nailing" is overlaid in a large, bold, yellow font across the middle of the image.

Deck nailing



New wood

Roof nailing



New wood

The background of the image is a close-up of a wooden surface. The upper portion is composed of oriented strand board (OSB), showing a dense, chaotic pattern of light-colored wood chips and fibers. The lower portion is a smoother, darker brown material, likely plywood, which has a more uniform texture with some visible grain and small dark spots. A horizontal line separates the two materials.

New wood

New wood

THIS SIDE DOWN
STRENGTHENED
SPACE PAVING
18 INCH
ATTEND
No Pulgades
En Los Finales
Palas Coadas

Georgia Pacific



New wood

The background image shows a piece of corrugated cardboard with various markings. On the left, there is a logo for 'North Pacific' and some text including 'Product of the United States'. In the center, there is a date stamp 'SEP 29 2012' and '11:26'. On the right, there is a large 'APA' logo, the text 'MILL 500', and a circular logo with 'AB' inside. At the bottom right, there is a logo for 'SA 30 FOR INIT'.

A close-up photograph of wooden roof decking. The image shows several horizontal wooden planks with a light brown, weathered appearance. There are numerous dark spots, possibly knots or stains, scattered across the surface. A vertical seam or joint runs down the center of the image. Several silver-colored nails are visible, securing the planks. Overlaid on the lower half of the image is the text "Roof deck nail" in a bold, yellow, sans-serif font.

Roof deck nail