



**COLUMBIA COUNTY
BUILDING DEPARTMENT
Roof Inspection Affidavit**

Permit Number: 000038755

I Lewis Walker

Print name

, licensed as a(n) Contractor* / Engineer/Architect,
FS 468 Building Inspector*

License #: RC0067442

did personally inspect the

On or about Nov 22, 2019

(Date & time)

☒ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal
manufacturer's instructions

☒ Roof deck attachment ☐ Secondary water barrier ☐ Roof to wall connection

work at 131 Sw webbs Gln, Lake city, FL 32024

(Job Site Address)

Based upon that examination I have determined the installation was done according
to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

[Signature]
Contractor's Signature

STATE OF FLORIDA
COUNTY OF COLUMBIA



BARBARA JOHNSTON
Commission # GG 306135
Expires May 6, 2023
Bonded Thru Budget Notary Services

Sworn to and subscribed before me this 25 day of November, 2019

By Lewis Walker, Notary Public, State of Florida

[Signature]
(Print, type or stamp name)

Personally known ☒ or

Produced Identification ☐ Type of identification produced. _____

* Include photographs of each plane of the roof with the permit
number clearly shown marked on the deck for each inspection.
Place a tape measure next to the nailing pattern to show distance
between nails.

* Photographs must clearly show all work and have the permit
number indicated on the roof.

* Affidavit and Photographs must be provided when final
inspection is requested.

* Metal overlay & purlin installations shall have photographs of
purlins or underlayment, whichever applies.