

## Columbia County, FL. Building & Zoning **Roof Replacement or Repair Permit** #000038996



**OWNER: SPICER PAUL & KATHLEEN** ADDRESS:

**PHONE**: 386-590-1040 DATE ISSUED: December 09, 2019 1880 SW COUNTY ROAD 778 FORT WHITE, FL 32038

PARCEL ID: 17-7S-17-10012-026 **ACRES: 4.93** 

SUBDIVISION: BLK: PHASE: UNIT:

ZONING: AGRICULTURE - 3 A-3 FLOOD ZONE: X **Latitude:** 29.886483 **Longitude:** -82.638671

CONTRACTOR

ADDRESS: **PHONE:** 386.364.6464 NAME: PAUL SPICER POB 460

**BUSINESS:** SPICER CONSTRUCTION, INC. LIVE OAK, FL 32064 LICENSE: CCC048156 -

## PROJECT DETAILS

TYPE OF STRUCTURE: Mobile Home **COST OF CONSTRUCTION:** 5000.00 COMMERCIAL OR RESIDENTIAL: Residential ROOF AREA (FOR THIS JOB) SQ FT: ROOF PITCH: 4/12 IS THE EXISTING ROOF BEING REMOVED?: TYPE OF NEW ROOFING PRODUCT: FLORIDA PRODUCT APPROVAL NUMBER: fl4595.10 **BUILDING CODE EDITION:** Florida Building Code 2017 6th Edition & 2014 National Electrical Code

Notice: in addition to the requirements of this permit, there may be additional restrictions applicable to this property that may be found in the public records of this county. The issuance of this permit does not waive compliance by permittee with deed restrictions. Notice: all other applicable state or federal permits shall be obtained before commencement of this permitted development.

"WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF COMMENCEMENT."

Every permit issued shall become invalid unless the work authorized by such permit is commenced within 180 days after its issuance, or if the work authorized by such permit is suspended or abandoned for a period of 180 days after the time the work is commenced. A valid permit receives an approved inspection every 180 days. Work shall be considered not suspended, abandoned or invalid when the permit has received an approved inspection within 180 days of the previous inspection.