DATE 07/05/2006		•	Building Pe ar From the Date o		PERMIT
APPLICANT STAC	Y BECKHAM	expires One re	PHONE	352-745-2738	000024707
ADDRESS 269	SW PARER LANE		LAKE CITY		FL 32024
OWNER JACO	B & REBECCA JONES		PHONE		
ADDRESS 166	NW DEER RUN (LOT	I) GLENN	LAKE CITY		FL 32055
CONTRACTOR	STACY BECKHAM		PHONE	352-745-2738	
LOCATION OF PRO	PERTY 441 N, ACRO	SS FROM TAMMY	LN, L INTO DEER RUI	N MH PARK	
	TAKE 1ST LA	ANE TO END ON L	EFT		
TYPE DEVELOPME	NT MH,UTLIY	EST	TIMATED COST OF CO	NSTRUCTION	0.00
HEATED FLOOR AR	EA	TOTAL ARE	Α	HEIGHT	STORIES
FOUNDATION	WALLS	R	ООГ РІТСН	FLO	OR
LAND USE & ZONIN	IG RSF/MH-2		MAX	. HEIGHT 35	
Minimum Set Back Re	equirments: STREET-FRO	ONT 25.00	REAR	15.00	SIDE 10.00
NO. EX.D.U. 13	FLOOD ZONE	x	DEVELOPMENT PERM	MIT NO.	
PARCEL ID 17-3S	-17-05018-000	SUBDIVISION	N DEER RUN MOBI	LE HOM PARK	
LOT I BLOC	CK PHASE	UNIT	ТОТА	AL ACRES	
			-	12-111	
		H0000512		MA	
Culvert Permit No. EXISTING	Culvert Waiver Contr 05-0610-N	actor's License Num BK	ber	Applicant/Owner/C	
Driveway Connection	Septic Tank Number	LU & Zoning		roved for Issuance	N New Resident
-	R ONE FOOT ABOVE THE I	·		10704 107 155441100	
SECTION 2.3.8 MH PA		, 101111	S DAID I III III I		
				Check # or Cas	h 2164
	FOR BUILI	DING & ZONIN	G DEPARTMENT	ONLY	(footer/Slab)
Temporary Power		Foundation		Monolithic	(looter/Slab)
_	date/app. by		date/app. by	-	date/app. by
Under slab rough-in plu		Slab		Sheathing/Na	ailing
Framing	date/app. by		date/app. by		date/app. by
	Ro	ough-in plumbing abo	ove slab and below wood	floor	date/app. by
Electrical rough-in		eat & Air Duct	,	Dani karan (Tintak)	date/app. by
_	date/app. by		date/app. by	Peri. beam (Lintel)	date/app. by
Permanent power	date/app. by	C.O. Final		Culvert	****
M/H tie downs blocking	g, electricity and plumbing	da	te/app. by	D. 1	date/app. by
	5, olooutony and planfoling	date/app.	by	Pool	date/app. by
Reconnection	date/app. by	Pump pole	Utility Pole		
M/H Pole	Travel 7		pp. by	date/app. by Re-roof	
date/app. b	у	da	te/app. by		date/app. by
BUILDING PERMIT F	EE \$ 0.00 CE	RTIFICATION FEE	\$ 0.00	CLIDOLLABOR	EE & 0.00
	CE	KILITICATION FEE	φ <u>0.00</u>	SURCHARGE F	EE \$ 0.00
MISC. FEES \$ 20					
	0.00 ZONING CER	T. FEE \$ 50.00	FIRE FEE \$	WASTE	FEE \$

NOTICE: IN ADDITION TO THE REQUIREMENTS OF THIS PERMIT, THERE MAY BE ADDITIONAL RESTRICTIONS APPLICABLE TO THIS PROPERTY THAT MAY BE FOUND IN THE PUBLIC RECORDS OF THIS COUNTY. AND THERE MAY BE ADDITIONAL PERMITS REQUIRED FROM OTHER GOVERNMENTAL ENTITIES SUCH AS WATER MANAGEMENT DISTRICTS, STATE AGENCIES, OR FEDERAL AGENCIES.

INSPECTORS OFFICE

"WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF COMMENCEMENT."

CLERKS OFFICE

This Permit Must Be Prominently Posted on Premises During Construction

PLEASE NOTIFY THE COLUMBIA COUNTY BUILDING DEPARTMENT AT LEAST 24 HOURS IN ADVANCE OF EACH INSPECTION, IN ORDER THAT IT MAY BE MADE WITHOUT DELAY OR INCONVIENCE, PHONE 758-1008. THIS PERMIT IS NOT VALID UNLESS THE WORK AUTHORIZED BY IT IS COMMENCED WITHIN 6 MONTHS AFTER ISSUANCE.

	PERMIT APPLICATION / MANUFACTURED HOME INSTALLATION APPLICATION
	TOFFICE Use Only (Revised 8-23-05) Zoning Official CK 29.06.06 Building Official OK TH 6-21-06
AP	# 0606-8/ Date Received 6-2/-06 By LH Permit # 24707
FIG	ood Zone X Development Permit N/A Zoning Land Use Plan Map Category
Co	mments Section 2.3.8 Mobile Home Park as a Nonconforming use
FE	MA Map# Elevation Finished Floor River In Floodway
J.	Site Plan with Setbacks Shown DEH Signed Site Plan DEH Release DWeil letter Existing well
4	Copy of Recorded Deed or Affidavit from land owner Letter of Authorization from installer
	Lot I Deer Run MHP
	Property ID # Must have a copy of the property deed
	New Mobile Home Used Mobile Home Year/98 o
	Applicant Stacy Beckham Phone # 352-745-2238
	Address 0/19 See Parter LN hote Cit X1. 82024
	Name of Property Owner Neer Aun MHP Phone#
	911 Address Kelle NW Deer Run Lots Hear LC A. 72055
	Circle the correct power company - FL Power & Light - Clay Electric
	(Circle One) - <u>Suwannee Valley Electric</u> - <u>Progress Energy</u>
	Name of Owner of Mobile Home Deer Aun MHP Phone #
	AddressPhone #
	Relationship to Property Owner Same
	Current Number of Dwellings on Property
	Lot Size Total Acreage
	Do you : Have an Existing Drive or need a Culvert Permit or a Culvert Waiver (Circle one)
	is this Mobile Home Replacing an Existing Mobile Home 1/e5
	Driving Directions to the Property 441 North 4 Dew Am MHD
	Lot I across from Tammy lan 1st lane to the
3	and on the left.
	Name of Licensed Dealer/Installer Stary Breckhon Phone # 352745-2238
	Installers Address 369 Sw Porter KN Lote Cit. 4.32024 License Number J. HO0008/2 Installation Decel # 187677
	Installation Decal # Installation Decal #

	manings wall plans within 2 of end of homes par Rule 15C	Show locations of Longitudinal and Lateral Systems (use dark lines to show these locations)	if home is a triple or quad wide sketch in remainder of home I understand Lateral Arm Systems cannot be used on any home (new or used) where the sidewall ties exceed 5 ft 4 in. Installer's initials	Installer Shey Bethan License # THEROSTZ Address of home being installed Manufacturer Dried Color one half of the blocking plan
within 2' of end of home spaced at 5' 4" oc Sidewall Longitudinal Stabilizing Device w/ Lateral Arms Manufacturer Mithin 2' of end of home spaced at 5' 4" oc Sidewall Longitudinal Marriage wall Shearwall	18.5 × 18.5 × 18.5 × 18.5 × 18.5 × 18.5 × 18.5 × 17 × 22.5 × 20 × 20 × 20 × 20 × 20 × 20 × 25 1/2 × 25 1/2 × 24 × 24 × 24 × 24 × 24 × 24 × 24 ×	city (sq in) (200) (342) (400) (404) (200)	PIER SPACING TABLE FOR USED HOMES 16" x 16" 18 1/2" x 18 1/2" 20" x 20" 22" x 22" 24" x 24" 2	New Home Used Home Home installed to the Manufacturer's Installation Manual Home is installed in accordance with Rule 15-C Single wide Wind Zone II Wind Zone III Double wide Installation Decal # 15-627 Triple/Quad Serial # SRUMF 3725/6098

PERMIT NUMBER

1. Test the perimeter of the home at 6 locations. 2. Take the reading at the depth of the footer. 3. Using 500 lb. increments, take the lowest reading and round down to that increment. XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	The pocket penetrometer tests are rounded down to 50 psf or check here to declare 1000 lb. soil without testing.
---	--

TORQUE PROBE TEST

The results of the torque probe test is $^{1}\!\!\!/\,\ell\!\!\!\!/\,\ell\!\!\!\!/\,\ell$ inch pounds or check here if you are declaring 5' anchors without testing . A test showing 275 inch pounds or less will require 4 foot anchors.

Note: A state approved lateral arm system is being used and 4 ft. anchors are allowed at the sidewall locations. I understand 5 ft anchors are required at all centerline tie points where the torque test reading is 275 or less and where the mobile home manufacturer may requires anchors with 4000 by holding capacity.

Installer's initials

ALL TESTS MUST BE PERFORMED BY A LICENSED INSTALLER

installer Name

Date Tested

6/14/8

Electrical

Connect electrical conductors between multi-wide units, but not to the main power source. This includes the bonding wire between multi-wide units. Pg/5

Plumbing

Connect all sewer drains to an existing sewer tap or septic tank. Pg. 15^{-6}

Connect all potable water supply piping to an existing water meter, water tap, or other independent water supply systems. Pg. ///

Site Preparation

Debris and organic material removed

Water drainage: Natural Swale Pad Other

Fastening multi wide units

Floor: Type Fastener:

Walls: Type Fastener:

Roof: Type Fastener:

For used homes a min. 30 gauge, 8" wide, galvanized metal strip will be centered over the peak of the roof and fastened with galv. roofing natis at 2" on center on both sides of the centerline.

Gasket (weatherproofing requirement)

I understand a properly installed gasket is a requirement of all new and used homes and that condensation, mold, meldew and buckled marriage walls are a result of a poorly installed or no gasket being installed. I understand a strip of tape will not serve as a gasket.

Installer's initials
Installed:
Between Floors Yes
Between Walls Yes
Bottom of ridgebeam Yes

Type gasket

Weatherproofing

The bottomboard will be repaired and/or taped. Yes
Siding on units is installed to manufacturer's specifications. Yes
Fireplace chimney installed so as not to allow intrusion of rain water. Yes

Miscellaneous

Skirting to be installed. Yes
Dryer vent installed outside of skirting. Yes
Range downflow vent installed outside of skirting. Yes
Drain lines supported at 4 foot intervals. Yes
Electrical crossovers protected. Yes
Other:

Installer verifies all information given with this permit worksheet is accurate and true based on the

manufacturer's installation instructions and or Rule 15C-1 & 2
Installer Signature

Butter

Bu

Columbia County Property Appraiser DB Last Updated: 6/19/2006

Parcel: 17-3S-17-05018-000

2006 Proposed Values

Interactive GIS Map | Print Tax Record **Property Card**

Owner & Property Info

Owner's Name JONES JACOB W & REBECCA C			
Site Address			
Mailing Address	CO-TRUSTEES 301 NW BROOKSIDE CT LAKE CITY, FL 32055		
Description	N1/2 OF NE1/4 OF NW1/4 OF SW1/4. ORB 625- 561, 726-166, 762-1760, 813-2377, (DEER RUN MH PARK)WD 1017-1492		

<< Prev Se	arch Result: 6 of 14 Next >>
Use Desc. (code)	PARKING/MH (002802)
Neighborhood	17317.00
Tax District	2
UD Codes	MKTA03
Market Area	06
Total Land Area	5.000 ACRES

Property & Assessment Values

Mkt Land Value	cnt: (3)	\$32,500.00
Ag Land Value	cnt: (0)	\$0.00
Building Value	cnt: (12)	\$46,219.00
XFOB Value	cnt: (2)	\$63,400.00
Total Appraised Value		\$142,119.00

Just Value	\$142,119.00
Class Value	\$0.00
Assessed Value	\$142,119.00
Exempt Value	\$0.00
Total Taxable Value	\$142,119.00

Sales History

Sale Date	Book/Page	Inst. Type	Sale VImp	Sale Qual	Sale RCode	Sale Price
6/3/2004	1017/1492	WD	I	Q		\$172,500.00
11/22/1995	813/2377	WD	I	U	08	\$125,000.00
7/21/1992	762/1760	СТ	I	U	11	\$20,000.00

Building Characteristics


Bldg Item	Bldg Desc	Year Blt	Ext. Walls	Heated S.F.	Actual S.F.	Bldg Value
1	MOBILE HME (000800)	1972	Alum Siding (26)	1614	1752	\$9,261.00
2	MOBILE HME (000800)	1972	Alum Siding (26)	720	720	\$3,066.00
3	MOBILE HME (000800)	1969	Alum Siding (26)	576	672	\$2,555.00
4	MOBILE HME (000800)	1972	Alum Siding (26)	960	1768	\$5,681.00
_ 5	MOBILE HME (000800)	1968	Alum Siding (26)	768	896	\$3,407.00
6	MOBILE HME (000800)	1972	Alum Siding (26)	720	720	\$3,066.00
7	MOBILE HME (000800)	1973	Alum Siding (26)	720	720	\$3,066.00
9	MOBILE HME (000800)	1973	Alum Siding (26)	684	844	\$3,253.00
10	MOBILE HME (000800)	1961	Alum Siding (26)	672	744	\$3,132.00
11	MOBILE HME (000800)	1972	Alum Siding (26)	792	792	\$3,632.00
12	MOBILE HME (000800)	1963	Alum Siding (26)	672	672	\$3,050.00
13	MOBILE HME (000800)	1973	Alum Siding (26)	672	672	\$3,050.00
	Note: All S.F. calculations are based on exterior building dimensions.					

Extra Features & Out Buildings

Code	Desc	Year Blt	Value	Units	Dims	Condition (% Good)
0259	MHP HOOKUP	0	\$62,400.00	13.000	0 x 0 x 0	(.00)
					**	


Application for Onsite Sewage Disposal System Construction Permit. Part II Site Plan Permit Application Number: 05-06/01/

ALL CHANGES MUST BE APPROVED BY THE COUNTY HEALTH UNIT





PRELIMINARY MOBILE HOME INSPECTION REPORT

	- ZI-06 BY LH IS THE M/H ON THE PROPERTY WHERE THE PERMIT WILL BE ISSUED? YES
NERS NAME	Tacob & Nebecca Jones PHONE CELL
RESS	
	RK Deer Run MHPark SUBDIVISION
	ONS TO MOBILE HOME 441 North, (1) into Decr Aun, 1st
	lane to the end on ((Got I)
	Share I dila mare
	STALLERStavey beelelenPHONECELL
	INFORMATION OF THE STATE OF TH
AKE	stigadene YEAR SO SIZE 14 x 1,0 COLOR Peach & Who
	Must be wind zone II or higher NO WIND ZONE I ALLOWED
	INSPECTION STANDARDS
NTERIOR: P or F) - P= P	PASS F= FAILED
	SMOKE DETECTOR () OPERATIONAL () MISSING
	FLOORS () SOLID () WEAK () HOLES DAMAGED LOCATION
	DOORS () OPERABLE () DAMAGED
	WALLS () SOLID () STRUCTURALLY UNSOUND
	WINDOWS () OPERABLE () INOPERABLE
	PLUMBING FIXTURES () OPERABLE () INOPERABLE () MISSING
	CEILING () SOLID () HOLES () LEAKS APPARENT
EXTERIOR:	ELECTRICAL (FIXTURES/OUTLETS) () OPERABLE () EXPOSED WIRING () OUTLET COVERS MISSING () LIGHT FIXTURES MISSING
	WALLS / SIDDING () LOOSE SIDING () STRUCTURALLY UNSOUND () NOT WEATHERTIGHT () NEEDS CLEANING
	WINDOWS () CRACKED/ BROKEN GLASS () SCREENS MISSING () WEATHERTIGHT
	ROOF () APPEARS SOLID () DAMAGED
STATUS: APPROVED	WITH CONDITIONS:
	DNEED REINSPECTION FOR FOLLOWING CONDITIONS
CICMATIBE	ID NUMBER DATE
TIMINAL OVE	VAISVAIS



This information, GIS Map Updated: 6/19/2006, was derived from data which was compiled by the Columbia County Property Appraiser
Office solely for the governmental purpose of property assessment. This information should not be relied upon by anyone as a
determination of the ownership of property or market value. No warranties, expressed or implied, are provided for the accuracy of the data
herein, it's use, or it's interpretation. Although it is periodically updated, this information may not reflect the data currently on file in the
Property Appraiser's office. The assessed values are NOT certified values and therefore are subject to change before being finalized for ad
valorem assessment purposes.





PRELIMINARY MOBILE HOME INSPECTION REPORT

ATE RECEIVED 6-21-06 BY CH IS THE M/H ON THE PROPERTY WHERE THE PERMIT WILL BE ISSUED?	
WNERS NAME	4 cob & Nebecca Jones PHONE CELL
DDRESS	
IOBILE HOME PARK	Deer Run MHPark SUBDIVISION_
RIVING DIRECTION	STO MOBILE HOME YYI North, Winto Deer Aun, 1st
	land to the end on (Cot I)
AOBILE HOME INST	ALLERStacky becklarPHONECELL
NOBILE HOME I	
	de Brigaden YEAR SO SIZE 14 x 60 COLOR Peach & White
	FLIAF 33 2516 098
WIND ZONE	Must be wind zone II or higher NO WIND ZONE I ALLOWED
INTERIOR: (P or F) 7 P= PA	INSPECTION STANDARDS SS F= FAILED
• • • • • • • • • • • • • • • • • • • •	MOKE DETECTOR () OPERATIONAL () MISSING
	FLOORS () SOLID () WEAK () HOLES DAMAGED LOCATION
./.	DOORS () OPERABLE () DAMAGED
	WALLS () SOLID () STRUCTURALLY UNSOUND
	WINDOWS () OPERABLE () INOPERABLE
///	PLUMBING FIXTURES () OPERABLE () MISSING
1/	CEILING () SOLID () HOLES () LEAKS APPARENT
	ELECTRICAL (FIXTURES/OUTLETS) () OPERABLE () EXPOSED WIRING () OUTLET COVERS MISSING () LIGHT FIXTURES MISSING
EXTERIOR:	WALLS / SIDDING () LOOSE SIDING () STRUCTURALLY UNSOUND () NOT WEATHERTIGHT () NEEDS CLEANING
'/	WINDOWS () CRACKED/ BROKEN GLASS () SCREENS MISSING () WEATHERTIGHT
. / "	
	ROOF () APPEARS SOLID () DAMAGED
STATUS: APPROVED	WITH CONDITIONS:
NOT APPROVED	NEED REINSPECTION FOR FOLLOWING CONDITIONS
70 -2-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	
SIGNATURE	0 10 NUMBER 306 DATE 7-6.06