

## **Envelope Leakage Test Report**

(Blower Door Test) R402.4.1.2 Compliance



	Permit #:
Job Information	
Builder: Americas HomePlae Community:	Lot:
Address: 438 SW Don Coch Way Unit:  City: Fet 1.1 to State: Fl. 7in: 77035	
City: Fort White State:	FL Zip: 32038
Air Leakage Test Results Passing results must be 7 ACH(50) or less	
CFM(50) x 60 ÷ Gybb = Yr ACH(50)  PASS  FAIL  When ACH(50) is less than 3, Mechanical Ventilation insta	Method for calculating building volume:  Retrieved from architectural plans  Code software calculated  Field measured and calculated  allation must be verified by building department.
Certification of Test Results	
<b>R402.4.1.2 Testing.</b> The building or dwelling unit shall be tested and verified as having an air leakage rate of not exceeding 7 air changes per hour in Climate Zones 1 and 2, 3 air changes per hour in Climate Zones 3 through 8. Testing shall be conducted with a blower door at a pressure or 0.2 inches w.g. (50 Pascals). Testing shall be conducted by either individuals as defined in Section 553.993(5) or (7), F.S. or individuals licensed as set forth in Section 489.105(3)(f), (g), or (i) or an approved third party. A written report of the results of the test shall be signed by the party conducting the test and provided to the code official. Testing shall be performed at any time after creation of all penetrations of the building thermal envelope.	
Testing Company	
Company Name: Southern Home Energy Solutions	Phone: 8506301683
I hereby verify that the above Air Leakage results are in accordance with the 5th Edition Florida Building Code Energy Conservation requirements Section R402.4.1.2, Climate Zone 1 and 2.	
Date of Test:	
	ssuing Authority: HSBA
* Attach Copy of Certificate	