

Work Order

Number	2025-00006160	Request Date	5/6/2025 12:00:00 AM
Type	Water Inspection	Schedule Date	5/6/2025 12:00:00 AM
Priority		Assign Date	
Requester	Shasta Pelham	Assigned To	Scott, William Brian
Account	143300-001	Service Address	912 NW FAIRWAY DR
	Reyes, Yasmanis Phone:		LAKE CITY, FL 32055

Comments	10:20 am Please verify that they plumbed to meter 99287167 correctly. Mr. Reyes will be available 05/06/25, 2-3 pm. Call when you are on your way and he will meet you there. 561-254-0433 - SMP
-----------------	--

[illegible]

Read 0000010

Read

Water on upon my arrival customer on site
_____ 10:00am-10:30am

Read Date 05-06-2025

Read Date / /

Comments Water meter and backflow front left

Water meter check valve and backflow installed properly

Completed By: Kap

Work Order

Number	2025-00006161	Request Date	5/6/2025 12:00:00 AM
Type	Sewer Inspection	Schedule Date	5/6/2025 12:00:00 AM
Priority		Assign Date	
Requester	Shasta Pelham	Assigned To	Scott, William Brian
Account	143300-001 Reyes, Yasmanis Phone:	Service Address	912 NW FAIRWAY DR LAKE CITY, FL 32055

Comments	10:20 am Please verify that they plumbed to the sewer tap correctly. Mr. Reyes will be available 05/06/25, 2-3 pm. Call when you are on your way and he will meet you there. 561-254-0433 - SMP
-----------------	---

New Meter Device				

Read

Read

Customer on site

1:00pm-1:30pm

05-06-2025

Read Date

Read Date

Comments

Sewer tap and clean out installed properly

Clean out front left by road

Completed By:

Kap