

UES Project No.: A24140.00430.000 **Date Typed:** September 02, 2025

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Construction Materials Testing Services FIELD AND LABORATORY REPORT COVER PAGE

Client: Wentworth Construction Services

190 SW Thistlewood Lane

Ft. White, FL 32038

Project: Gary Residence, Lake City, FL

258 SE Ripley Place, Lake City, FL - Columbia County, FL 32024

As requested, Universal Engineering Sciences, LLC. (UES) representative(s) performed construction materials testing and/or field inspection services on the above project. Testing results and/or inspection observations are reported on the attached sheets. The contents of this package are summarized below:

Scope of Work

Work Order No.	Date	Type of Report			
1133518-1	08/28/2025	In-Place Density Test Report			

We hope this information is sufficient for your immediate needs. If you have any questions, please do not hesitate to contact the undersigned.

Sincerely, Universal Engineering Sciences, LLC FBPE Registry No. 00000549

Keith L. Butts, P.E. **STATE OF FLORIDA** Professional Engineer No. 53986

Attachments (1)

This item has been electronically signed and sealed by Keith L. Butts, P.E. using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.



UES Project No: A24140.00430.000

Workorder No: 1133518-1 Report Date: 09/02/2025

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

In-Place Density Test Report

Client: Wentworth Construction Services

190 SW Thistlewood Lane

Ft. White, FL 32038

Project: Gary Residence, Lake City, FL

258 SE Ripley Place , Lake City, FL - Columbia County, FL 32024

Type of Test:

Area Tested: House Pad

Field: ASTM D-6938 Nuclear Gauge Method

UES Technician: Saad Alamri

Date Tested: 08/28/2025

Material: Fill

Laboratory: ASTM D1557 Modified Proctor

Reference Datum: 0 = Top of Fill

The tests below meet the 95% minimum compaction requirement.

Test No.	Location of Test	Range	Maximum Density (pcf)	Optimum Moisture (%)	Field Dry Density (pcf)	Field Moisture (%)	Soil Compaction (%)	Pass or Fail
1	NE Corner of Pad	-1-0 ft	107.8	14.5	103.6	4.2	96	Pass
2	SE Corner of Pad	-1-0 ft	107.8	14.5	103.1	5.7	96	Pass
3	SW Corner of Pad	-1-0 ft	107.8	14.5	105.5	4.9	98	Pass
4	NW Corner of Pad	-1-0 ft	107.8	14.5	109.0	3.5	101	Pass
5	Center of Pad	-1-0 ft	107.8	14.5	102.1	5.5	95	Pass