

FIELD DENSITY WORKSHEET

CLIENT Emergency Home Place DATE 4-2-25
 PROJECT NAME 132 SE Lakeland Pl. Lake City PROJECT NO. _____
 EARTH CONTRACTOR _____ PERMIT NO. _____
 COMPACTION REQUIREMENT (%) 95 ☐ Standard Proctor TESTED BY CE
☒ Modified Proctor FIELD CONTACT _____
 TOTAL ON-SITE TIME _____ MILES FROM OFFICE _____
☐ Limerock ☐ Subgrade ☐ Pipe Backfill ☒ Building Pad ☒ Building Footing ☐ Other _____

TEST LOCATION	LAB PROCTOR		TEST DEPTH	PROBE DEPTH	% MOIST	WET DENSITY (PCF)	DRY DENSITY (PCF)	% COMP
	DENS	OMC						
Approx 15' NW of SE corner	1192	110	16"	12"	35	1101	1064	974
15' section corner					42	1128	1082	991
1' at South footing					39	1114	1072	982

REMARKS _____

* Density failed to meet minimum project requirement
 ** Retest indicates minimum density requirement was obtained.
 () Client is aware of unsatisfactory test results.