GEO-TECH, INC.

Engineering Consultants in Geotechnical • Environmental • Construction Materials Testing

FIELD DENSITY WORKSHEET

CLIENT: Marcinda Homes

DATE: 10-16-24

PROJECT NO.:

PROJECT NAME: Forest Ave (160 S. Orange Ave, Ocala)

PERMIT NO.: # 50907

EARTH CONTRACTOR: Lot 1

TESTED BY: CB

COMPACTION REQUIREMENT (%): 95 ☐ Standard Proctor ☒ Modified Proctor

FIELD CONTACT:

TOTAL ON-SITE TIME:

MILES FROM OFFICE:

☐ Limerock ☐ Subgrade ☐ Pipe Backfill ☒ Building Pad ☐ Building Footing ☐ Other

TEST LOCATION	LAB PROCTOR DENS.	LAB PROCTOR OMC	TEST DEPTH	PROBE DEPTH	% MOIST.	WET DENSITY (PCF)	DRY DENSITY (PCF)	% COMP.
NE corner	113.0	9.7	1/1	12	3.9	111.9	110.6	97.9
SE			1/1		3.2	115.1	111.5	98.7
NW			1/1		4.1	115.2	110.7	98.0
SW			1/1		4.6	116.3	111.2	98.4
approximate center			1/1		4.0	115.8	111.3	98.5
160								

REMARKS: Left copy in permit Box

* Density failed to meet minimum project requirement

** Retest indicates minimum density requirement was obtained.

( ) Client is aware of unsatisfactory test results.

1016 S.E. 3RD AVENUE • OCALA, FLORIDA 34471 • (352) 694-7711