



WEST SHORE

HOME

WINDOW MEASURE SHEET

OF INSTALLERS NEEDED: 3

CUSTOMER: William & Kathy Groover TECH: Joshua

DAYS TO COMPLETE: 1

ADDRESS: J-359470

LOCATION	QUANTITY	STYLE	WIDTH X HEIGHT	MISC.
Garage	1	Pic	70 ⁷ / ₈ x 57 ¹ / ₄	SV 3/4
Garage	1	Eve	70 ⁷ / ₈ x 16	SL: 7 ¹ / ₂ 6V 0/4
M Bath	1	Geo	37 ¹ / ₂ x 62 ¹ / ₈	SL: 54 ¹ / ₄ 3V 1/4
M Bath	1	DH	22 ⁵ / ₈ x 46 ¹ / ₄	
MBR	2	DH	34 ⁷ / ₈ x 58 ³ / ₄	
FM RM	1	3Lite	71 ¹ / ₈ x 58 ⁵ / ₈	1/4 · 1/2 · 1/4
FM RM	1	DH	28 ¹ / ₂ x 69 ⁷ / ₈	Temp
FM RM	1	DH	29 ¹ / ₂ x 70	Temp
BR1	1	3Lite	70 ⁷ / ₈ x 58 ³ / ₄	1/4 · 1/2 · 1/4
Bath	1	DH	35 x 34 ⁷ / ₈	
BR2	1	3Lite	70 ⁷ / ₈ x 58 ³ / ₄	1/4 · 1/2 · 1/4
			X	
			X	
			X	
			X	

Temp
Temp
Temp

- Type of tear out Metal Frame
- Any mullions being removed ☒ Yes ☐ No 7
- Will shutter/blinds fit again ☒ Yes ☐ No
- Bays/Bows
 - Roof or soffit tie in
 - Supports or brick underneath? Condition? _____
 - Need jamb depth & projection (degree _____)
 - If in brick extend jamb to brick
 - Exterior opening size _____
- Shoemold _____
- Changes Made ☐ Yes ☒ No

NOTES: Brick · Marble sill · Beige Inside & outside
· Half screens · 3Lites Full Fiber

William & Kathy Groover

- J-359470
- 1,2. Garage · Pic/Eye · $71\frac{1}{8} \times 74\frac{1}{2}$ SL: $66\frac{1}{8}$ · Temp
 3. MBath · Geo · $37\frac{3}{4} \times 62\frac{3}{8}$ SL: $54\frac{1}{2}$ · Temp · Brick
 4. MBath · DH · $22\frac{3}{8} \times 46\frac{1}{2}$ · Marble sill
 5. MBR · DH · $35\frac{1}{8} \times 59$ · Beige Inside
 6. MBR · DH · $35\frac{1}{8} \times 59$ · Beige outside
 7. FM RM · 3Lite · $71\frac{7}{8} \times 58\frac{7}{8}$ · 1/2 screens
 8. FM RM · DH · $28\frac{3}{4} \times 70\frac{1}{8}$ · Temp · 3Lite Full Fibers
 9. FM RM · DH · $28\frac{3}{4} \times 70\frac{1}{4}$ · Temp
 10. BR1 · 3Lite · $71\frac{1}{8} \times 59$
 11. Bath · DH · $35\frac{1}{4} \times 35\frac{1}{8}$
 12. BR2 · 3Lite · $71\frac{1}{8} \times 58\frac{7}{8}$

William & Kathy Groover
J-359470

