

## COLUMBIA COUNTY BUILDING DEPARTMENT **Blower Door Test Results Form**

1 27 18			21	074
Date: 6-27-18		Permit Number: _	260	164
Job Address: 213 SW (	Erin glen	Lake Cita	y, FL	32024
MINIMISTER AND ON STEELER ESC	Dins.		*	
CFM (50) = 1028				
Volume = 14 499				
ACH (50) = CFH (50) X 60 / Volume = _	4.2	P	ASS	FAIL
CERTIFICATION OF TEST RESULTS				
R402.4.1.2 Testing. The Building or dw exceeding 7 air changes per hour in Cli through 8. Testing shall be conducted a shall be conducted by either individual licensed as set forth in Section 489.105 of the test shall be signed by the party performed at any time after creation of	mate Zones 1 and 2, an with a blower door at a Is as defined in Section 5 5(3)(f), (g), or (i) or an ap conducting the test and	d 3 air changes per ho pressure of 0.2 inches 553.993(5) or (7), Flor oproved third party. A d provided to the code	ur in Climate s w.g. (50 Pas ida Statutes written repo e official. Tes	e Zones 3 scals). Testing or individuals ort of the results
I hereby certify that the above Air Infiltration Test results demonstrate compliance with Florida Energy Code requirements in accordance with the5th Edition 2014 Florida Building Code-Energy Conservation R402.4.1.2.				
Testing Company Name:	Testing	Service 1	_لـو	
Tester Name: Tanya C	Sikes	Lic./Cert.#: 50	55995	3
Tester Signature: Tauga	C. Olke			
U .				
135 NE Hernando Avenue, B-21	**************************************			: 386-758-1008 36-758-2160

www.columbiacountyfla.com