



ENGINEERING & TESTING LABORATORY

P.O. Box 1625, Lake City, FL 32056-1625
7540 103rd St. Suite 215 • Jacksonville, FL 32210

Lake City • (386) 755-3633

Fax • (386) 752-5456

Jacksonville • (904) 381-8901

Fax • (904) 381-8902

JOB NO.: 24-018
DATE TESTED: 11-24

REPORT OF IN-PLACE DENSITY TEST

ASTM METHOD: _____ (D-2922) Nuclear _____ (D-2937) Drive Cylinder _____ Other

PROJECT: 495 Sew Jordan st.

CLIENT: flower concrete

GENERAL CONTRACTOR: SAC EARTHWORK CONTRACTOR: SAC

SOIL USE (SEE NOTE): _____ SPECIFICATION REQUIREMENTS: 95%

TECHNICIAN: J. Green

MODIFIED (ASTM D-1557): _____ STANDARD (ASTM D-698): _____

TEST NO.	TEST LOCATION	TEST:	PROCTOR NO.	WET DENS. LBS. CU. FT.	DRY DENS. LBS. CU. FT.	MOIST PERCENT	% MAX. DENS.
		DEPTH ELEV. LIFT					
1	10 ft from E corner		1	111.8	106.9	4.5	102
2	10 ft from SE corner		1	110.6	107.5	2.9	102
3			1	113.3	108.5	4.4	103

REMARKS:

PROCTOR NO.	SOIL DESCRIPTION	PROCTOR VALUE	OPT. MOIST.
		105.2	15.3

NOTE: 1. Building Fill 2. Trench Backfill 3. Base Course 4. Subbase/Stabilized Subgrade 5. Embankment 6. Subgrade/Natural Soil 7. Other
The test results presented in this report are specific only to the samples tested at the time of testing. The tests were performed in accordance with generally accepted methods and standards. Since material conditions can vary between test location and change with time, sound judgement should be exercised with regard to the use and interpretation of the data.