

UES Project No.: 0210.1800019.0000 **Date Typed:** April 06, 2018

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Construction Materials Testing Services FIELD AND LABORATORY REPORT COVER PAGE

Client: SF Brevard, LLC

40 South Palafox Place, Suite 400

Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD

385 SW Property Place, Lake City, Columbia County, FL 32024

As requested, Universal Engineering Sciences, Inc. (UES) representative(s) performed construction materials testing and/or field inspection services on the above project. Testing results and/or inspection observations are reported on the attached sheets. The contents of this package are summarized below:

Scope of Work

Work Order No.	Date	Type of Report
1044094-1	04/05/2018	Field Inspection Report
1044121-1	04/05/2018	4" x 8" Cylinder Test Specimens Activity Record
1044122-1	04/06/2018	Field Inspection Report

We hope this information is sufficient for your immediate needs. If you have any questions, please do not hesitate to contact the undersigned or Jeannine Seider.

Sincerely, Universal Engineering Sciences, Inc. Certificate of Authorization No. 00000549

Attachments (3)

Keith L. Butts, P.E. 4-11-18
STATE OF FLORIDA

Professional Engineer No. 53986

This item has been electronically signed and sealed by Keith L. Butts, P.E. using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.

UES Project No: 0210.1800019.0000

UES Report No: 02-1044094

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC

40 South Palafox Place, Suite 400

Building Code Administration, Compliance Inspection & Plan Review

Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD

385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: 04/05/2018

Technician: Cleveland English

As Requested, a Universal Engineering Sciences Technician was present at the above referenced location for the purpose of obtaining (1) set of (5) Grout Prisms cast on 4/3/18 to be returned to the UES Laboratory for further testing.



UES Project No: 0210.1800019.0000 **UES Report No:** 1044121-1 ARC 040518

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC

40 South Palafox Place, Suite 400

Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD

385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: Thursday, April 05, 2018

Technician: Cleveland English

As requested, a Universal Engineering Sciences Technician was present at the above referenced project site for the purpose of concrete testing for the Zone A.

While on site, the technician observed the general condition of the areas to be tested and cast 4 sets of (5) 4 x 8 specimens for compressive strength testing.

UES Project No: 0210.1800019.0000

UES Report No: 02-1044122

4475 Southwest 35th Terrace, Gainesville, FL 32608 - P: 352.372.3392 - F: 352.336.7914

Activity Record

Client: SF Brevard, LLC

40 South Palafox Place, Suite 400

Building Code Administration, Compliance Inspection & Plan Review

Pensacola, FL 32502

Project: The Rehab Center of Lake City, CSD

385 SW Property Place, Lake City, Columbia County, FL 32024

Date of Activity: 04/06/2018

Technician: Cleveland English

As Requested, a Universal Engineering Sciences Technician was present at the above referenced location for the purpose of obtaining (4) sets of concrete cylinders cast on 4/5/18 to be returned to the UES Laboratory for further testing.