Envelope Leakage Test Report (Blower Door Test) Residential Prescriptive, Performance or ERI Method Compliance 2017 Florida Building Code, Energy Conservation, 6th Edition

Jurisdiction: Columbia County	Permit #: 00	0041623
Job Information:		
Builder: LDM CONSTRUCTION Community: Cox Survey Lot 28 Address: 608 SW BONIFAY Glen Unit: City: Font White State: Florida Zip: 32038		
Address: 608 500 BONNAY Glen		Unit:
City: Fort White Star	te: Florida	Zip: 32038
Air Leakage Test Results: Passing results must meet either the Performance, Prescriptive, or ERI Method		
PRESCRIPTIVE METHOD- The building or dwelling unit shall be tested and verified as having an air leakage rate of not exceeding 7 air changes per hour at a pressure of 0.2-inch w.g. (50 pascals) in Climate Zones 1 and 2.		
PERFORMANCE or ERI METHOD- The building or dwelling unit shall be tested and verified as having an air leakage rate of not exceeding the selected ACH(50) value, as shown on FORM R405-20J7 (Performance) or R406-2017 (ERI), section labeled as Infiltration, sub-section ACH.		
Image: State of the second state of the sets, shall be closed, but not sealed, beyond the intended weather-stripping or other infiltration control measures. Image: State of the set of the sets, shall be closed, but not sealed, beyond the intended infiltration control measures. Image: State of the set of the sets, shall be closed and sealed.		
Testing Company		
Company Name: airEnalasys Phone: 877-437-7728 I hereby verify that the above Air Leakage results are in accordance with the 2017 6th Edition Florida Building Code Energy Conservation requirements according to the compliance method selected above. Signature of Tester: W. Mago Date of Test: OZ/10/2Z Printed Name of Tester: William Mago		
License/Certification# RESNET 4309320	Issuing Authority:	FSEC