

To Columbia County Building Department

207 SW High Field Terrace Lake City, Florida 32024

Jarvis Heat and Air installed a Daikin Mini Split system, the building had been spray foamed on ceiling and walls. Mini split system is properly installed according to code with proper disconnect at condenser unit, etc. unit is cooling/heating properly.

Rob Jarvis Jarvis Heat and Air 7066 South CR 231 Lake Butler, FL 32054 CAC1816766 To Troy Crews,

In regards to the dwelling at 207 SW High Field Terrace Lake City, Florida 32024, I performed an inspection of the plumbing system from what I can see all drains are flowing properly and all water lines are tight, connections all meet proper code requirements.

Curtis Graddy Curtis Graddy Plumbing 1039 SW Mauldin Ave Lake City, FL 32024 CFC043064 To: Mr. Troy Crews
Columbia County Building and Zoning Director

RE: 207 SW High Field Terrace Lake City, Florida 32024

In regards to the dwelling at 207 SW High Field Terrace Lake City, Florida 32024, an inspection was performed to assess the safety of the electrical system on the premises. Having no knowledge of or access to wiring methods behind walls, inspection was limited to visible components only. The following observations were made:

- 1. Wire sizing and overcurrent devices are sized properly.
- 2. Distribution panel: Neutral and ground wiring is sized properly and neutrals are isolated from the ground bus at the sub panel inside.
- 3. Receptacles adjacent to sink and wet locations are GFCI protected.
- Appliance circuits are sized properly.

This is not a conventional dwelling but nothing was observed that would indicate an unsafe installation, based on the limited access to visible components.

R. K. Lee Electric can accept no liability for any future incidents occurring at this location as no work was performed by same.

Ryan Lee R. K. Lee Electric, LLC (386)438-4736



To Columbia County Building Department

207 SW High Field Terrace Lake City, Florida 32024

Jarvis Heat and Air installed a Daikin Mini Split system, the building had been spray foamed on ceiling and walls. Mini split system is properly installed according to code with proper disconnect at condenser unit, etc. unit is cooling/heating properly.

Rob Jarvis

Jarvis Heat and Air 7066 South CR 231

Lake Butler, FL 32054

CAC1816766

To: Mr. Troy Crews
Columbia County Building and Zoning Director

RE: 207 SW High Field Terrace Lake City, Florida 32024

In regards to the dwelling at 207 SW High Field Terrace Lake City, Florida 32024, an inspection was performed to assess the safety of the electrical system on the premises. Having no knowledge of or access to wiring methods behind walls, inspection was limited to visible components only. The following observations were made:

1. Wire sizing and overcurrent devices are sized properly.

2. Distribution panel: Neutral and ground wiring is sized properly and neutrals are isolated from the ground bus at the sub panel inside.

3. Receptacles adjacent to sink and wet locations are GFCI protected.

4. Appliance circuits are sized properly.

This is not a conventional dwelling but nothing was observed that would indicate an unsafe installation, based on the limited access to visible components.

R. K. Lee Electric can accept no liability for any future incidents occurring at this location as no work was performed by same.

Ryan Lee R. K. Lee Electric, LLC (386)438-4736

Reyon Ley

To Troy Crews,

In regards to the dwelling at 207 SW High Field Terrace Lake City, Florida 32024, I performed an inspection of the plumbing system from what I can see all drains are flowing properly and all water lines are tight, connections all meet proper code requirements.

Curtis Graddy

Curtis Graddy Plumbing

1039 SW Mauldin Ave

Lake City, FL 32024

CFC043064