

40114

CLIENT Amira Builders DATE 7-13-20

PROJECT NAME 643 Macynik Dr. High Springs PROJECT NO. _____

EARTH CONTRACTOR _____ PERMIT NO. _____

TESTED BY ce

COMPACTION REQUIREMENT (%) 95 ☐ Standard Proctor

☒ Modified Proctor FIELD CONTACT _____

TOTAL ON-SITE TIME _____ MILES FROM OFFICE _____

☐ Limerock ☐ Subgrade ☐ Pipe Backfill ☒ Building Pad ☐ Building Footing ☐ Other _____

REMARKS _____

- * Density failed to meet minimum project requirement
- ** Retest indicates minimum density requirement was obtained.
- () Client is aware of unsatisfactory test results.