



Noling Pest Control

Cory Noling, Owner
Phone (386) 454-3888
(386) 935-2007
P.O. Box 949

GRAPH AND SPECIFICATIONS



31505

BUYER'S NAME Ronald Downis SELLER'S NAME _____ DATE 10/6/13
INSPECTION ADDRESS 21 SW 22nd St CITY Lytle City STATE TX ZIP 32024
BUSINESS PHONE _____ HOME PHONE _____ INSPECTED BY Cory Noling

Scale Used _____ Well. ☐ Yes ☐ No How close to house? _____ ft. Additions? ☐ Yes ☐ No Access? _____

Additional specifications and comments. 5 qft not to 5 qft Termidor SCWG
52 gallons.

Lineal Footage _____ Square Footage. 378 sq ft Contract Price. _____
Type Foundation ☐ Floating Slab ☐ Supported Slab ☐ Monolithic Slab ☐ Crawl ☐ Basement Type Construction: ☐ CBS ☐ Woodframe ☐ Brick

Type Infestation Key	Location Key			General Conditions	
	F - Front R - Right L - Left RE - Rear C-Center				
T-Subterranean Termite Activity	Infested Area	Type	Location	Stucco below grade?	Yes ☐ No ☐
D - Drywood Termite Activity	☐ Sills / Joists			Are Termites swarming?	Yes ☐ No ☐
ST - Suspected Termite Activity	☐ Sub Floor			Wood supports on ground?	Yes ☐ No ☐
P - Powder Post Beetles	☐ Finished Floor			Proper clearance for treating?	Yes ☐ No ☐
W - Wood Borers	☐ Walls, Studs, Plates			Make A3 access opening?	Yes ☐ No ☐
M - Moisture Condition	☐ Interior Trim			Electricity available?	Yes ☐ No ☐
F - Wood Decaying Fungi	☐ Paneled Wall			Bath trap opening?	Yes ☐ No ☐
X-Damage Present	☐ Door/Window Frame			Shrubbery Light ☐ Heavy ☐	
... - Vertical Drill Location	☐ Furniture/Cabinets			Type Floor Covering: _____	
	☐ Attic			Other: _____	
	☐ Roof				

VISIBLE DAMAGE WHICH EXISTS AT THE TIME OF THE INSPECTION IS DESIGNATED BY AN "X"

