NO Application CODE ENFORCEMENT

PRELIMINARY MOBILE HOME INSPECTION REPORT

Call to Bofore going to have the Gate unlocked.

Wilson
DATE RECEIVED 12-9-13 BY LH IS THE M/H ON THE PROPERTY WHERE THE PERMIT WILL BE ISSUED? Yes
OWNERS NAME Cliff Boone (Leslie) PHONE CELL 384-984-0468
ADDRESS 489 SU Sean Place, Calact, Fr, 32024
MOBILE HOME PARKSUBDIVISION
DRIVING DIRECTIONS TO MOBILE HOME 10 v, Q 341, Stay on Dyal Rel, (B) 1-118 Rol at the 90° Curve & Mouldin Rd off 1815 Stay on the line rock Rel (Sean Place, Yey mile on Q Gate with Key Pad
MOBILE HOME INSTALLER BO ROYALS PHONE CELL 365-4444
MOBILE HOME INFORMATION off
MAKE Fleetwood YEAR SIZE 14 x 60 COLOR White
SERIAL NO. FLFL 1A E 07 7006348
WIND ZONE Must be wind zone II or higher NO WIND ZONE I ALLOWED
INSPECTION STANDARDS
INTERIOR: (P or F) - P= PASS F= FAILED \$50.00
SMOKE DETECTOR () OPERATIONAL () MISSING Date of Payment: 12-6-13
FLOORS () SOLID () WEAK () HOLES DAMAGED LOCATION
DOORS () OPERABLE () DAMAGED Notes
WALLS () SOLID () STRUCTURALLY UNSOUND
WINDOWS () OPERABLE () INOPERABLE
PLUMBING FIXTURES () OPERABLE () INOPERABLE () MISSING
CEILING () SOLID () HOLES () LEAKS APPARENT
ELECTRICAL (FIXTURES/OUTLETS) () OPERABLE () EXPOSED WIRING () OUTLET COVERS MISSING () LIGHT FIXTURES MISSING
EXTERIOR: WALLS / SIDDING () LOOSE SIDING () STRUCTURALLY UNSOUND () NOT WEATHERTIGHT () NEEDS CLEANING
WINDOWS () CRACKED/ BROKEN GLASS () SCREENS MISSING () WEATHERTIGHT
ROOF () APPEARS SOLID () DAMAGED
STATUS
APPROVED WITH CONDITIONS:
NOT APPROVED NEED RE-INSPECTION FOR FOLLOWING CONDITIONS
SIGNATURE JOS DATE 12-9-13