1401-37

CODE ENFORCEMENT DEPARTMENT COLUMBIA COUNTY, FLORIDA OUT OF COUNTY MOBILE HOME INSPECTION REPORT

COUNTY THE MOBILE HOME IS BEING MOVED FROM _ AlaChua
OWNERS NAME QUIGLEY ROBERT PHONE (38) 365-0221
INSTALLER RUST L. Knowler PHONE 386755-6946ELL 386-597-0386
INSTALLERS ADDRESS 5801 SW SR49 LAKE A F132024
MÖBILE HOME INFORMATION
MAKE LIVE Oaks Homes YEAR 4-27-2010 SIZE 32 x 76 Box
COLOR BOWN SERIAL NO. LOHGAIDISTO AB GEO1494610/GEO149461
WIND ZONE SMOKE DETECTOR OF MISSING
INTERIOR: GOOD
DOORS (FOOR)
WALLS Good
CABINETS Good
ELECTRICAL (FIXTURES/OUTLETS) 1 Browne Outlet Cover
EXTERIOR: WALL3 / SIDDING
windows Good no Screenes
DOORS Good
INSTALLER: APPROVED NOT APPROVED
INSTALLER OR INSPECTORS PRINTED NAME Rusty L. Knowlos
installer/inspector Signature License No ZH 1038218 Date 1-16-14
NOTES:
ONLY THE ACTUAL LICENSE HOLDER OR A BUILDING INSPECTOR CAN SIGN THIS FORM.
NO WIND ZONE ONE MOBÎLE HOMES WILL BE PERMITTED, MOBILE HOMES PRIOR TO 1977 ARE PRE-HUD AND THE WIND ZONE MUST BE PROVEN TO BE PERMITTED,
BEFORE THE MOBILE HOME CAN BE MOVED INTO COLUMBIA COUNTY THIS FORM MUST BE COMPLETED AND RETURNED TO THE COLUMBIA COUNTY BUILDING DEPARTMENT.
ONGE MOVED INTO COLUMBIA COUNTY AN INSPECTOR MUST COMPLETE A PRELIMINARY INSPECTION ON THE MOBILE HOME. CALL 386-758-1008 TO SET UP THIS INSPECTION. NO PERMIT WILL BE ISSUED BEFORE THIS IS DONE.
Code Enforcement Approval Signature On Mu Date 1/24/14

CODE ENFORCEMENT PRELIMINARY MOBILE HOME INSPECTION REPORT 1401 - 37

DATE RECEIVED 2/4/19 BY CH IS THE M/H ON THE PROPERTY WHERE THE PERMIT WILL BE ISSUED?
OWNERS NAME PROBLET PHONE CELL 365-0279
ADDRESS 171 NW Leonia Way Lake City for 32055
MOBILE HOME PARKSUBDIVISION
DRIVING DIRECTIONS TO MOBILE HOME 90 W, (R) Lake Jeffrey, (R) Leonia Way,
MOBILE HOME INSTALLER Rusty Knowles PHONE CELL 397-0886
MOBILE HOME INFORMATION
MAKE Live Oale YEAR 2010 SIZE 32 x 80 COLOR Brown
SERIAL NO. LO 14GA 11 O 11 9 le A & C
WIND ZONE Must be wind zone II or higher NO WIND ZONE I ALLOWED
INSPECTION STANDARDS INTERIOR: (P or F) · P= PASS F= FAILED SMOKE DETECTOR () OPERATIONAL () MISSING FLOORS () SOLID () WEAK () HOLES DAMAGED LOCATION DOORS () OPERABLE () DAMAGED WALLS () SOLID () STRUCTURALLY UNSOUND WINDOWS () OPERABLE () INOPERABLE PLUMBING FIXTURES () OPERABLE () INOPERABLE () MISSING CEILING () SOLID () HOLES () LEAKS APPARENT ELECTRICAL (FIXTURES/OUTLETS) () OPERABLE () EXPOSED WIRING () OUTLET COVERS MISSING () LIGHT FIXTURES MISSING
EXTERIOR: WALLS / SIDDING () LOOSE SIDING () STRUCTURALLY UNSOUND () NOT WEATHERTIGHT () NEEDS CLEANING WINDOWS () CRACKED/ BROKEN GLASS () SCREENS MISSING () WEATHERTIGHT ROOF () APPEARS SOLID () DAMAGED
STATUS
APPROVED WITH CONDITIONS:
NOT APPROVED NEED RE-INSPECTION FOR FOLLOWING CONDITIONS
SIGNATURE ID NUMBER DATE