BLOWER DOOR TESTING, LLC



BPI ID# 5059955

COLUMBIA COUNTY BUILDING DEPARTMENT Blower Door Test Results Form

Date: 4/13/23	Permit Number: 4	4044
Job Address: 214 Siw. Cherry Blos	SOM WAY, LAKE	City, Fl. 32
AIR INFILTRATION TEST RESULTS	-	
CFM (50) = 914		
Volume = 13716		
ACH (50) = CFH (50) X 60 / Volume = 4.0	KPASS	FAIL
CERTIFICATION OF TEST RESULTS		
R402.4.1.2 Testing. The Building or dwelling unit shall be a exceeding 7 air changes per hour in Climate Zones 1 and 2 through 8. Testing shall be conducted with a blower door shall be conducted by either individuals as defined in Sectionsed as set forth in Section 489.105(3)(f), (g), or (i) or a of the test shall be signed by the party conducting the test performed at any time after creation of all penetrations or	2, and 3 air changes per hour in C at a pressure of 0.2 inches w.g. (tion 553.993(5) or (7), Florida Sta an approved third party. A writte at and provided to the code offici	Climate Zones 3 50 Pascals). Testing tutes or individuals in report of the results al. Testing shall be
I hereby certify that the above Air infiltration Florida Energy Code requirements in accorda	Test results demonstrate nce with the 5th Edition 2	compliance with 014 Florida
Building Code-Energy Conservation R402.4.1.	.2. BLOWER DOOR TEST	ring, LLC
Testing Company Name: BLOWER Doon Te Tester Name: TAMES W. George	BPI ID# 5059	955
	Lic./Cert.#: <u>5059</u>	955
Tester Signature pames (U. Le	orgi	
135 NE Hernando Avenue, 8-21	•	hone: 386-758-1008
Lake City, FL 32055		Fax: 386-758-2160
www.columbiacountyfla.com		