

Engineering Consultants in Geotechnical • Environmental • Construction Materials Testing

CLIENT Maranda Homes DATE 4-22-25
PROJECT NO. _____
PROJECT NAME Forest Cove lot 7 PERMIT NO. _____
EARTH CONTRACTOR _____ TESTED BY CB
COMPACTION REQUIREMENT (%) 95 ☐ Standard Proctor
☒ Modified Proctor FIELD CONTACT _____
TOTAL ON-SITE TIME _____ MILES FROM OFFICE _____
☐ Limerock ☐ Subgrade ☐ Pipe Backfill ☐ Building Pad ☐ Building Footing ☐ Other _____

[illegible]

REMARKS _____

- Density failed to meet minimum project requirement
- ** Retest indicates minimum density requirement was obtained.
- () Client is aware of