

A FDID State Incident Date MM DD YYYY Station Incident Number Exposure ☐ Delete ☐ Change ☐ No Activity		NFIRS-1 Basic	
B Location Type ☒ Street address ☐ Check this box to indicate that the address for this incident is provided on the Wildland Fire Module in Section B, "Alternative Location Specification." Use only for wildland fires.			
☒ Intersection 463 SW COUNTY ROAD 240 ☐ In front of Number/Milepost Prefix Street or Highway ☐ Rear of Apt./Suite/Room CITY ☐ Adjacent to State 32025 ZIP Code ☐ Directions ☐ U.S. National Grid Cross Street, Directions or National Grid, as applicable			
C Incident Type ☒ 111 Building fire Incident Type		E1 Dates and Times Midnight is 0000 Alarm ☒ Arrival ☒ ☐ Controlled ☒ Last Unit Cleared	
D Aid Given or Received ☒ None ☐ Mutual aid received ☐ Auto. aid received ☐ Mutual aid given ☐ Auto. aid given ☐ Other aid given Their FDID Their State Their Incident Number		E2 Shifts and Alarms Local Option Shift or Platoon 1 D45	
F Actions Taken ☒ Extinguishment by 11 fire service personnel 12 Salvage & overhaul		G1 Resources ☒ Check this box and skip this block if an Apparatus or Personnel Module is used. Suppression EMS Other ☐ Check box if resource counts include aid received resources.	
G2 Estimated Dollar Losses and Values LOSSES: Required for all fires if known. Optional for non-fires. Property \$ Contents \$ PRE-INCIDENT VALUE: Optional Property \$ Contents \$			
Completed Modules ☒ Fire-2 ☒ Structure Fire-3 ☐ Civilian Fire Cas.-4 ☐ Fire Service Cas.-5 ☐ EMS-6 ☐ HazMat-7 ☐ Wildland Fire-8 ☒ Apparatus-9 ☒ Personnel-10 ☐ Arson-11		H1 Casualties ☒ None Deaths Injuries Fire Service Civilian	
H2 Detector Required for confined fires. ☐ 1 ☐ Detector alerted occupants ☐ 2 ☐ Detector did not alert them ☐ U ☐ Unknown		H3 Hazardous Materials Release ☐ None ☐ 1 ☐ Natural gas: slow leak, no evacuation or HazMat actions ☐ 2 ☐ Propane gas: <21-lb tank (as in home BBQ grill) ☐ 3 ☐ Gasoline: vehicle fuel tank or portable container ☐ 4 ☐ Kerosene: fuel burning equipment or portable storage ☐ 5 ☐ Diesel fuel/fuel oil: vehicle fuel tank or portable storage ☐ 6 ☐ Household solvents: home/office spill, cleanup only ☐ 7 ☐ Motor oil: from engine or portable container ☐ 8 ☐ Paint: from paint cans totaling <55 gallons ☐ 0 ☐ Other: special HazMat actions required or spill > 55 gal (Please complete the HazMat form.)	
J Property Use ☒ Structures ☐ 131 ☐ Church, place of worship ☐ 161 ☐ Restaurant or cafeteria ☐ 162 ☐ Bar/Tavern or nightclub ☐ 213 ☐ Elementary school, kindergarten ☐ 215 ☐ High school, junior high ☐ 241 ☐ College, adult education ☐ 311 ☐ Nursing home ☐ 331 ☐ Hospital		☐ 341 ☐ Clinic, clinic-type infirmary ☐ 342 ☐ Doctor/Dentist office ☐ 361 ☐ Prison or jail, not juvenile ☒ 419 ☐ 1- or 2-family dwelling ☐ 429 ☐ Multifamily dwelling ☐ 439 ☐ Rooming/Boarding house ☐ 449 ☐ Commercial hotel or motel ☐ 459 ☐ Residential, board and care ☐ 464 ☐ Dormitory/Barracks ☐ 519 ☐ Food and beverage sales	
☐ 936 ☐ Vacant lot ☐ 938 ☐ Graded/Cared for plot of land ☐ 946 ☐ Lake, river, stream ☐ 951 ☐ Railroad right-of-way ☐ 960 ☐ Other street ☐ 961 ☐ Highway/Divided highway ☐ 962 ☐ Residential street/driveway		☐ 539 ☐ Household goods, sales, repairs ☐ 571 ☐ Gas or service station ☐ 579 ☐ Motor vehicle/boat sales/repairs ☐ 599 ☐ Business office ☐ 615 ☐ Electric-generating plant ☐ 629 ☐ Laboratory/Science laboratory ☐ 700 ☐ Manufacturing plant ☐ 819 ☐ Livestock/Poultry storage (barn) ☐ 882 ☐ Non-residential parking garage ☐ 891 ☐ Warehouse	
☐ 981 ☐ Construction site ☐ 984 ☐ Industrial plant yard		☐ 10 ☐ Assembly use ☐ 20 ☐ Education use ☐ 33 ☐ Medical use ☐ 40 ☐ Residential use ☐ 51 ☐ Row of stores ☐ 53 ☐ Enclosed mall ☐ 58 ☐ Business & residential ☐ 59 ☐ Office use ☐ 60 ☐ Industrial use ☐ 63 ☐ Military use ☐ 65 ☐ Farm use ☐ 00 ☐ Other mixed use	
☐ 124 ☐ Playground or park ☐ 655 ☐ Crops or orchard ☐ 669 ☐ Forest (timberland) ☐ 807 ☐ Outdoor storage area ☐ 919 ☐ Dump or sanitary landfill ☐ 931 ☐ Open land or field			

K1 Person/Entity Involved

Local Option

BRYAN ZECHER CONSTRUCTION

Business Name (if applicable)

386

Area Code

752

Phone Number

8653

☐ Check this box if same address as incident location (Section B). Then skip the three duplicate address lines.

MR

Mr., Ms., Mrs.

BRYAN

First Name

MI

ZECHER

Last Name

Suffix

465

Number

NW

Prefix

ORANGE

Street or Highway

ST

Street Type

Suffix



Post Office Box

Apt./Suite/Room

LAKE CITY

City

FL

State

32055

ZIP Code

☐ More people involved? Check this box and attach Supplemental Forms (NFIRS-1S) as necessary.

K2 Owner

Local Option

☐ Same as person involved? Then check this box and skip the rest of this block.

Business Name (if applicable)

386

Area Code

344

Phone Number

4545

☒ Check this box if same address as incident location (Section B). Then skip the three duplicate address lines.

MRS

Mr., Ms., Mrs.

JESSICA

First Name

MI

DICKS

Last Name

Suffix

Number

Prefix

Street or Highway

Street Type

Suffix



Post Office Box

Apt./Suite/Room

City

State

ZIP Code

L

Remarks:

JAMES THOMAS**April 4, 2022 13:31:23**

CCFR UNITS RESPONDED TO 463 SW CR 240 FOR A STRUCTURE FIRE. E-45 AND T-45 ARRIVED ON SCENE FIRST AND ADVISED OF HEAVY SMOKE COMING FROM BACK OF HOUSE. BATT-48 ARRIVED ON SCENE, NOTICED HEAVY SMOKE COMING FROM THE BACK PORCH EVE AREA OF THE HOUSE. E-45 CREW HAD A LINE PULLED TO THE REAR OF THE HOUSE AND MADE ENTRY INSIDE WITH NO FIRE FOUND. CF-10 SPOKE WITH HOME OWNER AND BUILDING CONTRACTOR, THEY ADVISED OF AN ATTIC ACCESS INSIDE. BY NOW E-44, T-44 E-48 AND T-48 HAS ARRIVED ON SCENE. CF-10 ADVISED TO PULL ANOTHER PRECONNECT. TWO FF MADE ENTRY TO THE ATTIC ACCESS, WHILE TWO MORE FF PULLED WOOD CEILING ON THE BACK PORCH. INSIDE CREWS ADVISED LITTLE TO NO FIRE IN THE ATTIC, THAT FIRE WAS EXTINGUISHED. ONCE WOOD CIELING WAS REMOVED IN THREE SPOTS ON THE BACK PORCH, HEAVY SMOKE, WITH FIRE IN ONE CORNER OF THE PORCH CIELING WAS FOUND. THAT FIRE WAS EXTINGUISHED WITH WATER FROM E-45.

ATTIC APPEARED TO STILL HAVE FIRE IN IT DUE TO SMOKE COMING FROM THE EVE. CF-10 PUT A FAN INSIDE THE HOUSE AT THE ATTIC ACCESS TO TRY AND PUSH THE SMOKE OUT AND CLEAR UP THE ATTIC. CREWS WERE ASKED TO CUT A HOLE IN THE ROOF OVER THE BACK PORCH TO MAKE SURE NO FIRE WAS VISIBLE. CREWS CUT ANOTHER HOLE AT THE PEAK TO VENT THE ATTIC AND REMOVE THE SMOKE.

☒ More remarks? Check this box and attach Supplemental Forms (NFIRS-1S) as necessary.

M Authorization

Check box if same as Officer in charge. ☒

CF10

Officer in charge ID

Signature

Position or rank

Assignment

04

Month

04

Day

2022

Year

CF10

Member making report ID

Signature

Position or rank

Assignment

04

Month

04

Day

2022

Year